

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

THUR, 30 JUN 1898

Date of writing Report	June 21 1898	When handed in at Local Office	June 21 1898	Port of Newcastle
No. in Reg. Book.	Survey held at	Newcastle	Date, First Survey	111 Feb 1898
30	29	on the Machinery of the Wood, Iron or Steel s.s. <i>Drake Standard</i> Master	Last Survey	June 18 1898
Tonnage	Gross 3708		No. of Vessels	20
Net	2345	Vessel built at Newcastle	YEAR.	MONTH.
Registered	298	By whom Sir W. G. Armstrong Mitchell & Co. When 1893.	2	
Horse Power	298	Engines made at Newcastle	1893	
No. of Main Boilers	2	When 1893 Boilers, when made (Main) / 1893 (Donkey) / 1893		
No. of Donkey Boilers	1	Owners European Petroleum Co. Ltd A Startup Port London		
Steam Pressure	in Main Boilers 16 lbs	Voyage Batum		
in Donkey Boilers 100 lbs	If Surveyed Afloat or in Dry Dock Smith's Pontoon			
(State name of Dock.)				

Last Survey No. 35625 Port N.W.C.

Particulars of Examination and Repairs (if any)

(Periodical Surveys, when held, must be reported in detail and variation in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

Do. " Donkey " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

Has the propeller shaft been drawn and examined at this time?

State the distance between lignum vita of stern bush and top of after bearing of screw shaft?

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done? Donkey boiler safety valves to be adjusted

Damage Repairs

Damage through main Boilers being short of water. The whole of the internal parts all more or less damaged. The main boilers have been removed and repaired on shore. All the internal parts have been renewed including stays and tubes. Main steam pipes and boiler mountings removed and these together with the boilers tested by a hydraulic pressure of 320 lbs per square inch with satisfactory result. Donkey boiler examined and found in good condition.

Vessel placed on the above pontoon. The propeller sternbush, and seacock fastenings examined and found in good order.

To complete the survey for D.S. the donkey boiler safety valves to be adjusted

General Observations, Opinion, and Recommendation:

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, H.S. 9,97, H.G.M.S. 9,97 or Q.L.M.C. 9,97, 140 lb., P.D., &c.)

The Engines and Boilers of this vessel so far as seen, are now in good working condition and eligible in my opinion to remain as classed and to be noted D.S. 6-95 in the Register Book when the donkey boiler safety valves have been adjusted.

Office or Registration Fee (per Sec. 27) £ 2. 14. : 29/6 18/98

Survey Fee (per Section 28) £ 2. 14. :

Special Damage Fee (per Section 28) £ 1. 16. :

Travelling Expenses (if chargeable) £ 1. 16. :

State if Certificate is required

Committee's Minute FRI, 1 JUL 1898

Assigned as now

note

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER as for Special Survey. Date of last Survey and of Periodical Surveys.	Machinery and Boilers (including date of S.B., if any).
100 ft. 10.97 Spar deck carrying Petroleum in bulk SS. Shl No 1-97	£ 5 m 63.97

Is a Survey sent now, or when will it be sent?

Do. " Donkey " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

Has the propeller shaft been drawn and examined at this time?

State the distance between lignum vita of stern bush and top of after bearing of screw shaft?

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done? Donkey boiler safety valves to be adjusted

Damage Repairs

Damage through main Boilers being short of water. The whole of the internal parts all more or less damaged. The main boilers have been removed and repaired on shore. All the internal parts have been renewed including stays and tubes. Main steam pipes and boiler mountings removed and these together with the boilers tested by a hydraulic pressure of 320 lbs per square inch with satisfactory result. Donkey boiler examined and found in good condition.

Vessel placed on the above pontoon. The propeller sternbush, and seacock fastenings examined and found in good order.

To complete the survey for D.S. the donkey boiler safety valves to be adjusted

General Observations, Opinion, and Recommendation:

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, H.S. 9,97, H.G.M.S. 9,97 or Q.L.M.C. 9,97, 140 lb., P.D., &c.)

The Engines and Boilers of this vessel so far as seen, are now in good working condition and eligible in my opinion to remain as classed and to be noted D.S. 6-95 in the Register Book when the donkey boiler safety valves have been adjusted.

Office or Registration Fee (per Sec. 27) £ 2. 14. : 29/6 18/98

Survey Fee (per Section 28) £ 2. 14. :

Special Damage Fee (per Section 28) £ 1. 16. :

Travelling Expenses (if chargeable) £ 1. 16. :

State if Certificate is required

Committee's Minute FRI, 1 JUL 1898

Assigned as now

note

G. L. Hindmarsh
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

FRI, 12 AUG 1898

FRI, 23 SEP 1898

FRI, 14 OCT 1898

© 2018

Lloyd's Register Foundation

Boat and Engine repair to 2000ft. to return to port

10 Nov 1909 from 1000ft. to 2000ft. to return to port

Port of Manila

10 Nov 1909 from 1000ft. to 2000ft. to return to port

10 Nov 1909 from 1000ft. to 2000ft. to return to port

10 Nov 1909 from 1000ft. to 2000ft. to return to port

10 Nov 1909 from 1000ft. to 2000ft. to return to port

10 Nov 1909 from 1000ft. to 2000ft. to return to port

10 Nov 1909 from 1000ft. to 2000ft. to return to port

10 Nov 1909 from 1000ft. to 2000ft. to return to port

10 Nov 1909 from 1000ft. to 2000ft. to return to port

10 Nov 1909 from 1000ft. to 2000ft. to return to port

10 Nov 1909 from 1000ft. to 2000ft. to return to port

10 Nov 1909 from 1000ft. to 2000ft. to return to port

10 Nov 1909 from 1000ft. to 2000ft. to return to port

10 Nov 1909 from 1000ft. to 2000ft. to return to port

10 Nov 1909 from 1000ft. to 2000ft. to return to port

10 Nov 1909 from 1000ft. to 2000ft. to return to port

10 Nov 1909 from 1000ft. to 2000ft. to return to port

10 Nov 1909 from 1000ft. to 2000ft. to return to port

10 Nov 1909 from 1000ft. to 2000ft. to return to port

10 Nov 1909 from 1000ft. to 2000ft. to return to port

10 Nov 1909 from 1000ft. to 2000ft. to return to port

10 Nov 1909 from 1000ft. to 2000ft. to return to port

10 Nov 1909 from 1000ft. to 2000ft. to return to port

10 Nov 1909 from 1000ft. to 2000ft. to return to port

10 Nov 1909 from 1000ft. to 2000ft. to return to port

10 Nov 1909 from 1000ft. to 2000ft. to return to port

10 Nov 1909 from 1000ft. to 2000ft. to return to port

10 Nov 1909 from 1000ft. to 2000ft. to return to port

10 Nov 1909 from 1000ft. to 2000ft. to return to port

10 Nov 1909 from 1000ft. to 2000ft. to return to port

10 Nov 1909 from 1000ft. to 2000ft. to return to port

10 Nov 1909 from 1000ft. to 2000ft. to return to port

10 Nov 1909 from 1000ft. to 2000ft. to return to port

10 Nov 1909 from 1000ft. to 2000ft. to return to port

10 Nov 1909 from 1000ft. to 2000ft. to return to port

10 Nov 1909 from 1000ft. to 2000ft. to return to port

10 Nov 1909 from 1000ft. to 2000ft. to return to port

10 Nov 1909 from 1000ft. to 2000ft. to return to port

10 Nov 1909 from 1000ft. to 2000ft. to return to port

10 Nov 1909 from 1000ft. to 2000ft. to return to port

10 Nov 1909 from 1000ft. to 2000ft. to return to port

10 Nov 1909 from 1000ft. to 2000ft. to return to port

10 Nov 1909 from 1000ft. to 2000ft. to return to port

10 Nov 1909 from 1000ft. to 2000ft. to return to port

10 Nov 1909 from 1000ft. to 2000ft. to return to port

Boat taken at 8
and all internal parts removed
to reef damage through shooting

It is submitted that this
vessel WILL BE eligible for
the record.

The S.B. Safety orders
have been completed
under chart

30/6/98

