

Master Name
Name Discharge type Update

N.B.-If this Report is copied by Copying Press, special care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

It is submitted that
this vessel is eligible to
remain as Classed.

D.P.S.
17.3.16

LR-FAF-SA20-325

OF THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.

pt. 9.

No. 795

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

TUE. MAR. 16. 1915,

Date of writing Report	When handed in at Local Office	Port of <u>Halifax</u>	
No. in Reg. Book.	Survey held at <u>Halifax</u>	Date, First Survey <u>26 Feb</u>	Last Survey <u>1st March 1915</u>
No. in Reg. Book.	<u>64</u> on the Machinery of the Wood, Iron or Steel	S/s <u>Baku Standard</u>	(No. of Visits Two)
Gross Tonnage	<u>3708</u>	Master <u>A. Torrance</u>	YEAR. MONTH.
Net Tonnage	<u>2375</u>	Vessel built at <u>Newcastle q.B.</u> By whom <u>Armstrong Mitchell & Co. Ltd</u>	When <u>1893 - 2</u>
Registered Horse Power	<u>193</u>	Engines made at <u>Newcastle q.B.</u> By whom <u>Wallend Slip C. Ltd</u>	When <u>1893</u>
No. of Main Boilers	<u>2</u>	Boilers, when made (Main) <u>1893 (J. Jones & Sons)</u>	(Donkey) <u>1907</u>
No. of Donkey Boilers	<u>1</u>	Owners <u>Associated Oil Carriers Ltd</u> Port <u>Swansea</u>	Voyage <u>Foreign</u>
Steam Pressure in Main Boilers	<u>160</u>	If Surveyed Afloat or in Dry Dock <u>Afloat</u>	
Steam Pressure in Donkey Boilers	<u>160</u>		

Last Report No. Port

Particulars of Examination and Repairs (if any)

Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

Damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined?

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " "

This was not done, state for what reasons?

What parts of the Boilers could not be thus thoroughly examined?

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

, and of the Donkey Boiler?

Did the Surveyor examine the drain plugs of the Main Boilers?

, and of the Donkey Boiler?

Did the Surveyor examine all the mountings of the Main Boilers?

, and of the Donkey Boiler?

Has the screw shaft now been drawn and examined?

Is it fitted with continuous liner? — or two liners? — or is it without liners?

Has the shaft now been changed?

If so, state reasons

Has the shaft now fitted new?

To

Has it a continuous liner? — or two liners? — or is it without liners?

Has the distance between lignum vitae of stern bush and top of after bearing of screw shaft?

Has the Surveyor not completed what arrangements have been made for its completion and what remains to be done?

Damaged Survey (state of weather)

Upon Examination I found the main discharge pipe cracked at the flange.

The main discharge pipe was removed repaired and replaced.

General Observations, Opinion, and Recommendation:

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9/II, B.M.S. 9/II, or ½ L.M.C. 9/II, 140 lb., E.D., &c.)

I recommend that the vessel's classification be retained as in the Register Book

L.M.C. 1/II

Fees (per Section 26)	<u>W</u> / 1.0	Fees applied for
Initial Damage or Repair Fees (if any) (per Section 26)	<u>W</u>	10
Allowing Expenses (if chargeable)	<u>W</u>	Received by me,
		John L G Cooke

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute	FRI. MAR. 19. 1915	FRI. JUN. 25. 1915	FRI. AUG. 4-1916
Signed	<u>As now</u>	FRI. 31 MAR. 1916	FRI. 6 MAR. 1917
		FRI. 17 AUG. 1917	FRI. 14 JUL. 1916
			FRI. 22 JUN. 1917
			FRI. 18 JAN. 1918

Insert Character of Ship and Machinery precisely as in the Register Book

To a Certificate required if so to be sent to