

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office 6 JUN 1911)

Date of writing Report	5 th June	To 11	When handed in at Local Office	3 rd June	To 11	Port of	Leith
No. in Reg. Book	Survey held at Leith		Date, First Survey		23 rd Jan'y.	Last Survey	24 th May 1911 (No. of Visits)
1765	on the Machinery of the Wood, Iron or Steel		S/S "Stettin"		Master		L Robertson
Tonnage	Gross 876	Net 528	Vessel built at Glasgow	By whom Barclay Curle & Co.	When 1864	YEAR.	11
Registered Horse Power	98	Engines made at Leith	By whom Hawthorn & Co. Ltd.	When 1864	MONTH.		
No. of Main Boilers	2	Boilers, when made (Main)	1864 1889	(Donkey)	1889		
No. of Donkey Boilers	1	Owners Lomie & Co.	Port Leith	Voyage			
Steam Pressure— in Main Boilers	150	If Surveyed Afloat or in Dry Dock Commencing day 1 st (State name of Dock)	Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).				
in Donkey Boilers	50						

Last Survey No. Port

Particulars of Examination and Repairs (if any) L.M.C.

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined? _____ also whether any damage report was made, and, if so, by whom? _____

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? No

Do. " Donkey " " " No

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler? No To what pressure were they afterwards adjusted under steam? 150 lbs

Did the Surveyor examine the Safety Valves of Donkey Boiler? No To what pressure were they afterwards adjusted under steam? 60 lbs

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? Yes, and of the Donkey Boiler? Yes

Did the Surveyor examine the drain plugs of the Main Boilers? Same, and of the Donkey Boiler? Same

Did the Surveyor examine all the mountings of the Main Boilers? No, and of the Donkey Boiler? No

Has screw shaft now been drawn and examined? No Is it fitted with continuous liner? No or two liners? No or is it without liners? ✓

Has shaft now been changed? No If so, state reasons.

Is the shaft now fitted new? Has it a continuous liner? or two liners? or is it without liners?

State the distance between lignum vitae of stern bush and top of after bearing of screw shaft? 8"

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done?

Exam'd cylinders, pistons, shins, pumps, condenser, crank, thrust, tunnel and propeller shafts, all sea cocks, pipes, bilge suction rods and details and found in good condition

The condenser and pumps being defective - much corroded, - the bushes were lightened and taken to shop. A new condenser, air, circulating, feed & bilge pumps supplied complete, and fitted in a satisfactory manner.

Engines refitted, refastened. H.P. cylinder liner removed and a new H.P. piston fitted. Main steam pipes took and refitted.

Main boiler exam'd throughout and found satisfactory. Drift bolts in water tube chamber removed.

Exam'd donkey boiler throughout and found in good order.

All safety valves adjusted.

General Observations, Opinion, and Recommendation:—The machinery of this vessel is

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 0,07, B&M.S. 0,07, or G.L.M.C. 0,07, 140 lbs. F.D., &c.)

now in good order and eligible in my opinion to remain as classed and to have work of L.M.C. 5.11

Survey Fee (per Section 28).....

23.10.-

Special Damage or Repair Fee (if any)
(per Section 28).....

23.10.-

Travelling Expenses (if chargeable).....

E. -

Fees applied for	23.10.-
Received by me,	23.10.-
	19.6.11

Y. A. Shattoe
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute

WED 7 JUN 1911

Assigned

L.M.C. 5.11

S.S. 1/2 due 4/10 - no held throughout re

Master

Engines slowed & shot. ~~Next~~^b - If this Report is copied by Copying Press, special care must be taken that the copying paper is not so much dampened as to spread the ink, or to cause it to show through to the other side.

Contractors & Agents supplied
Engines offered to file.
Agents effected their
bills.

It is submitted that
this vessel is capable for
and适合于
long

John
10/10/11

P. 51

or THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARIN.