

950

Report of Survey for Repairs, &c., of Engines and Boilers.

No. 230		Date of Writing Report	21 st Decemb. 1892	Port of	Trieste	Received at London Office	31 DEC 92
No. in Reg. Book.	Survey held at	Trieste		Date, first Survey	23. 11	Last Survey	20. 12
621	on the Machinery of the			Mineral (late Charles Howard)	Master	Ashfield	1892
Tonnage	Gross	1304				No. of Visits	4
	No.	849	Vessel built at	Sunderland	By whom	W. Sile	YEAR MONTH
Registered Horse Power		120	Engines made at	Stock	When	1866 11	
No. of Main Boilers		1	Owners	A. Stuart	Port	Sunderland	
Steam Pressure in Main Boilers	65 lbs	Surveyed Afloat & in Dry Dock	(State name of Dock.)	San Marco	Voyage	Atlantic + Black Sea	
in Donkey Boiler	50						
Last Survey No.	W. 3 86	Port	Newcastle				
	No. 1 go						
						Class of Vessel & Machinery	
						(As in Register Book, including dates of Special Surveys of Ship and of last Boiler Survey.)	F 90 A 1
							F N B 3.86
							L M C 6.90

Particulars of Examination and Repairs (if any) Repairs of Damage

(State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs.) Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case.

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

Do. " Donkey " "

yes

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

65 lbs yes

At what pressure were they afterwards adjusted under steam?

yes

50 lbs

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted

On the request of the Master I went on board & found the following damage to Machinery which were sustained through stress of weather, when the ship was on her voyage from Philadelphia to St. Louis on the 23rd September & subsequent date. For particulars see log book.

The Main Engine (a Single Crank Engine) having raced heavily the large fly wheel on coupling of Crank shaft & Thrustshaft was loosened and cracked, the shafts strained & several coupling bolts broken.

After taking out & disconnecting this parts having to bore out 6 coupling bolts, found after web of Crankshaft had sustained a bad blow and the two bottom main bearing brasses were cracked. - Joints between H. & L. D. cylinders & between Exhaust column & Condenser appeared started & leaky; L. D. junk ring was cracked, several springs in H. D. piston were broken & valve spindle bent; one Eccentric strap bolt broken & feed valve chest cracked. Several stockhole plates broken & the wood flooring damaged, eight bilge suction pipes broken & bent, & ashguards at front of Boiler damaged.

Continued:

General Observations, Opinion, and Recommendation: - I am of opinion that

(State clearly what alteration, if any, is suggested to be made in the existing classification and notation of the vessel's machinery in the Register Book, consequent upon this survey: thus, for example, B.S. 1.01, B.C.M.S. 1.01 or L.M.C. 1.01, as the case may be.)

Engine & Boilers remain as classed with denotation L.M.C 12.92

It is submitted that
this vessel is eligible for
THE RECORD L.M.C. 12.92
on account of damage the stern
and cranes etc. and the
flywheel have been
repaired and other
repairs carried out
Frederick Phamal

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Office or Registration Fee (per Sec. 21)

£ - - -

Fees applied for

18

Survey Fee (per Section 28)

£ - - -

Received by me,

18

Special Damage Fee (per Section 28)

£ 6 - -

Travelling Expenses (if chargeable)

£ - - -

*State if Certificate is required

Committee's Minute

TUES. 3 JAN 1893

Assisted

L M C 12.92

The following Repairs of damage were done as recommended:
New couplings were welded on Thrust & Crank shafts & coupled up with new bolts, fly wheel patched & hole bored out bigger & fitted on shaft with new keys; also another shaft carriage was fitted on a new support close to wheel. Crank shaft journals taken off & webs reversed & a strong welded ring shrunk on the defective web. Both shafts turned true in lathe, new bottom main brasses fitted & shafts lined up in place, Thrust block reset & liners adjusted.

Engine sky light removed & both Cylinders were lifted out, all clearancing taken off put into shop & examined; new junk ring fitted on L. S. piston, R. S. piston springs renewed, valve spindle turned true & new brass liners fitted in stuffing boxes; feltting partly renewed & all parts put together again as before & re-adjusted.

New bolt fitted for Eccentric strap, a new feed valve chest cast & fitted & feed pipes jointed together where required; space below Engine platforms & bilges ect. properly cleaned for examination.

Sea cocks & valves opened out & ground in, als discharge valves.

The following ordinary Repairs were made:

Piston rods worn, these were turned up in lathe and new brass bushes put in glands and stuffing boxes. Top connecting rod brass found rather than a stout liner was pinned into it. White metal of Bottom connecting rod brasses worn - new metal run into both halves. R. S. valve face planed on the machine & bedded to face. L. S. valve leaky - this was faced up & a brass filling piece fitted in one port. Brass stoppers in bilge pump valve chests renewed & valves ground in. Air valves on Circulating pump damaged, new one were fitted & the pump opened out & put right.

Condenser leaky a number of tubes were drawn, some renewed & the rest cleaned and condenser tested. - Spare Crank shaft turned up in lathe & new coupling fitted to correspond to other Crank shaft, holes & keys cut & secured away in Engine room. Propeller shaft examined, and found it only a little worn down on bush.

Main Boiler in good condition, furnace doors & Cast Iron plates for bridges in furnaces these were repaired & renewed. All valves & cocks ground up & overhauled & leaky seams at shell corked.

Donkey Boiler had a leaky seam at furnace door & plate at one of the sludge doors rather thin, the seam was recorked & stiffening ring fitted on sludge door; all valves & cocks overhauled, new internal feed pipe placed. Main & Donkey Boiler feed pumps overhauled & put in working condition.

All tank & bilge valve boxes in Engine room & stock hole, examined, valves ground in & overhauled.