

Report of Survey for Repairs, &c., of Engines & Boilers.

(Received at London Office, 1689 778)

No. 428 Date of Writing Report 29th April 1889 Port of Havre
 No. in Reg. Book. Survey held at Havre Date, first Survey 19th April Last Survey 26th April 1889
 on the Machinery of the SC St. Géographique Master Pausset 33-89 No. of Visits 5
 Gross 2748 owners Bossière frères et cie
 Net 2001 Vessel built at Newcastle By whom Palmers & Co. When 1872 8th
 Registered Horse Power 290 Engines made at 2^d When 1872 Boilers, when made (Main) 7872 (Donkey) 1872
 No. of Main Boilers 2 Owners Bossière frères et Cie Port Havre Voyage Canada
 Steam Pressure in Main Boilers 60 lbs. If Surveyed Afloat or in Dry Dock yes (at Antwerp) Class of Vessel & Machinery 100 A1
 In Donkey Boiler 60 lbs. (State name of Dock) yes (at Antwerp) (As in Register Book.)
 Last Survey No. 1659 Port Antwerp and LMC 5.87
 S. 3 No 3-5.87

Particulars of Examination and Repairs (if any)

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs.) Repairs on account of Damage should be separated from repairs due to other causes. State also the dates and initials of any letters respecting this case

Did the Surveyor personally go inside each Boiler separately (including the Donkey Boiler, if any), and make a thorough examination at this time? yes

If this was not done, state for what reasons? -

And what parts of the Boilers could not be thus thoroughly examined? -

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of these parts of each boiler? -

- Special survey of the Boilers, now more than 6 years old

| | | | | | |
|----|----|----|---|---|---|
| 12 | 11 | 10 | 9 | 8 | 7 |
| | | | | | |
| | | | | | |
| | | | | | |
| 6 | 5 | 4 | 3 | 2 | 1 |

= Main boilers = The boilers being conveniently disposed, examined the furnaces and combustion chambers and found as follows:
 Furnace no 1: A small irregular patch on a side, and a small circular patch on a side of the combustion chamber; in order.

" no 2: A angular patch at the connexion of furnace, tube plate and a side of the combustion chamber; in good condition. a small crack along a rivet, at the junction of the vertical flange of crown and the tube plate (no leakage); found 10 rivets fitted on flaws of the tube plate, at the intervals of tubes (quite tight). The lower part of sides of combustion chamber a little bent, ends of stay bolts round and tight.

" no 3: A patch at the lower part of ash-pit (entrance); an angular patch at junction of crown and side of combustion (see the other side)

General Observations, Opinion, and Recommendation:--

(State clearly what alteration, if any, is suggested to be made in the existing class notation and notation of the vessel's machinery in the Register Book, consequent upon this survey.)

The boilers are now in a good and satisfactory condition and, in my opinion, merit the favourable consideration of the Committee to be marked BS 4.89 in the Register Book, Subject to being again surveyed within 6 months from the present time, all thicknesses of plating having to be ascertained.

| | | |
|--|-------------|-----------------------------|
| Office or Registration Fee (per Sec. 27) | £ 4 : 4 : 0 | Fees applied for |
| Survey Fee (per Section 28) | £ 4 : 4 : 0 | 188 |
| Special Damage Fee (per Section 28) | £ : | 4. 11. 0 |
| *Certificate (if required) as per margin | £ 0 : 5 : 0 | received by me, |
| Travelling Expenses (if chargeable) | £ 0 : 2 : 0 | 20 th April 1889 |

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute FRIDAY 3 MAY 1889

TUES 30 JULY 1889

Assigned

BS 4/89 Subject &c



© 2018

Lloyd's Register Foundation

chamber; two small flaws along rivets at junction of the vertical flange and the tube plate; this last slightly bent.

Furnace n° 4: A patch at the entrance of ash pit; crown of the furnace in two lengths; the junction was not quite tight, and from having been too often chiselled and caulked, had to be caulked outside. Tube plate, a little bent; at one side of the combustion chamber, a little flaw stopped with a rivet; one side of the combustion chamber a little bent; fitted a stay bolt with a nut.

Furnace n° 5: A patch at entrance of ash pit; two angular patches at end of crown; 3 small patches at sides of combustion chamber and a flaw stopped with two rivets; 5 flaws at intervals of tubes, one of which with a covering patch, and 4 ones stopped with rivets; the lower part of one side of combustion chamber, a little bent.

n° 6: A patch at entrance of ash pit; a small thin blister at crown a crack at a rivet of the flange, a patch at side of C. chamber 3 intervals of tubes showing rivets of stoppage.

n° 7: good condition; one small covering patch at tube plate.

n° 8: A small deflexion at one side of crown; cracks at the

~~n° 9~~ ~~good condition~~ flange along 3 rivets; 8 rivets at intervals of tubes.

n° 9: Furnace in good condition; tube plate a little bent; two patches on flaws.

n° 10: Furnace and combustion chamber, well.

n° 11: Furnace, well; angular patch; tube plate a little bent; a patch at an interval of tubes.

n° 12: Furnace well; a crack at flange; 3 patches at intervals of tubes.

Found the inside of shells at bottom well protected with cement; the lower stays unaltered, the furnaces clean.

Examined the outside of shells, and found several patches at the junction of bottom, front and back.

Examined the inside of the shells, found the plating, riveting stays and staybolts in order, all heating surfaces well cleaned.

Hammered all parts of the plating, including the superheater and found satisfactory.

All the described cracks or flaws, excepting the one at crown of n° 4 furnace, were found tight.

Examined the safety-valves and worked all outfits.

Added 3 2" iron stays at tube plate n° 2, and 4 at n° 4 tube plate.

Verified the new counterweights fitted for the damaged n° 4 of 60 lbs (see the continuation.)

Donkey boiler = Examined the furnace and found a patch at entrance of ash-pit and a elliptical blister 4 in long $\frac{1}{8}$ in thick at crown.

Added a second safety-valve.

Main and Donkey boilers were tested hydraulically under my control and "Commission De Surveillance Des bateaux à vapeur" at twice the working pressures, say at 120 lbs (required by the Commission), viz: the Donkey boiler on 20th April 89 the main boilers on 24th do.

and no leakage, no Deflexion was observed.

Verified again, under steam, the tightness, the correctness of the safety valves and the steam gauges.

}

It is submitted that this vessel is
eligible to have B.S. 4. 14.

recorded, subject to the

unless being again

surveyed within

6 months

MA.

1.5.89



© 2018

Lloyd's Register
Foundation