

No. 3362

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

Date of writing Report	25 th February 1897	When handed in at Local Office	Port of	Antwerp	
No. in Reg. Book.	Survey held at	Antwerp	Date, First Survey	16 th February 1897	
98	on the Machinery of the Wood, Iron or Steel S.s. Dm. Nederland		Last Survey	22 nd February 1897	
Tonnage	Gross 1879		(No. of Vessel by)	Appeld	
Net	2153		YEAR MONTH		
Registered	352 N.H.P.	Vessel built at	Newcastle	By whom	Palmer's (Lym) When 1873 6
Horse Power		Engines made at	D.	When	1873
No. of Main Boilers	Two	Owners Soc. anony. Belg. Americaine	Port	Boilers, when made (Main) 1873 (Donkey) 1873	
No. of Donkey Boilers	One				
Steam Pressure					
in Main Boilers	95 lbs				
in Donkey Boilers	60 lbs				
4 Surveyed Afloat or in Dry Dock No. 1 (State name of Dock.) Afloat Kattendijk Dock - Nine Day					Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Survey No. Port

Particulars of Examination and Repairs (if any) Special Survey No. 3

(Periodical Surveys, when held, must be reported in detail and variation in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarized at the end of the report. State also the dates and initials of any letters respecting this case.)

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

Do.

Donkey

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

At what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

At what pressure were they afterwards adjusted?

Has the propeller shaft been drawn and examined at this time? Yes
If the Survey is not complete state what arrangements have been made for its completion?

and its safety valves to be examined and all safety valves to be adjusted under steam on the ship's return from her present voyage.

The vessel shored in dry dock, on examination found one propeller blade broken off about two feet from the tip and other blades much pitted; clearance of the stern bush $\frac{5}{16}$; the sea cowee bivalve were all opened up ground in and repacked, tail shaft drawn in, etc. and found in efficient condition, examined HP slide valve, cylinder, piston, LP slide valve, crank, thrust intermediate shafts and bearings, air, circulating, feed and bilge pumps also the condenser found in general the machinery in fair working order with the exception of the HP slide valve and cylinder valve face much worn, ridge at top of HP cylinder, feed pump valves and seats battered, the white metal of the HP crank pin bushes cracked and several condenser tubes leaking.

Now done: Rewooded the stern bush, fitted new propeller, planed off HP slide valve face and fitted new valve face to cylinder; chipped off ridge in HP cylinder, renewed feed pump valves and seats also several condenser tubes and pinnacles, fitted HP spare crank pin bushes and overhauled the engines where required.

General Observations, Opinion, and Recommendation:

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 2,01, B&W.N. 4,01 or Q.L.M.C. 4,01, 140 lbs. P.D. &c.)

As far as seen, this vessel's Machinery is now in good and safe working condition, eligible, in my opinion, to remain as classed subject to Completion of Survey as above

Fee or Registration Fee (per Sec. 22)	£ - - - - -	Fee applied for	
Survey Fee (per Section 28)	£ 3. 3. 0	10	
Postal Damage Fee (per Section 28)	£ - - - - -		
Travelling Expenses (if chargeable)	£ - - - - -		

TUES. 9 AUG 1898

Stembot

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

*State if Certificate is required	Not	TUES 20 APR 1897	FRI. 26 NOV 1897	TUES. 10 MAY 1898
Committee's Minute	TUES MAR 2 1897	TUES 20 JUL 1897	TUES. 22 FEB 1898	TUES. 19 APR 1898
Assigned	Deferred	FRI. 30 SEP 1898	TUES. 28 JUN 1898	FRI. 4 NOV 1898
		FRI. 3 FEB 1899		

© 2018

Lloyd's Register
Foundation

1.000' due 05.06 will be completed

on the next' rotation.

Wells. * Laramie river & stream measured &

then again to express what's been made.

It is submitted that this

vessel WILL BE eligible for

the record. 4.0.1.2. 97. 13.0.1.97 when

the S. P. R. G. M. I. S. P. A. L. B. L. B.

& its safety rules have been examined

be coming off port also the

steamer back here have made

out in the main tributaries

left rules I have already

been here been applied

and clean.

The steamer should

be granted a date daily

in his next report date

to return to the con-

sider here her last

Ad.

1.3.97

OF THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARKIN.



© 2018
AF-542-176

Lloyd's Register
Foundation