

# REPORT ON OIL ENGINE MACHINERY.

No. 93151

Inspected at London Office 10 OCT 1928

of writing Report 10 When handed in at Local Office

10 Port of London (Spouch)

Date, First Survey Dec. 3<sup>rd</sup>, 1927 Last Survey Sep. 29<sup>th</sup> 1928

in Survey held at

on the   
 Single   
 Twin   
 Triple   
 Quadruple

Screw vessel

"Viceroy of India" (Auxiliaries for Electric Lighting)

Tons   
 Gross   
 Net

at Glasgow

By whom built G. Stephens + Sons Ltd

Yard No. 519 When built

ines made at Spwisch

By whom made Pelters (Spouch) Ltd.

Engine Nos. 1356 When made 1928.

key Boilers made at

By whom made

Boiler No. When made

ce Horse Power 250. each Engine.

Owners

Port belonging to

Horse Power as per Rule 71. each Engine Is Refrigerating Machinery fitted for cargo purposes

Is Electric Light fitted

de for which vessel is intended

ENGINES, &c. Type of Engines Semi-Diesel 2 or 4 stroke cycle 2 Single or double acting Single

imum pressure in cylinders 450 lbs Diameter of cylinders 14" Length of stroke 16" No. of cylinders 4 No. of cranks 4

of bearings, adjacent to the Crank, measured from inner edge to inner edge 16" Is there a bearing between each crank Yes

utions per minute 275 Flywheel dia. 5'-6" Weight 3700 lbs Means of ignition Electric Kind of fuel used Grade oil

ck Shaft, dia. of journals as per Rule 6.86" Crank pin dia. 7 1/8" Crank Webs Mid. length breadth 10" Kind of fuel used Grade oil

heel Shaft, diameter as fitted 7" Intermediate Shafts, diameter as per Rule as fitted Thrust Shaft, diameter at collars as per Rule as fitted

Shaft, diameter as per Rule as fitted Screw Shaft, diameter as per Rule as fitted Is the tube screw shaft fitted with a continuous liner

ize Liners, thickness in way of bushes as per Rule as fitted Thickness between bushes as per rule as fitted Is the after end of the liner made watertight in the

er boss If the liner is in more than one length are the junctions made by fusion through the whole thickness of the liner

liner does not fit tightly at the part between the bearings in the stern tube, is the space charged with a plastic material insoluble in water and non-corrosive

o liners are fitted, is the shaft lapped or protected between the liners Is an approved Oil Gland or other appliance fitted at the after

the tube shaft Length of Bearing in Stern Bush next to and supporting propeller

eller, dia. Pitch No. of blades Material whether Moveable Total Developed Surface sq. feet

od of reversing Engines Is a governor or other arrangement fitted to prevent racing of the engine when declutched Means of lubrication

Thickness of cylinder liners 1 at top 3/4 at bottom Are the cylinders fitted with safety valves Yes Are the exhaust pipes and silencers scater cooled or lagged with

nducting material If the exhaust is led overboard near the scaterline, what means are arranged to prevent water from being syphoned back to the engine

g Water Pumps, No. One on each Engine Is the sea suction provided with an efficient strainer which can be cleared within the vessel

Pumps worked from the Main Engines, No. Diameter Stroke Can one be overhauled while the other is at work

s connected to the Main Bilge Line No. and Size How driven

st Pumps, No. and size Lubricating Oil Pumps, including Spare Pump, No. and size

o independent means arranged for circulating water through the Oil Cooler Suctions, connected to both Main Bilge Pumps and Auxiliary Bilge

, No. and size:—In Machinery Spaces

ids, &c.

endent Power Pump Direct Suctions to the Engine Room Bilges, No. and size

l the Bilge Suction pipes in Holds and Tunnel Well fitted with strum-boxes Are the Bilge Suctions in the Machinery Spaces

m easily accessible mud-boxes, placed above the level of the working floor, with straight tail pipes to the bilges

Sea Connections fitted direct on the skin of the ship Are they fitted with Valves or Cocks

y fixed sufficiently high on the ship's side to be seen without lifting the platform plates Are the Overboard Discharges above or below the deep scater line

y each fitted with a Discharge Valve always accessible on the plating of the vessel Are the Blow Off Cocks fitted with a spigot and brass covering plate

ipes pass through the bunkers How are they protected

ipes pass through the deep tanks Have they been tested as per Rule

Pipes, Cocks, Valves, and Pumps in connection with the machinery and all boiler mountings accessible at all times

rrangement of valves and their connections such as to prevent the possibility of water passing from the sea or from water tanks into the cargo or machinery spaces, or from one

ment to another Is the Shaft Tunnel watertight Is it fitted with a watertight door worked from

od vessel, what means are provided to prevent leakage of either fuel oil or of lubricating oil from saturating the woodwork

ir Compressors, No. No. of stages Diameters Stroke Driven by

ary Air Compressors, No. No. of stages Diameters Stroke Driven by

Auxiliary Air Compressors, No. No. of stages Diameters Stroke Driven by

gging Air Pumps, No. Diameter Stroke Driven by

ry Engines crank shafts, diameter as per Rule as fitted

RECEIVERS:—Is each receiver, which can be isolated, fitted with a safety valve as per Rule Yes

internal surfaces of the receivers be examined No. What means are provided for cleaning their inner surfaces

a drain arrangement fitted at the lowest part of each receiver Yes

ressure Air Receivers, No. Cubic capacity of each Internal diameter thickness

lap welded or riveted longitudinal joint Material Range of tensile strength Working pressure by Rules

at Air Receivers, No. four Total cubic capacity 102 feet Internal diameter 14 1/2" thickness 400 lbs

lap welded or riveted longitudinal joint Seamless Material Steel Range of tensile strength 28-32 tons Working pressure by Rules



IS A DONKEY BOILER FITTED?

If so, is a report now forwarded?

PLANS. Are approved plans forwarded herewith for Shafting *Crank Shaft*. Receivers. Separate Tanks

Donkey Boilers  General Pumping Arrangements  Oil Fuel Burning Arrangements

SPARE GEAR. *As per attached list.*

The foregoing is a correct description,

Manufacturer.

Dates of Survey while building { During progress of work in shops - - }  
{ During erection on board vessel - - }  
Total No. of visits

Dates of Examination of principal parts—Cylinders *10-12-27 26-3-28 19-12-27*  
*8-1-28 27-2-28 15-1-28* Covers *14-4-28* Pistons *3-1-28 19-4-28 11-1-28 17-4-28* Connecting rods  
Crank shaft *10-12-27 4-2-28 3-1-28 14-4-28* Flywheel shaft *Linas* Thrust shaft *Linas* Intermediate shafts *Linas* Tube shaft *Linas*

Screw shaft  Propeller  Stern tube  Engine seatings  Engines holding down bolts

Completion of fitting sea connections  Completion of pumping arrangements  Engines tried under working conditions

Crank shaft, Material *Steel* Identification Mark *LLOYD'S 19/12/28. A.S.T.* Flywheel shaft, Material  Identification Mark

Thrust shaft, Material  Identification Mark  Intermediate shafts, Material  Identification Marks

Tube shaft, Material  Identification Mark  Screw shaft, Material  Identification Mark

Is the flash point of the oil to be used over 150° F. *Yes.*

Is this machinery duplicate of a previous case  If so, state name of vessel

General Remarks (State quality of workmanship, opinions as to class, &c. *These engines have been constructed under special survey & the Society's Rules, the materials + workmanship are good. On completion of the engines were coupled to an electric generator + run at full power for 4 hours + 10% overload for 1 1/2 hours. engine + generator worked satisfactory throughout the trial. Has now been sent to Glasgow to be fitted on the vessel.*

Certificate (if required) to be sent to  
(The Surveyors are requested not to write on or below the space for Committee's Minute.)

The amount of Entry Fee ... £ : : :  
Special ... £ *14-4-0* : : :  
Donkey Boiler Fee ... £ : : :  
Travelling Expenses (if any) £ : : :  
When applied for, *13 OCT 1928*  
When received, *Low loc 10/2/29*

*A.E. Farminier.*  
Engineer Surveyor to Lloyd's Register of Shipping  
TUE. 9 APR 1929

Committee's Minute *GLASGOW 12 MAR 1929*  
*Assigned See Glasgow Report No 48950*