

Report of Survey for Repairs, &c., of Engines and Boilers.

THUR. 17 SEP 1896

(Received at London Office)

Port of London

Date of writing Report 16th Sept. 96 When handed in at Local Office

No. in Reg. Book. Survey held at London.

634. on the Machinery of the Wood, Iron or Steel S.S. Silvertown " ex Hooper Master D. Morton.

Tonnage Gross 14935 Net 3724 Vessel built at Newcastle By whom C. Mitchell & Co. When 1873 3

Registered Horse Power 4466 Engines made at Do. When 1873 Boilers, when made (Main) 1880 (Donkey) 1880

No. of Main Boilers 4 Owners and Rub. Gut. per. & Griff. London. Voyage Laid up.

No. of Donkey Boilers 1 If Surveyed Afloat or in Dry Dock Royal Victoria Dock Articulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Steam Pressure— in Main Boilers 80 in Donkey Boilers 80 (State name of Dock.)

Last Survey No. 57686 Port Lon

Particulars of Examination and Repairs (if any) Repair of Boilers

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Furnaces & combustion examined

Do. " Donkey " " No.

If this was not done, state for what reasons? Not due for survey.

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

At what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted?

Has the propeller shaft been drawn and examined at this time?

If the Survey is not complete state what arrangements have been made for its completion? Complete.

On account of wear & tear the following repairs were effected—the crowns of the centre furnace of the forward Starboard boiler, the forward furnace of the after port boiler, and the after furnace of the forward port boiler were cut out and renewed. One patch and several rivets in butt straps of forward furnace of forward Starboard Boiler renewed. One patch in forward furnace of forward port B. and two in centre furnace of after starb. B. also renewed. The three boilers in which the crowns were renewed were tested under an hydraulic pressure of 120 lbs. & found tight.

General Observations, Opinion, and Recommendation:—This vessel's boilers are now in safe working condition and eligible, in my opinion, to remain as classed without further record of survey.

Office or Registration Fee (per Sec. 27).....	£	1	Fees applied for
Survey Fee (per Section 28).....	£	1	18
Special Damage Fee (per Section 28).....	£	1	
Travelling Expenses (if chargeable).....	£	1	

*State if Certificate is required.

Committee's Minute FRI. 18 SEP 1896

Assigned as now. N.

R. Elliott

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Three courses of grumes renewed
other repairs in main bilges.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much dampened as to spread the ink, or cause it to show through to the other side.

It is submitted that
this vessel is eligible to
remain AS CLASSED.

J. H. S.
11.9.96

* THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.