

REPORT ON STEAM RECIPROCATING ENGINE MACHINERY.

Received at London Office

Date of writing Report 29 AUGUST 1942 When handed in at Local Office 29 AUGUST 1942 Port of VANCOUVER, B.C.No. in Survey held at VICTORIA, B.C. Date, First Survey 9 APRIL Last Survey 13 AUGUST 1942
Reg. Book. (Number of Visits)on the STEEL SINGLE SCREW STEAMER, "FORT DOUGLAS" Tons Gross 7128.82
Net 4260.89Built at VICTORIA, B.C. By whom built VICTORIA MACHINERY DEPOT CO. LTD. Yard No. 21 When built 1942Engines made at TORONTO - ONT. By whom made JOHN INGLIS CO. LTD. Engine No. 75 When made 1942Boilers made at VANCOUVER, B.C. By whom made VANCOUVER IRON WORKS LTD. Boiler Nos. 161
163 When made 1942
164Registered Horse Power 229 Owners MINISTER OF MUNITIONS & SUPPLY OF CANADA Port belonging to -Nom. Horse Power as per Rule 504 Is Refrigerating Machinery fitted for cargo purposes NO Is Electric Light fitted YESTrade for which Vessel is intended GENERAL CARGO

ENGINES, &c.—Description of Engines TRIPLE EXPANSION - SUPERHEAT TO 575°F Revs. per minute 80
 Dia. of Cylinders 24 1/2" x 34" x 70" Length of Stroke 48" No. of Cylinders 3 No. of Cranks 3
 Crank shaft, dia. of journals as per Rule 13.99" Crank pin dia. 14.25" Crank webs Mid. length breadth 24 1/2" Thickness parallel to axis 7 1/8" PIN
 as fitted 14.25" Mid. length thickness 9 1/2" H.P. & M.P. shrunk Thickness around eye-hole 7 5/8" JOURNAL
 Intermediate Shafts, diameter as per Rule 13.33" Thrust shaft, diameter at collars as fitted 14.25"
 as fitted 13.5" Tube Shafts, diameter as per Rule - Screw Shaft, diameter as per Rule 14.87" Is the tube shaft fitted with a continuous liner YES
 as fitted - as fitted 15.25" Is the screw YES
 Bronze Liners, thickness in way of bushes as per Rule .75" Thickness between bushes as per Rule .5625" Is the after end of the liner made watertight in the
 as fitted .78125" as fitted .68" propeller boss YES If the liner is in more than one length are the junctions made by fusion through the whole thickness of the liner SOLID
 If the liner does not fit tightly at the part between the bearings in the stern tube, is the space charged with a plastic material insoluble in water and non-corrosive TIGHT FIT
 If two liners are fitted, is the shaft lapped or protected between the liners - Is an approved Oil Gland or other appliance fitted at the after end of the tube
 shaft NO If so, state type - Length of Bearing in Stern Bush next to and supporting propeller 61"
 Propeller, dia. 18 1/2" Pitch 16 1/2" No. of Blades 4 Material BRONZE whether Moveable NO Total Developed Surface 117 sq. feet
 Feed Pumps worked from the Main Engines, No. NONE Diameter - Stroke - Can one be overhauled while the other is at work -
 Bilge Pumps worked from the Main Engines, No. TWO Diameter 4 1/2" Stroke 26" Can one be overhauled while the other is at work YES
 Feed Pumps { No. and size TWO - 10" x 7" x 2 1/2" - 4000 IMP. GAL. Pumps connected to the { No. and size (BUE) 1-10" x 12" x 10" - 1-9" x 6" x 10" - 2- RAMS.
 How driven STEAM - "WORTHINGTON TYPE" Main Bilge Line { How driven DUPLEX STEAM - DUPLEX STEAM - MAIN ENG.
 Ballast Pumps, No. and size ONE - 10" x 12" x 10" DUPLEX Lubricating Oil Pumps, including Spare Pump, No. and size NONE
 Are two independent means arranged for circulating water through the Oil Cooler - Suctions, connected to both Main Bilge Pumps and Auxiliary
 Bilge Pumps;—In Engine and Boiler Room ENG. RM. 1-3" DIA. PORT & STARBOARD - BLR RM. 1-3" DIA. PORT & STARBOARD - THRUST RECESS - 1-2" DIA.
 In Pump Room - In Holds, &c. FOREPEAK - 1-4" DIA. - NOS 1-2-3-4-5 HOLDS - 1-3" DIA. PORT
& STARBOARD IN EACH HOLD - 1-4" DIA. IN AFT. PEAK - 1-2 1/2" DIA. TO TUNNEL WELL.
 Main Water Circulating Pump Direct Bilge Suctions, No. and size ONE - 9" DIA. Independent Power Pump Direct Suctions to the Engine Room Bilges,
 No. and size ONE - 5" DIA. - STARBOARD SIDE Are all the Bilge Suction Pipes in holds and tunnel well fitted with strum-boxes YES
 Are the Bilge Suctions in the Machinery Space led from easily accessible mud-boxes, placed above the level of the working floor, with straight tail pipes to the bilges YES
 Are all Sea Connections fitted direct on the skin of the ship YES - MAIN INJECTION FITTED TO Are they fitted with Valves or Cocks VALVES & COCKS
 Are they fixed sufficiently high on the ship's side to be seen without lifting the stokehold plates YES Are the Overboard Discharges above or below the deep water line BELOW
 Are they each fitted with a Discharge Valve always accessible on the plating of the vessel YES Are the Blow Off Cocks fitted with a spigot and brass covering plate YES
 What Pipes pass through the bunkers STEEL AIR PIPES TO NO 4 D.B. TANK How are they protected STEEL STRAPS WELDED ACROSS FRAMES
 What pipes pass through the deep tanks NO 7 D.B. TANK AIR PIPES Have they been tested as per Rule YES
 Are all Pipes, Cocks, Valves, and Pumps in connection with the machinery and all boiler mountings accessible at all times YES
 Is the arrangement of Valves and their connections such as to prevent the possibility of water passing from the sea or from water tanks into the cargo or machinery spaces, or from one
 compartment to another YES Is the Shaft Tunnel watertight YES Is it fitted with a watertight door NO worked from -

MAIN BOILERS, &c.—(Letter for record S) Total Heating Surface of Boilers 7140 SQ. FT. ✓
 Is Forced Draft fitted YES No. and Description of Boilers 3- SINGLE END MULTITUBULAR Working Pressure 220 LBS. PER SQ. IN.
FITTED WITH SUPERHEATERS

IS A REPORT ON MAIN BOILERS NOW FORWARDED? YESIS A DONKEY BOILER FITTED? NO If so, is a report now forwarded? -Is the donkey boiler intended to be used for domestic purposes only -PLANS. Are approved plans forwarded herewith for Shafting APPROVED PLANS IN UNITED KINGDOM. Main Boilers - Auxiliary Boilers - Donkey Boilers -
(If not state date of approval)Superheaters - General Pumping Arrangements - Oil fuel Burning Piping Arrangements -

SPARE GEAR.

Has the spare gear required by the Rules been supplied YES

State the principal additional spare gear supplied.

AS PER LIST FORWARDED WITH VCR. RPT. NO 5718 - "S.S. FORT ST. JAMES"

The foregoing is a correct description,

Victoria Machinery Depot Co., Ltd.

J. Couper

Manufacturer.

PILLA
Cen
St
Pl
STRIP
Up
St
Th
Th
Th
If
Sec
St
FLAT P
BOTOM
of Str
BILGE F
Strake
SIDE P
Strake
UPPER
strake
UPPER
strake
STRAKE
strake
STRAKE
strake
POOP S
BRIDGE
FOREC'
Total
MIDSE
COLLI
AFTEI
STEE

During progress of work in shops - - - SEE TORONTO, ONT. RPT. NO. 835
Dates of Survey while building - - - 1942. April 9-13-16-17-20-21-22-24-30. May 1-13-29. June 3-4-5-6-10-12-18-22-23.
During erection on board vessel - - - July 2-6-10-12-14-15-16-17-21-22-24-25-28-31. August 1-2-3-4-5-6-7-8-10-11-12-13.
Total No. of visits 47

Dates of Examination of principal parts - Cylinders Slides Covers
Pistons Piston Rods RPT. NO. 835 Connecting rods
Crank shaft SEE TORONTO, ONT. RPT. NO. 835 Thrust shaft 12-9-41 - 7-2-42. Intermediate shafts 23-1-42 - 16-1-42.
Tube shaft - Screw shaft 20-12-41 - 20-4-42. Propeller 24-4-42 - 21-7-42.
Stern tube 25-3-42 - 16-4-42. Engine and boiler seatings 6-3-42 - 12-6-42. Engines holding down bolts 2-7-42.
Completion of fitting sea connections 29-4-42
Completion of pumping arrangements 28-7-42. Boilers fired 12-6-42. Engines tried under steam 25-7-42 - 8-8-42.
Main boiler safety valves adjusted 24-7-42. Thickness of adjusting washers 3442 - 352-8-41 - 3468-3-5, 10-10-41. (RV 475) (RV 1600) (RV 628)
Crank shaft material O.H. STEEL. Identification Mark J.B. 7-2-42. Thrust shaft material O.H. STEEL. Identification Mark O.N. 12-9-41. (Loyos 3942) (Loyos 3065-23-1-42 T.M.) (Loyos 3064-16-1-42 T.M.) (Loyos 3035-16-1-42 T.M.) (Loyos 6441)
Intermediate shafts, material O.H. STEEL. Identification Marks 3068-23-1-42 T.M. (Loyos 4040) (Loyos 3087-23-1-42 T.M.) (Loyos 3064-23-1-42 T.M.) Identification Mark
Screw shaft, material O.H. STEEL. Identification Mark 20-12-41. Steam Pipes, material S.D. STEEL. Test pressure 660 LBS. Date of Test 17-7-42.
Is an installation fitted for burning oil fuel. No. Is the flash point of the oil to be used over 150°F.
Have the requirements of the Rules for the use of oil as fuel been complied with.
Is the vessel (not being an oil tanker) fitted for carrying oil as cargo. No. If so, have the requirements of the Rules been complied with.
If the notation for Ice Strengthening is desired, state whether the requirements in this respect have been complied with.

Is this machinery duplicate of a previous case. YES. If so, state name of vessel S.S. "FORT CAMOSUN" - V.R. RPT. NO. 5769

General Remarks (State quality of workmanship, opinions as to class, &c.) The Machinery of this vessel has been constructed under Special Survey of the Toronto, Ont. Surveyors, and installed on board under Special Survey in accordance with the approved plans, New York letter and otherwise in conformity with the Society's Rules. The Materials and workmanship are good and the tests required by the Rules have been satisfactorily carried out. The whole installation has been examined and tested under full working conditions on sea trials and afterwards opened out, examined and found satisfactory. The Machinery has also been surveyed during construction and installation on behalf of Wartime Merchant Shipping Ltd., to ensure that the terms of the Specifications have been fully complied with and this work has been satisfactorily carried out.

The Machinery of this vessel is eligible in our opinion to be classed in the Register Book with Notation + L.M.C. 8-42 - SCREW SHAFT. C.L. 3 - S.E. BOILERS 220 LBS. PER SQ. INCH. F.D.

Please refer to Continuation Sheet for particulars of damage sustained at time of launching.

The amount of Entry Fee ... £ : : When applied for,
Special ... £ 133.00 10th Aug. 1942
Donkey Boiler Fee ... £ : : When received,
Travelling Expenses (if any) £ 60.00
Committee's Minute TUE 10 NOV 1942
Assigned J.D. C.A.,

S.S. "FORT DOUGLAS" (DAMAGE)

This Vessel was successfully launched at 3:15 A.M., 30th April, 1942, and about 3:45 A.M., the same day, grounded on the Victoria Harbour Breakwater, damaging propeller.

NOW DONE:-

Vessel placed on drydock.

PROPELLER (Bronze 4 Blades)

1 Blade bent forward at tip and small piece broken out at tip.

New Bronze propeller now fitted.

SCREW SHAFT

Drawn, placed in lathe, tested for truth and found good. Shaft refitted.

STERN TUBE, stern bush and fastenings specially examined and found satisfactory.

Please refer to copy of Damage Report attached to Hull First Entry Report.

S.D. Boomer per R.R.