

REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office

16 OCT 1946

Date of writing Report 10-10-46 When handed in at Local Office 19-10-46

Port of LIVERPOOL

No. in Survey held at Glasson Dock (Plan) Date. First Survey 2/9/46 Last Survey 3/9/46 (No. of Visits 8)

66503 on the Machinery of the Wood, Iron or Steel ST. ST PHILIP (EX KUNISHI)

Gross Tonnage 303 Net 214 Nominal Horse Power 99 HP No. of Main Boilers 150 No. of Donkey Boilers 10 Steam Pressure in Main Boilers 180 in Donkey Boilers 100 Vessel built at Ince, Lancs. By whom Smiths Dock Co. Ltd. Engines made at " By whom " Boilers, when made (Main) (Donkey) Owners Boston Dock & Sea Fisheries Co. Ltd. Managers R.A. Parkes If Surveyed Afloat or in Dry Dock Glasson Dock

Particulars of Classification which must be inserted precisely as in Register Book & Supplements.

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Years assigned now expired.	Machinery and Boiler Surveys (Including date of N.B., if any)
Classification contemplated		

Last Report No. Port

Particulars of Examination and Repairs (if any) Classification (LMC)

Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

Damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined. Not applicable

Was a damage report made by anyone else? If so, by whom? "

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

Did the Surveyor personally go inside each Donkey Boiler separately and make a thorough examination at this time? "

What parts of the Boilers could not be thus thoroughly examined? Not stated

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? Not stated

State latest date of internal examination of each boiler. Present condition of funnel? Good

Did the Surveyor examine the Safety Valves of the Main Boilers? 12-8-46 To what pressure were they afterwards adjusted under steam? 180 lb./sq. in.

Did the Surveyor examine the Safety Valves of the Donkey Boilers? " To what pressure were they afterwards adjusted under steam? "

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? Yes, and of the Donkey Boilers? "

Did the Surveyor examine the drain plugs of the Main Boilers? None, and of the Donkey Boilers? "

Did the Surveyor examine all the mountings of the Main Boilers? Yes, and of the Donkey Boilers? "

Has the screw shaft now been drawn and examined? Yes Has it a continuous liner? Yes Is an approved oil retaining appliance fitted at the after end? No.

Has the shaft now been changed? No If so, state reasons. Has the shaft now fitted been previously used? No Has it a continuous liner? "

Is an approved oil retaining appliance fitted at the after end? No State date of examination of Screw Shaft. 12-8-46 State the wear down in the stern bush. Close fit

Is electric light and/or power fitted? Yes If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses? Yes

Is the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? Yes

When the Survey is not complete, state what arrangements have been made for its completion and what remains to be done. Complete.

Work Done:- Messes placed in dry dock propellers, stem tube, sea cocks, valves & their fastenings examined & found or placed in good condition. Screw shaft drawn & examined.

Examined cylinders, piston valves & casings, crank & thrust shafts, main & auxiliary pumps, pumping arrangements, condenser (tested) main steam pipe (tested), windlass, steering engine & electrical installation, shore gear & all found in place in efficient good condition.

Examined the boiler throughout with mountings, doors & fastenings & found in place in good condition & subsequently examined under steam & safety valves adjusted to pressure as above.

For Particulars of scantlings of the Engines & Boilers now taken please see Survey Entry reports attached. :- (Please see continuation sheet.)

General Observations, Opinion, and Recommendation:- The machinery of this vessel is in a good &

efficient condition and is eligible in my opinion to be classed with the Society with record of Survey LMC 9-46 & to have the notation of TS (CL) 8-46


License Fee

Survey Fee (per Section 29) £ 25 0 0 Conversion & Classification 25 0 0 Special Damage or Repair Fee (if any) (per Section 29) £ : : Travelling expenses (if chargeable) £ 12 7 0

Fees applied for 11 OCT 1946 Received by me, J.A. Lindley

Engineer Surveyor to Lloyd's Register of Shipping.

Committee's Minute LIVERPOOL 15 OCT 1946 LMC 9.46 T.S. 8.46



Insert Character of Ship and Machinery precisely as in the Register Book.

Is a Certificate required? If so, to be sent to

Noted
Bell
24/10/46

[Faint, mostly illegible handwritten text, possibly bleed-through from the reverse side of the page.]



© 2020

Lloyd's Register
Foundation

S/T. ST PHILIP (EX KUNISHI).

Boiler Repair :-

Crane lift lifting + re-headers.

Condenser shell bottom half renewed complete.

50% of tubes renewed, condenser tested on completion.

Main steam pipe renewed complete.

LP piston renewed + rings renewed throughout.

All pins + walsingham tubes annealed + tested.

Auxiliary + main engine pumps overhauled, chambers
bored out + new buckets + piston fitted.

All bilge suction pipe lines renewed to engine room
+ holds.

Wendler + stem gear overhauled. steady men
retain effects.

Stem tube removed for access for stem frame
repairs, examined + replaced.

TS lower stemmed + bush renewed.

FP tank suction line renewed complete.

On completion the main + auxiliary machinery, pumping
arrangements examined under trial conditions + found
satisfactory.

Boiler Repair :- Several welds on back + ring stays
renewed.

Gas collector check renewed.

Bottom door flange built up electrically +
door fitted.

J.A.F.

Electrical Equipment,

Installation examined + tested under working conditions on
completion of repair and renewal. Insulation test carried out. All found
satisfactory. Details of electrical equipment are as shown on first entry
Reports attached hereto.

td.