

REC'D NEW YORK JUL 8 1942

(Received at London Office 18 AUG 1942)

No. 2182

Rpt. 8.

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 8 May 1942 When handed in at Local Office

Port of Curacao, N.W.I.

No. in Survey held at Curacao, N.W.I. Date, First Survey Oct 1940 Last Survey 1 May 1942
Reg. Book. 701942 on the Wood, Iron or Steel m.v. Bonaire ex Henry Horn ex Residente (No. 77) ex Walder Van No. of Visits 77
TONNAGE: Built at Hamburg By whom Reitberg, Schiffst. Masch. When 1926
GROSS 3164
UNDER D.K. 2526
NET 1857
Owners Government of Curacao N.W.I. Owners' Address Curacao N.W.I.
Managers Royal Netherlands Steamship Co. Port belonging to Willemstad
Surveyed Afloat and Name of Dock Juliani Dry Dk. Destined Voyage
CellDBorDBa feet; uE&B feet; f feet
total capacity tons. FPT tons; APT tons; MT feet tons.Only alterations in the existing records of tanks should be inserted.
N.B.—All alterations in the existing records should be underlined.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER.
 for Special Survey.
Date of last Survey and of Periodical Surveys.

Machinery and Boiler Surveys (including date of N.B., if any).

(Class contemplated)

Last Report, No. Port

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Freeboard (if assigned) as painted on Ship and now verified } fl. ins.

Was a damage report made by anyone else? If so, by whom?

*Classification First Entry, 2nd Special Survey No. 3, Drydocking Repairs
now due:- Vessel placed in dry dock, bottom, sides & rudder (lifted) cleaned, examined, placed in satisfactory condition & recaulked. All wood ceiling, timbers, cargo battens and broken cement chocks removed from the holds, all steel work repaid & cleaned. The holds, tween decks, machinery spaces including under decky bridge, bridge, poop, forecastle and peak spaces, chain lockers and plating under sidelights examined, shell plating drilled, all placed in satisfactory condition & caulked. All double bottom tanks, cofferdams, liner tanks & peak tanks cleaned, broken cement removed, examined internally including structure in way of struts, fitted to rule requirements, placed in satisfactory condition and caulked where necessary. The decks, with portions of sheathing & coaming removed from superstructure decks, ceiling hatches, beams & coopers (in place) & parapetins, deck battens, ventilator coverings, mast (no wedges).*

SUMMARY OF DAMAGE REPAIRS:-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items.
Renewed								<i>where all continuation shds</i>
Removed and Fairied or Repaired								
Fairied or Repaired in place								

PRESENT CONDITION OF THE

Decks	<i>Good</i>	Bulkheads	<i>Good</i>	Engine Room Skylights	<i>Good</i>	Copper or Y.M. (State if on Felt.)	<input checked="" type="checkbox"/>
Caulking of Decks	<i>Good</i>	Ceiling	"	Bunkers, Openings, Covers, &c.	"	When fitted, Month	<input checked="" type="checkbox"/> Year <input checked="" type="checkbox"/>
Coamings	"	Cement or Asphalt	<i>Good</i>	Oil Bunkers	"		
Beams & Fastenings	"	Rudder	<i>Good</i>	Scuppers	"		
Outside Plating	"	Steering gear and its connections	"	Gage Hatchways	"		
" " in way of sidelights	"	Windlass	"	Hatches	"		
Frames	"	Have pumps been examined and found efficient?	<i>Yes</i>	Planking			
Reverse Frames	"	Have Sluice Valves been examined and found efficient?	<i>Yes</i>	Gauking			
Longitudinals	"	Have Watertight Doors been examined and found efficient?	<i>Yes</i>	Treenails			
Transverses	"	Have Ventilators and their Coamings been examined and found efficient?	<i>Yes</i>	Breasthooks & Stemson			
Floors	"	Air and Sounding Pipes	<i>Good</i>	Transoms, Pointers & Crutches			
Keelsons	"	Doubling Plates under Sounding Pipes	"	Timbers of Frame at openings			
Stringers	"			" " another places			
Inner Bottom Plating	"			Stringers, Clamps & Shelves			
Have the Tanks been examined internally?	<i>Yes</i>			Salting			
Have the Tanks been tested?	<i>Yes</i>			(State if examined.)			

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1-38," or "to remain as classed and to have record of survey, 1-38, and the notations of ss No. 1-38."

This vessel is now in a good and efficient condition and eligible in my opinion to be assigned the notation 100 A1, 2nd Special Survey No. 3 with date and record of Survey 2-42 when the equipment has been placed in accordance with the Rule Requirements.

Survey Fee (per Section 20) 1st Entry	<i>Yes.</i>	1575:00	Fees applied for,
Special Repair Fee (if any) (per Sec. 20)	<i>Yes.</i>	250:00	8 May 1942
Travelling Expenses (if chargeable)	<i>Yes.</i>	64:50	Received by me,
Second Surveyor's Fee (if any)	<i>Yes.</i>	787:50	19
Assignment of Load Line	<i>Yes.</i>	150:00	
Committee's Minute			

Character Assigned

DUTCH VESSEL WRITE ST.

W. Th. J. van der Poel
Surveyor to Lloyd's Register of Shipping.

See Other Co. Rpt. 2182

© 2020



Lloyd's Register Foundation

m.v. "Bonaire"

rigging, boats, windlass, electric and hand steering gear, watertight doors, pumps, air & venting pipes with damping plates underneath, general equipment and etc., except anchors & cables, examined and placed in satisfactory condition.

Freight markings verified with those contained on the old certificates and letters changed from G.L. to L.R. Provisional freight certificates, valid for six months, issued by Curacao Government pending arrangement of new freightards by the Society. Report C 11 Linstead.

To complete the special survey, the anchors and cables to be ranged, tested and placed in accordance with the rule requirements. This will be attended to at the first convenient opportunity.

Repairs

Main deck:

5 plates renewed in stoke adjoining stringer on p.s. forward.

5 " " " " " " " " S.S. "

4 " " " " " " " " 35. aft.

3 " " " " " " " " p.s. "

1 " " " " " " " " No 1 hatch on p.s.

3 " " " " " " " " No 192 hatch on S.S.

4 " " " " " " " " No 374 hatches on S.S.

2 " " " " " " " " No 4 hatch on p.s.

2 " part renewed between No 192 hatch ends.

2 " " " " " " " " 374 "

2 stringer plates renewed on p.s. aft.

3 " " " " " " " " 2-3. bridge space.

1 " " " part renewed on S.S. bridge space.

Deck plates doubled between No 1 hatch corner & forecastle bulkhead.

" " " " " half " " " " " prop "

7 hatch corner doublers renewed.

Deck plating renewed in fore peak stow space.

" " fitted with small doublers at prop entrance.

After deck angle renewed on No 4 hatch.

Horizontal bulk stiffener renewed on S.S. No 3 hatch.

120 cleats renewed on forward hatches.

76 " " " after "

2 beams renewed for No 4 hatch.

1 " " " " No 3 "

Wood hatch covers renewed throughout. X

6 starpankins renewed.

All latten bars renewed.

All bulwark filling port shutters renewed.

1 ventilator covering renewed on S.S. forward.

1 " " " " " " " " S.S. aft.

Please see continuation sheet.

m.v. "Bonaire"

Main deck continued.

2 ventilator coverings part renewed (approx 7ft) on fore deck.

2 " " " renewed from main deck to prom. deck aft.

2 " " " part renewed (approx 7ft) on after deck.

8 ladders renewed from main deck to forecastle, bridge & prop deck.

Ladders renewed on fore & main masts.

ladder " " forward star. ventilator starboard port.

All winch foundation channels renewed.

Water service line renewed throughout.

Other minor repairs effected.

Forecastle deck:-

Wood sheathing removed, refitted with part new & caulked.

Deck plating fitted with small doublets & odd places where fitted

All ventilator coverings renewed.

Paint locker steel door on ss bulkhead renewed.

All door locks placed in good order.

Other minor repairs effected.

Bridge:-

3 deck plates renewed on port side adjoining stringer.

3 " " " " " machinery casing.

1 " " " " " other. " " "

3 " " " " " stringer & 1 part renewed.

3 " " " " in centre at after end.

Corner doublets renewed at after end of machinery casing.

Wood sheathing removed, refitted with part new & caulked.

All T bar pillars renewed from bridge front to promenade deck.

One watertight door with fittings renewed on front bulkhead.

Two " " " " " after " " .

Other minor repairs effected.

Porth:-

All wood sheathing renewed.

Deck plating renewed throughout except after plate & stringers.

After deck plate doubled.

4 ventilator coverings renewed.

Companionsway door & fittings renewed.

Steam chain locker sides renewed.

Two watertight doors with fittings renewed on bulkhead.

Other minor repairs effected.

Promenade Deck:-

2 stringer plates renewed on port side

1 " " " " " other. "

1 central " " at after end.

2 plates renewed in stanches adjoining machinery casing on other side

1 " part " " " " " "

Please see 3rd Combination Sheet.

m.v. Bonaire

Promenade deck continued:-

2 plates renewed on port side adjoining stringer.

2 " " " stbd. - " "

1 " port renewed " port " " "

Balustrade plating renewed on port sides forward.

All T bar pillars supporting boat deck front renewed.

Approx. 25% of wood sheathing renewed & all caulked.

Asbestosite composition placed on deck in way of accommodation.

Other minor repairs effected.

Boat deck:-

11 plates renewed on port side

3 " " at centre.

8 " " on starbd. side and 1 port renewed.

Approx. 30% of wood sheathing renewed & all caulked.

Asbestosite composition placed on deck in way of accommodation.

Engine room skylight renewed throughout.

Fiddley top plating part renewed.

Dustole air & steam pipes renewed.

Other minor repairs effected.

Fore Peck:-

Tank top plating renewed throughout.

14 frames renewed from tank top to main deck.

Bulbhead renewed for 3 feet above tank top for full width.

No 1 hold:-

2 stiffener brackets renewed on collision bulkhead.

26 shell frames fitted with iron plates in way of bilge brackets where needed.

Forward centre line bulkhead in lower hold part renewed at bottom.

After " " " - twin deck " " " "

No 2 hold:-

Forward centre line bulkhead part renewed at bottom.

Twin deck plating part renewed in three places, approx 4' x 2' each.

No 4 hold:-

Journal plating part renewed on ss. & doubled on port side at bottom.

No 10 D.B. tank top doubled over small area in way after manhole.

Approx 80% wood ceiling, timbers & cargo battens renewed in all holds.

" 10% " covers renewed in twin deck hatches.

Two lifeboats with equipment renewed.

Rudder pintles & bushes overhauled.

Other minor repairs effected.

W. Chapman