

26 NOV 1959

WRECK

Rpt. 9 SECTION
Date of writing report 15/10/59

Survey held at SINGAPORE

WRECK
SECTION

No.

20 NOV 1959

SINGAPORE

No. 13572

First date 13.10.59 Last date 16.10.59

REPORT OF PERIODICAL SURVEYS & REPAIRS OF MACHINERY

No. in R.R. 05828 Name S.S. "CAPE ORA"

Owners GALARO CIA NAV. S.A.

Engines made 1937-5 by N.E. MARINE ENG. CO. LTD.

No. of Main Engines 1 No. of Screws 1

No. of Main Boilers 3 SB W.P. 220 lb Spt.

No. of Donkey/Donkey Boilers - W.P. -

Surveyed Afloat or in Dry Dock Afloat

Nature of Survey Damage

Was Damage Report issued? No Int. Cert? Yes

Last Report (For Head Office only)

Gross Tons 5282 Date of built 1937-5

Port of Registry FUERTO LIMON

Type T 3C

Records of Survey & Special Notices as per Register Book

Hull	Machinery	
+100A1 SS11/58(Adv) with freeboard	+LMC	11.58 (Adv.)
	MBS	4.59
	TSCL	11.57
Dkg. 4,59	Sps	6.58
SS (adv.) 11.58		
		OF4/50

The condition of any of the following items is to be described as "good" only when the part has been examined, found or placed in good condition, and is considered to be acceptable until the due date of the next Periodical Examination. Where it is considered that re-examination or repairs should be effected before the due date of the next Periodical Examination a distinguishing mark thus + should be inserted against the item and the circumstances and action recommended described fully under "defects and repairs". At part or complete Special Surveys those items which are not applicable to the ship should be cancelled with a black line; this need not be done when the machinery is on a continuous survey basis. When any part has been subjected to pressure test this should be stated. Engine parts when referred to by numbers should be counted from forward.

DOCKING Propellers	Wear Down of Stern Bushes	Oil Glands	Sea Connections
Fastenings	Has Screwshaft Tubeshift been drawn?	Date of Examination	Has Shaft been changed?
			Approved oil gland?
	Has Shaft now fitted been previously used?	Has Shaft now examined/fitted a continuous liner?	
MAIN ENGINES (Recip. Steam or I.C.)	PORT		STARBOARD
1 Cyls., Covers, Pistons & Rods			
2 Valves & Seats			
3 Connecting Rods, { Side Top Ends & Guides Centre			
4 Crankpins & Bearings { Side Centre			
5 Journals & Bearings			
MAIN ENGINE DRIVEN AIR COMPRESSORS			
6 Cyls., Covers, Pistons & Rods			
7 Connecting Rods & Top Ends			
8 Crankpins & Bearings			
9 Journals & Bearings			
10 Coolers & Safety Devices			
MAIN ENGINE DRIVEN SCAVENGE PUMPS			
11 Cyls., Covers, Pistons & Rods			
12 Connecting Rods & Top Ends			
13 Crankpins & Bearings			
14 Journals & Bearings			
15 Levers			
16 SCAVENGE BLOWERS			
17 SUPERCHARGERS			
MAIN TURBINES			
18 Casings, Rotors, Blading, Bearings & Thrusts			
19 EXHAUST STEAM TURBINES (WITH RECIP. ENGINES)			
20 STEAM COMPRESSORS			
21 CLUTCHES & HYDRAULIC COUPLINGS			
22 REDUCTION GEARING			
23 THRUST BLOCKS, SHAFTS & BEARINGS			
24 INTERMEDIATE SHAFTS & BEARINGS			
25 HOLDING DOWN BOLTS & CHOCKS			
26 CONDENSERS (MAIN & AUX.)			
27 STEAM RE-HEATERS			
28 DE-SUPERHEATERS			
29 STOP & MANOEUVRING VALVES			
30 MAIN ENGINE DRIVEN PUMPS			
31 CRANKCASE DOORS & EXPLOSION RELIEF DEVICES		Have Main Engines been tested working and manoeuvring? Yes	

OPINION ON MACHINERY AND RECOMMENDATIONS The machinery of this ship, so far as now seen, is eligible in my opinion to remain as classed.

Date of Committee

THURSDAY 3 DECEMBER 1959

Decision

As now

40in.4.57. T. (MADE AND PRINTED IN ENGLAND)

Noted
for
Header

© 2020



Engineer Surveyor to Lloyd's Register of Shipping

Foundation

002711-002716-0192

32 Essential Independent Pumps (Identify by position)

33 Bilge, Ballast & Oil Fuel Suction Lines, Fittings & Controls.....

34 Have the remaining Piping Arrangements & Fittings in the machinery space been examined as considered necessary?

35 Fresh Water Coolers..... 36 Lub. Oil Coolers..... 37 Heaters (state service).....

38 Independent Air Compressors, Coolers & Safety Devices.....

39 Air Receivers & Safety devices—Main..... 40 Auxiliary.....

41 Oil Fuel Tanks (Not forming part of hull structure).

42 Evaporators..... 43 Have Evaporator Safety Valves been tested under steam?

44 Steering Machinery..... 45 Windlass..... 46 Fire Extinguishing Arrangements.....

AUXILIARY ENGINES (Identify by position).....

PROPELLION	PORT	ELECTRICAL EQUIPMENT		AUXILIARY EQUIPMENT
		STARBOARD		
a Generators.....				i Generators & Governors.....
b Exciters.....				m Motors.....
c Air Coolers.....				n Switchboards & Fittings.....
d Motors.....				o Circuit Breakers.....
e Air Coolers.....				p Cables.....
f Control Gear, Cables, etc.....				q Insulation Resistance.....
g Insulation Resistance.....				r Steering Gear Generators and Motors.....
h Insulating Oil Test.....				s Navigation Light Indicators.....
i Overspeed Governors.....				
j Magnetic Couplings.....				
k Air Gap.....				

BOILERS OPENED UP & EXAMINED (Identify by position and state latest date of internal examination of each boiler)

MAIN AUXILIARY, DONKEY or PRESS

Superheaters

Safety Valves

Mountings, Doors & Fastenings

Safety Valves Adjusted to { Sat.....
Spt.....

Boiler Securing Arrangements

Main Economisers

Exhaust Gas Heated Economisers

Steam Heated Steam Generators

Steam Generator Safety Valves Adjusted to

Were Oil Burning System & Remote Controls examined working in accordance with Rules?

Forced Circulating Pumps

Have Saturated Steam Pipes in cylindrical boiler smoke boxes been examined as required by Rules?

Funnel

EXAMINATION & TESTING OF STEAM PIPES (State material)

Main

Auxiliary (over 3 in. bore)

Were Copper Pipes annealed?

Have Saturated Pipes in cylindrical boiler smoke boxes been tested?

PARTICULARS OF DEFECTS & REPAIRS, ETC. (Damage repairs should be detailed separate from wear and tear repairs; state what action has been taken regarding items which are subjects of class)

The ship was on passage in the Malacca Straits from Europe to the Far East on the 10th October when the main engine was stopped due to a knocking sound from the M.P. piston. On examination one M.P. piston ring was found broken and a new spare ring was fitted from stock.

The main engine was restarted and due to continued knocking the M.P. top exhaust valve chest was opened out and the C.I. valve found broken and removed.

The ship proceeded at slow speed to Singapore to carry out repairs and arrived on the 11th October 1959. A permanent repair was effected by supplying and fitting a new M.P. cast iron top exhaust valve.

Opportunity was taken to open up and examine the M.P. bottom exhaust valve and the L.P. slide valve which were found in good condition.

Repairs were completed on the 16th October 1959 and the ship continued on the voyage to the Far East.

It is submitted that this vessel is eligible to remain
as CLASSED.
27.10.59.



LEAVE THIS SPACE BLANK

Leave this space blank to be filled in with
details of survey or inspection by the surveyor

Damage fee ...

Expenses... ...

\$ 20

Date when A/c rendered.

26th October, 1959.

© 2020

Lloyd's Register
Foundation