

REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS,

(Received at London Office

13 JUL 1954

Date of writing Report 8.7. 19 54 When handed in at Local Office 19 54 Port of Helsingfors
No in Reg. Book. Survey held at Åbo Date. First Survey 13.3. Last Survey 15.6. 19 54.
(No. of Visits 8)

~~28659~~ on the Machinery of the ~~Woodstock~~ Steel s/s "SUSANNE"

		Year.		Month.		
Tonnage	Gross	5000 4012	Vessel built at	Sunderland	By whom J.L.Thompson & Sons, Ltd.	When 1924-12
	Net	2112 2293	Engines made at	"	By whom Richardsons, Westgarth & Co. Ltd	When

Nominal Horse Power	345	Boilers, when made (Main)	(Donkey)
No. of Main Boilers	2	Owners	W. Rostedt
		Managers	-
		Owners' Address	Åbo
			(if not already recorded in Appendix to Register Book.)
		Port	Voyage

Donkey Boilers ————— If Surveyed Afloat or in Dry Dock in floating dock
Pressure ————— 180 lb. (State name of Dock.) Grichton-Vulcan
Boilers —————
Particulars of Classification (which must be inserted
precisely as in Register Book & Supplements).

key Boilers	CHARACTER.	Machinery and Boiler
	✱ for Special Survey.	Surveys
	Date of last Survey, and of	(including any R. & R. if any)

Report No.	Port	Periodical Surveys.	(including date of A.B.S. if any)
Particulars of Examination and Repairs (if any) BS, TS and oil fuel installation		+100 A 1	+IMC 7.51

Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and is of any letters respecting this case.

Damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

a damage report made by anyone else? If so, by whom?	TS 5,51
	CL

the Surveyor personally go inside each Main Boiler separately and make a through examination at this time? yes Donkey boiler not
Donkey D.B. now removed to be used.

It, state for what reasons.....What parts of the Boilers could not be thus thoroughly examined?

Special means, in the absence of internal examination, were adopted by the
 voyer to assure himself of the thorough efficiency of those parts of each Boiler?

Latest date of internal examination of each boiler SS-Boiler 8.6.54, ps-Boiler 8.6.54 Present condition of funnel(s) satisfactory

The Surveyor examined the Safety Valves of the Main Boilers? yes To what pressure were they afterwards adjusted under steam? 180 lb

Examine the Safety Valves of the Donkey Boilers? To what pressure were they afterwards adjusted under steam?

never examine all the manholes, doors and their fastenings of the Main Boilers? Yes....., and of the Donkey Boilers?

Surveyor examine the drain plugs of the Main Boilers? **Yes**, and of the Donkey Boilers?

Surveyor examine all the mountings of the Main Boilers? , and of the Donkey Boilers?

Examined? **yes** Has it a continuous liner? **yes** Is an approved oil retaining appliance fitted at the after end? **no**

If so, state reasons..... Has the shaft now fitted been previously used?..... Has it a continuous liner?
, at the after end?..... State date of examination of Screw Shaft..... **9.6.54**
 State the wear down in the

electric light and/or power fitted?.....If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses?.....

generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? no

Complete.

Survey is not complete, state what arrangements were made. Donkey Boiler no. 1 removed. Both Main Boilers inspected inside, outside and all their parts. Boiler one staybolt renewed and the main steam valve provided with

In the ss-Boiler one staybolt renewed and the main steam valve provided with
 buntings opened. In the ss-Boiler 4 staybolts renewed and 8 rivets cap-welded in the ss-combustion

new seat. In the combustion chamber one anchor stay nut repacked, main steam valve provided ham in the center combustion chamber. The boiler was found satisfactory. Safety valves adjusted under

with new seat. In other respects the Boilers were found satisfactory. Safety valves adjusted under
weathering and oil fuel shut off tried. (The matters according Special Reason List

No. 133 have thus been dealt with). - Tailshaft drawn and inspected. Lignum vitae in bottom half of bearing installation including pipelines inspected. After finished

of sterntube renewed. - The oil burning installation including pipelines inspected. After finished trial run was effected with all the machinery to full satisfaction.

work trial run was cancelled

1. Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and what alterations have been made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, BS 0.11, B&MS 0.11, & LMC 0.11 or

also any alteration required to be made
 *LMC 140 lb., ED, &c.)
 CS 3371 and boilers are eligible in my opinion to remain as classed with fresh record of

BS 6.54 and of TS 6.54.

25 0.01 and 1

Bank. 50,000:- Fee applied for 54

Survey Fee (per Section 20).....
 Repair Fee (if any).....
 Received by me.....

Special Damage or Repair (per Section 29.) £ 19

Selling expenses (if chargeable) £

Engineer Surveyor to Lloyd's Register of Shipping.

TUESDAY 10 AUG 1954

Committee's Minute

Subject

Assigned _____ As now, ~~without spec. instruction~~

002743-002749-0123

