

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 5th Dec. 1957 When handed in at Local Office WRECK SECTION No. 114873
 No. in Reg. Book 55055 Survey held at South Shields Date, First Survey 29th Nov., Last Survey 3rd Dec. 1957.
 on the Wood & Iron Steel S.S. "CAMBERWELL" (No. of Visits 2)

TONNAGE: — Built at Newcastle By whom Tyne I.S.B. Co. Ltd. When 1924 4 MONTH.
 GROSS 1577 Owners South Eastern Gas Board. Owners' Address (if not already recorded in Appendix to Register Book)
 UNDER DEK 906 Managers A.G. Gostelow. Port belonging to LONDON
 NET 906

Surveyed Afloat or in Dry Dock? Both Name of Dock J. Readhead & Sons Destined Voyage

Cell DBor DBa feet: uE&B feet: f feet
 total capacity tons. FPT tons: APT tons: MT feet tons.

only alterations in the existing records of tanks should be inserted.

N.B.—All alterations in the existing records should be underlined.

Last Report, No. 114068 Port Nwe

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the Survey should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form State also the dates and initials of any letters respecting this case

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Machinery and Boiler Surveys (Including date of N.B., if any).
<u>+ 100 A.1.</u>	<u>+ L.M.C. 11.56</u>
<u>S.S. Shl. 11.56</u>	<u>B.S. 11.56</u>
<u>(Dr) 7.48</u>	<u>C.L. 11.56 N.</u>
<u>D.S. 1.57</u>	<u>Stm. Pipes 11.56</u>

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined. Yes

Society's Freeboard (if assigned) as 2 ft. 4 1/2 ins.
 painted on Ship and now verified

Owners Superintendent not required.

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE FOR

ANNUAL.

NOW DONE:—

Ship placed in dry dock, shell plating, sternframe and rudder cleaned and examined. Ship undocked 3rd December, 1957.

EXAMINED:—

Weather decks, hatchways with their closing and securing appliances, ventilators and other deck openings, casings and superstructure bulkheads with their closing appliances, windlass, general equipment, main and auxiliary steering arrangements.

All parts surveyed found or placed in good condition.

(Continued on page 2.....)

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors.	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed ...								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place ..								

PRESENT CONDITION OF THE

Decks <u>Good</u>	Bulkheads <u>Good</u>	Engine Room Skylights <u>Good</u>	Copper, or Y.M. <u>(State if on Felt)</u>
Planking of Decks <u>Good</u>	Ceiling <u>Good</u>	Coal Bunkers, Openings, Covers, &c. <u>Good</u>	When fitted, Month <u></u> Year <u></u>
Amings <u>Good</u>	Cement or Asphalt <u>Good</u>	Oil Bunkers <u>Good</u>	Boats <u>Not Exd.</u>
Stems & Fastenings <u>Good</u>	Rudder <u>Good</u>	Scuppers <u>Good</u>	Masts, Yards, &c. <u>Good</u>
Side Plating <u>Good</u>	Steering gear and its connections <u>Good</u>	Cargo Hatchways <u>Good</u>	Condition, how ascertained <u>From deck.</u>
" " in way of sidelights <u>Good</u>	Windlass <u>Good</u>	Hatches <u>Good</u>	Equipment letter <u>P</u>
Mes. <u>Good</u>	Have pumps been examined and found efficient? <u>Yes</u>	Planking <u>Good</u>	Anchors, No. of <u>3B. 1S.</u>
Reverse Frames <u>Good</u>	Have Sluice Valves been examined and found efficient? <u>Yes</u>	Caulking <u>Good</u>	Cables (State if now ranged) <u>Stated complete.</u>
Longitudinals <u>Good</u>	Have Watertight Doors been examined and found efficient? <u>Yes</u>	Treenails <u>Good</u>	" length <u>mean diam.</u>
Transverses <u>Good</u>	Have Ventilators and their Coamings been examined and found efficient? <u>Yes</u>	Breasthooks & Stemson <u>Good</u>	" Rule length <u>size</u>
Floors <u>Good</u>	Air and Sounding Pipes <u>At deck Good</u>	Transoms, Pointers & Crutches <u>Good</u>	Chain Locker <u>Good</u>
Keelsons <u>Good</u>	Doubling Plates under Sounding Pipes <u>Good</u>	Timbers of Frame at openings <u>Good</u>	Hawseers & Warps <u>Sufficient</u>
Stringers <u>Good</u>		" " at other places <u>Good</u>	Standing and Running Rigging <u>Efficient</u>
Inner Bottom Plating <u>Good</u>		Stringers, Clamps & Shelves <u>Good</u>	Sails <u>Good</u>
Have the Tanks been examined internally? <u>No</u>		Salting <u>Good</u>	
Have the Tanks been tested? <u>No</u>		State if examined	

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1.38," or "to remain as classed and to have record of survey, 1.38, and the notations of ss No. 1.38."

This ship so far as now surveyed is eligible in my opinion to remain as classed with record of docking 12.57.

Survey Fee (per Section 23) <u>£</u>	Fees applied for, <u>19</u>
Special Damage or Repair Fee (if any) (per Section 23) <u>£</u>	Received by me, <u>19</u>
Travelling Expenses (if chargeable) <u>£</u>	
Second Surveyor's Fee (if any) <u>£</u>	

Committee's Minute

THURSDAY - 9 JAN 1958

Character Assigned

DS 12.57

HBS 12.57

Surveyor to Lloyd's Register of Shipping.
A.I.L. PAGAN, F. SOUTHERN.



Lloyd's Register
 Foundation

002816 - 002824 - 0042

REPAIRS WEAR & TEAR:
Shell:- No.2 keel plate from forward found grooved in way of riveted butt to No.1 keel plate. Test hole drilled in grooving and thickness gauged (.41") grooving built up with welding.

REPAIRS WEAR & TEAR:-

Shell:- No.2 keel plate from forward found grooved in way of riveted butt to No.1 keel plate. Test hole drilled in grooving and thickness gauged (.41") grooving built up with welding.

Side shell plate D.4 (S.S.) (from fwd) grooved at butt to D.3 built up with welding; the test hole thickness, gauged in way of grooving, being considered satisfactory (.35").

A number of scrubbed and started rivets in upper bilge seam renewed.

One outdent in side shell plate E.5 (from aft) faired in place.

Lifted and all steel bushes renewed.

Lifted and all steel bushes renewed.
Riser of lower sternframe gudgeon machined off and carrier checked to ensure that
it was taking the rudder weight.

Steering Chains etc - Chain annealed, several shackles renewed.

Lower gudgeon fairing plate renewed.

Sternframe:- Found honeycombed at bottom of rudder post and corners of solepiece wasted. Sternframe chipped clean and built up with welding to original contour.

Bow Spirketting Plate:- Starboard side renewed.

Issued, copy attached and a copy placed on board.

Issued, copy attached and a copy placed on board.

J. I. Pagan.

When Anchors or Cables are supplied, the particulars are to be reported in the following form:—

ANCHORS.														Where and when tested and Superintendent.		
Number of Certificate.	Anchors.*	WEIGHT EX. STOCK.			WEIGHT OF STOCK.			TEST PER CERTIFICATE.				WEIGHT REQUIRED BY RULE.			Description of Anchor.	Makers.
		Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.	Tons	Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.		
	1st Bower															
	2nd "															
	3rd "															
	Collective Weight															
	Stream															
	Kedge															

If Patent state name of Patentee

If Stockless, state Mechanical Tests.

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

[illegible]

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN

is Ce
"W
lersto
ccura
for an
he So
rt. B.