

REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office

Date of writing Report May 1st 19 58 When handed in at Local Office. 19 58 Port of MONTREAL
No in Reg. Book. Survey held at Kingston Date. First Survey 15-10-57 Last Survey 18-11-19-57
06552 on the Machinery of the Woodburner Steel S/S "CITY OF KINGSTON" (No. of Visits TWO)

Tonnage	Gross	1690	Vessel built at	Quebec	By whom	Davie S.B. Rpg. Co.	When	1926 - 4
	Net	1013	Engines made at	Hartlepool	By whom	Richardsons, Westgarth	When	
MN As Per Rule		-	Boilers, when made (Main)		1926	(Donkey)	-	
No. of Main Boilers	2 SB		Owners	Canada Steamship Lines Ltd.	Owners' Address		-	
HS	" " "	-			(if not already recorded in Appendix to Register Book.)			
No. of Donkey Boilers	-		Managers	-	Port	Montreal	Voyage	-
Steam Pressure—			If Surveyed Afloat or in Dry Dock	Afloat				
in Main Boilers	185 lb.		(State name of Dock.)					
in Donkey Boilers	-							
						Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).		

Last Report No. 11978 Port MTL

Particulars of Examination and Repairs (if any).....Pt. BS & Pt. M.

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides, being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.....)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.....

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

" " Donkey "

If not, state for what reasons _____ What parts of the Boilers could not be thus thoroughly examined?

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler.....15-10-57.....Present condition of funnel(s).....Good

Did the Surveyor examine the Safety Valves of the Main Boilers?.....Yes.....To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of the Donkey Boilers? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? Yes and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers? and of the Donkey Boilers?

Did the Surveyor examine all the mountings of the Main Boilers? Yes , and of the Donkey Boilers?

Has the screw shaft now been drawn and examined?..... Has it a continuous liner?..... Is an approved oil retaining appliance fitted at the after end?

Has shaft now been changed?.....If so, state reasons.....Has the shaft now fitted been previously used?.....Has it a continuous liner?.....

Is an approved oil retaining appliance fitted at the after end? State date of examination of Screw Shaft State the wear down in the

stern bush Is electric light and/or power fitted? If so, did the Surveyor examine the generators, motors, switchgear cables and fuses?

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

Engine parts, when referred to by numbers, should be counted from forward. Auxiliary machinery should be referred to by position in Machinery Space.

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done.

BOILER SURVEY:- Both boilers examined internally and externally together with principal mountings and manholes and all found satisfactory.

TO COMPLETE THE SURVEY the safety valves remain to be adjusted under steam.

NOTE This vessel is laid up pending a decision whether she will be commissioned this season.

PART MACHINERY SURVEY:- The following items opened up, examined and found or placed in good condition:-
All crankshaft journals and main bearings.

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, etc.)

This vessel's machinery, so far as now seen, is eligible in my opinion to remain as classed with fresh record of MBS 12,57 when the survey is complete.

Survey Fee (per Section 23)..... \$ 85.00 Fees applied for,
Special Damage or Repair Fee (if any)..... \$: MAY 2¹⁹ 1958
(per Section 23.)
Travelling expenses (if chargeable)..... \$ 20.00 Received by me,
19

Committee's Minute

Assigned Deferred to ES

Noted
for
Header

Engineer Surveyor to Lloyd's Register of Shipping.

002853-002857-0100

Lloyd's Register
Foundation

Insert Character of Ship and Machinery precisely as in the Register Book

Is a Certificate required? If so, to be sent to