

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office

-5 SEP 1934

Date of writing Report

When handed in at Local Office

Port of

No. in Survey held at

Date, First Survey

Last Survey

on the Machinery of the Wood, Iron or Steel

CITY OF DIEPPE

Gross 7863
Net 4906

Vessel built at

By whom

When

Nominal Horse Power 1088

Engines made at

By whom

When

No. of Main Boilers 453

Boilers, when made (Main)

(Donkey)

No. of Donkey Boilers

Owners

Owners' Address

(if not already recorded in Appendix to Register Book.)

Port

Voyage

Team Pressure in Main Boilers

Managers

Surveyed Afloat or in Dry Dock

(State name of Dock.)

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Report No.

Port

Particulars of Examination and Repairs (if any)

Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Did the Surveyor personally go inside each Donkey Boiler separately and make a thorough examination at this time?

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler

Did the Surveyor examine the Safety Valves of the Main Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers?

and of the Donkey Boiler?

Did the Surveyor examine all the mountings of the Main Boilers?

and of the Donkey Boiler?

Has screw shaft now been drawn and examined? Is it fitted with continuous liner?

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Has shaft now been changed? If so, state reasons

Has the shaft now fitted been previously used? Has it a continuous liner?

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

State date of examination of Screw Shaft

State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft

Engine parts, when referred to by numbers, should be counted from forward.

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done

Electrical Installation

Alterations:- New top bridge removed from junction boxes in lower bridge. Two 1.H.P. fans fitted in No. 1 lower deck, feeds for motors previously used have been installed. Wiring in new forecabin head renewed as necessary.

Vessel placed in dry dock, propeller, stern bush fastenings examined - now in good order. Stern bush re. wooded.

Tailshaft drawn in, examined - found satisfactory. A new propeller, mean pitch 17'7", with cast iron boss and 14 bronze blades satisfactorily fitted at this time. 18'6" dia.

At owners request examined all 4 main boilers internally & externally with their safety valves, doors and mountings and found in good order. Minor repairs effected.

Boilers & steam pipes examined under steam & safety valves adjusted as above.

General Observations, Opinion, and Recommendation:-

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9,11, E.&M.S. 9,11, or L.M.C. 9,11, 140 lb., F.D., &c.)

is eligible in our opinion to remain as classed with fresh records of Tailshaft last seen 8.34 and BS 8.34

Survey Fee (per Section 29)

£ 5 : - : -

Fees applied for

Special Damage or Repair Fee (if any)

£ :

Travelling expenses (if chargeable)

£ :

Received by me

Committee's Minute

Assigned

B.S. 8.34.

T.S. 8.34. C.K.

H.R. Howells

R.C. Clayton

Engineer Surveyor to Lloyd's Register of Shipping.

Lloyd's Register Foundation

002897-002906-0110

N.B.—If this Report is copied by copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

Noted

Ym
6.9.34

Alfred K. K.

22

6	
7	8
8	9
9	10
10	11
11	12
12	13
13	14
14	15
15	16
16	17
17	18
18	19
19	20
20	21
21	22
22	23
23	24
24	25
25	26
26	27
27	28
28	29
29	30
30	31
31	32
32	33
33	34
34	35
35	36
36	37
37	38
38	39
39	40
40	41
41	42
42	43
43	44
44	45
45	46
46	47
47	48
48	49
49	50
50	51
51	52
52	53
53	54
54	55
55	56
56	57
57	58
58	59
59	60
60	61
61	62
62	63
63	64
64	65
65	66
66	67
67	68
68	69
69	70
70	71
71	72
72	73
73	74
74	75
75	76
76	77
77	78
78	79
79	80
80	81
81	82
82	83
83	84
84	85
85	86
86	87
87	88
88	89
89	90
90	91
91	92
92	93
93	94
94	95
95	96
96	97
97	98
98	99
99	100

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2020

Lloyd's Register
Foundation