

Rpt. 9

Date of writing report 31/10/60  
Survey held at CALCUTTAWRECK  
SECTION  
No. 269  
Received London

No. of visits 2

Port CALCUTTA

First date 16/10/60

Last Date 17/10/60

No. 19812  
17 NOV 1960

## REPORT OF PERIODICAL SURVEYS &amp; REPAIRS OF MACHINERY

No. in R. B. 82862 S.S. Name M. V. "TAYBANK" Gross tons 5627 Date of build 1930 - 8  
Owners Bank Line Ltd., Managers Andrew Weir & Co. Ltd., Port of Registry BELFAST.  
Engines made Sld. By Workman Clark (1938) Ltd., Type 2 oil engines 2 SA each 5 Cy.  
No. of Main Engines 2 No. of Screws 2  
No. of Main Boilers W. P.  
No. of Aux/Donkey Boilers db W. P. 120 lb  
Surveyed Afloat or in dry Dock AFLOAT  
Nature of Survey DAMAGE  
Was Damage Report issued? Int. Cert? YES  
Last Report (For Head Office only)

Records of Survey &amp; Special Notations as per Register Book

Hull	Machinery
+100 AL	+LMC
with freeboard	CS.3-57
1/60	d.7-59
(Dr) 12/52	CLP.4-58
ss. 3/57	s.2-57

DTs &amp; tanks between tunnels - vegetable oil.

The condition of any of the following items is to be described as "good" only when the part has been examined, found or placed in good condition, and is considered to be acceptable until the due date of the next Periodical Examination. Where it is considered that re-examination or repairs should be effected before the due date of the next Periodical Examination a distinguishing mark thus † should be inserted against the item and the circumstances and action recommended described fully under "defects and repairs". At part or complete Special Surveys those items which are not applicable to the ship should be cancelled with a black line; this need not be done when the machinery is on a continuous survey basis. When any part has been subjected to pressure test this should be stated. Engine parts when referred to by numbers should be counted from forward.

DOCKING Propellers ..... Wear Down of Stern Bushes ..... Oil Glands ..... Sea Connections .....  
Fastenings ..... Has Screwshaft/Tubeshaft been drawn? ..... Date of Examination ..... Has Shaft been changed? .....  
Has Shaft now fitted been previously used? ..... Has Shaft now examined/fitted a continuous liner? ..... Approved Oil gland  
MAIN ENGINES (Recip. Steam or I.C.) PORT STARBOARD  
1 Cyls., Covers, Pistons & Rods .....  
2 Valves & Gears .....  
3 Connecting Rods, { Side .....  
Top Ends & Guides { Centre .....  
4 Crankpins & { Side .....  
Bearings { Centre .....  
5 Journal & Bearings .....  
MAIN ENGINE DRIVEN AIR COMPRESSORS  
6 Cyls., Covers, Pistons & Rods .....  
7 Connecting Rods & Top Ends .....  
8 Crankpins & Bearings .....  
9 Journals & Bearings .....  
10 Coolers & Safety Devices .....  
MAIN ENGINE DRIVEN SCAVENGE PUMPS  
11 Cyls., Covers, Pistons & Rods .....  
12 Connecting Rods & Top Ends .....  
13 Crankpins & Bearings .....  
14 Journals & Bearings .....  
15 Levers .....  
16 SCAVENGE BLOWERS .....  
17 SUPERCHARGERS .....  
MAIN TURBINES  
18 Casings, Rotors, Blading, Bearings & Thrusts .....  
19 EXHAUST STEAM TURBINES (WITH RECIP. ENGINES) .....  
20 STEAM COMPRESSORS .....  
21 CLUTCHES & HYDRAULIC COUPLINGS .....  
22 REDUCTION GEARING .....  
23 THRUST BLOCKS, SHAFTS & BEARINGS .....  
24 INTERMEDIATE SHAFT & BEARINGS .....  
25 HOLDING DOWN BOLTS & CHOCKS .....  
26 CONDENSERS (MAIN & AUX.) .....  
27 STEAM RE-HEATERS .....  
28 DE-SUPERHEATERS .....  
29 STOP & MANŒUVRING VALVES .....  
30 MAIN ENGINE DRIVEN PUMPS .....  
31 CRANKCASE DOORS & EXPLOSION RELIEF DEVICES .....  
Have Main Engines been tested working and manœuvring? .....  
The machinery of this vessel so far as now seen is in  
good order and eligible to remain as classed without fresh record of survey subject to the  
port propeller and fastenings being examined at the next drydocking.

Date of Committee

Decision

THURSDAY 24 NOV 1960

As above, subject

Engineer Surveyor to Lloyd's Register of Shipping

A. McCOURT

Lloyd's Register  
Foundation

002916-002922-0200

32 Essential Independent Pumps (Identify by position)
33 Bilge, Ballast & Oil Fuel Suction Lines, Fittings & Controls
34 Have the remaining Piping Arrangements & Fittings in the machinery space been examined as considered necessary?
35 Fresh Water Coolers
36 Lub. Oil Coolers
37 Heaters (state service)
38 Independent Air Compressors, Coolers & Safety Devices
39 Air Receivers & Safety Devices—Main
40 Auxiliary
41 Oil Fuel Tanks (Not forming part of hull structure)
42 Evaporators
43 Have Evaporator Safety Valves been tested under steam?
44 Steering Machinery
45 Windlass
46 Fire Extinguishing Arrangements

AUXILIARY ENGINES (Identify by position)

PROPULSION	PORT	ELECTRICAL EQUIPMENT STARBOARD	AUXILIARY EQUIPMENT
a Generators			l Generators & Governors
b Exciters			
c Air Coolers			m Motors
d Motors			
e Air Coolers			n Switchboards & Fittings
f Control Gear, Cables, etc.			o Circuit Breakers
g Insulation Resistance			p Cables
h Insulating Oil Test			q Insulation Resistance
i Overspeed Governors			r Steering Gear Generators & Motors
j Magnetic Couplings			s Navigation Light Indicators
k Air Gap			

BOILERS OPENED UP & EXAMINED (Identify by position and state latest date of internal examination of each boiler)

MAIN AUXILIARY, DONKEY or PRESS

Superheaters

Safety Valves

Mountings, Doors & Fastenings

Safety Valves Adjusted to { Sat. Spt.

Boiler Securing Arrangements

Main Economisers Exhaust Gas Heated Economisers

Steam Heated Steam Generators Steam Generators safety Valves Adjusted to

Were Oil Burning System & Remote Controls Examined working in accordance with Rules? Forced Circulating Pumps

Have Saturated Steam Pipes in cylindrical boiler smoke boxes been examined as required by Rules? Funnel

EXAMINATION & TESTING OF STEAM PIPES (State material)

Main Auxiliary (over 3 in. bore)

Were Copper Pipes annealed? Have Saturated Pipes in cylindrical boiler smoke boxes been tested?

PARTICULARS OF DEFECTS & REPAIRS, ETC. (Damage repairs should be detailed separate from wear and tear repairs; state what action has been taken regarding items which are subjects of class)

Damage

Damage to port propeller stated sustained due to contact with lock wall when the vessel was leaving Kidderpore Dock on the 15th October 1960.

Ship examined afloat.

Now Done. 1st Propeller blade found turned over at tip for approximately 2'-0" on leading edge and about 1'-0" on trailing edge, distorted portion of blade cropped and dressed.

2nd Propeller blade turned back of trailing edge, for about 9" nothing done at this time.

3rd Propeller blade no damage found.

4th Propeller blade turned back on trailing edge over approximately 9"

An examination of the port propeller and fastenings were made by a diver and were reported satisfactory.

It is recommended that the propeller and fastenings should be again examined at the next drydocking, in the meantime considered satisfactory.

LEAVE THIS SPACE BLANK

Survey fees Damage Rs. 250/-

Sp: Attend: 16/10/60 Rs. 100/-

Damage fees ...

Expenses ... Rs. 20/-

Date when A/c rendered 31/10/60