

REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office 21 AUG 1957)

Date of writing Report 13. 8. 57 When handed in at Local Office 14. 8. 57 Port of GLASGOW

No in Reg. Book. Survey held at ARROSSAN Date. First Survey AND Last Survey 6th AUGUST 1957 (No. of Surveys ONE)21677 on the Machinery of the ~~Wood, Iron or Steel~~

SS. 'NARVA'

Tonnage { Gross 2044
Net 1088.

Vessel built at GÄVLE

By whom NYA A/B GÄVLE VARV & VERKS

When 1943

Nominal Horse Power

Engines made at HAMBURG

By whom CHRISTENSEN & MEYER

When 1943

No. of Main Boilers 25B.

Boilers, when made (Main) 1943

(Donkey)

No. of Donkey Boilers

Managers GLEN & CO. LD.

Owners' Address

(if not already recorded in Appendix to Register Book.)

Port GLASGOW

Voyage

Steam Pressure—
in Main Boilers 227 lbs (SPT)If Surveyed Afloat or in Dry Dock AFLOAT
(State name of Dock.)

in Donkey Boilers

Last Report No. 67085 Port GLS

Particulars of Examination and Repairs (if any) DAMAGE REPAIRS

Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a through examination at this time?

" " Donkey " " "

If not, state for what reasons.

What parts of the Boilers could not be thus thoroughly examined?

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler

Did the Surveyor examine the Safety Valves of the Main Boilers?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of the Donkey Boilers?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

, and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers?

, and of the Donkey Boilers?

Did the Surveyor examine all the mountings of the Main Boilers?

, and of the Donkey Boilers?

Has the screw shaft now been drawn and examined?

Has it a continuous liner?

Is an approved oil retaining appliance fitted at the after end?

Has shaft now been changed?

If so, state reasons.

Has the shaft now fitted been previously used?

Has it a continuous liner?

Is an approved oil retaining appliance fitted at the after end?

State date of examination of Screw Shaft

State the wear down in the

stern bush

Is electric light and/or power fitted?

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses?

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

Engine parts, when referred to by numbers, should be counted from forward. Auxiliary machinery should be referred to by position in Machinery Space.

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done. COMPLETE

Damage stated to have been caused on the 30th July 1957, when the vessel was on passage from Newcastle to Belfast; the Main Engines stopped and the vessel had to be towed into Arrossan.

Now done for damage repairs:— On opening up N°2 Engine unit, one of the junk ring set bolts was missing, on searching this engine, the bolt was found jammed in the top steam port, fouling the piston valve. A new valve spindle and guide bracket was fitted. All the junk ring set bolts were renewed and secured in position, also the eccentric rod was straightened, stress relieved and refitted. On completion, the engine was run ahead and astern and all found satisfactory. All the above repairs were carried out before the Surveyor was notified. The data concerning repairs was taken from the Chief Engineer's log book, and confirmed by the Repairs.

General Observations, Opinion, and Recommendation.— The machinery of this vessel so far as

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, BS 0.11, B&MS 0.11, & LMC 0.11 or

*LMC CS 3.34 140 lb., FD, &c.)

now seen to be in good order and eligible in my opinion to remain as classed without fresh record.

Survey Fee (per Section 29) £ : : Fees applied for

Special Damage or Repair Fee (if any) £ 3 3 0

(per Section 29.)

Travelling expenses (if chargeable) £ 0 7 0

Committee's Minute

Assigned

As now

Received by me,

19.

GLASGOW

20 AUG 1957

Engineer Surveyor to Lloyd's Register of Shipping.

Lloyd's Register Foundation

003385-003390-0232

noted

26 AUG 1957

010
330

Handwritten notes in Inuktitut syllabics, including the word "BETOM" (bottom) and "CONTINUED" (continued).

BETOM

131902

CONTINUED

000000

24 10300

1200 1000
200 200 200
14100 10000

000000 200000

100000

000000 100000

100000

000000 100000
000000 100000

000000 200000

100000

000000

100000

© 2020

Lloyd's Register
Foundation