

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office 11 DEC 1936)

Date of writing Report 7/12/36. When handed in at Local Office 7/12/36. Port of SPLIT

No. in Reg. Book. 89765 Survey held at SPLIT Date, First Survey 24th. Nov. Last Survey 30th. Nov. 1936. (No. of Visits 2)

on the Machinery of the ~~XXXXXX~~ Steel Sc. "PLAVNIK" ex "MATIGNON"

Tonnage (Gross 2711 Net 1649) Vessel built at Hamburg By whom Schiffsw (V.J. & Sch.) A.G. When 1922

Engines made at Hannover By whom Masch. A.G. When 1922

Boilers, when made (Main) (Donkey) Owners Brodar. Akcij. Drustvo "Oceania" Owners' Address (if not already recorded in Appendix to Register Book.) Port Susak Voyage

No. of Main Boilers 2 No. of Donkey Boilers 0 Managers If Surveyed Afloat or in Dry Dock Supaval afloat Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Report No. Port Commencement of Classen. Survey

Particulars of Examination and Repairs (if any) Trieste Surveyors.

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case. See London letter B.3/11/36 addressed

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

" " Donkey " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler 24/12/36 Present condition of funnel(s) Good

Did the Surveyor examine the Safety Valves of the Main Boiler? Yes To what pressure were they afterwards adjusted under steam? Not adjusted

Did the Surveyor examine the Safety Valves of Donkey Boiler? Yes To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? Yes, and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers? Yes, and of the Donkey Boiler?

Did the Surveyor examine all the mountings of the Main Boilers? No, and of the Donkey Boiler?

Has screw shaft now been drawn and examined? Is it fitted with continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Has shaft now been changed? If so, state reasons Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Has the shaft now fitted been previously used? Has it a continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

State date of examination of Screw Shaft State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft

Engine parts, when referred to by numbers, should be counted from forward. Is electric light and/or power fitted?

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done All the Rule requirements with

the exception of the following have to be complied with, and plans of the pumping arrangement and

shafting have to be submitted for consideration. It is stated that the survey will be advanced from

time to time until completed when the vessel calls at Trieste and Susak each voyage. Trieste Surveyors

advised.

NOW DONE:- Low pressure cylinder and piston examined and found in good condition. Boilers with

doors and fastenings examined and found in good condition, and scantlings verified and found in

accordance with approved plan. First Entry report herewith.

Mountings except SK to be examined