

Port Shimonoseki. No. 1521  
Writing Report 19-11-1959. When handed in at Local Office  
held at Shimonoseki, Japan No. of Visits 1 First Date and 19 11th Nov. 1959. Received London

## REPORT OF SHIP SURVEYS AND REPAIRS

The Surveyor's attention is drawn to the relevant requirements of Chapters B & C of the Rules.)

R.B. 7991 on the Iron or Steel SS. "KOHISTAN"  
at Shields, N. By Whom J. Readhead & Sons Ltd. Tons gross 6018  
Shahristan S.S. Co. Ltd. When 1930, Month 1  
F.C. Strick & Co. Ltd. Owners' address -  
(If not already in R.B.)  
Port of Registry London  
afloat Name of Dock --- Date of last examn. in Drydock ---

Any alterations in existing particulars in the Register Book should be reported and underlined.

Last Report: No. 1723 Port Bal  
to be filled in at Head Office.

Particulars of Classification (which must be inserted precisely as in Register Book and Supplement)

veys must be reported in the terms of the Rules. The nature and extent of Examinations and Repairs (if any) must be stated in detail, the parts examined and their condition being clearly indicated. For Annual, Special or other Condition Surveys the Summary of Examination and Condition on the back of the Report is to be carefully completed and applied if necessary in the body of the Report. Outstanding items to complete the Survey should be summarised at the end of the Report. The reasons for Repairs must be stated. Repairs on account of Damage (the alleged cause of which must be stated) should be separated from Repairs due to other causes, and, besides being detailed in the body of the Report, should be summarised in the form below. When, at a Special Survey, the Shell and Deck plating is drilled the results must be reported on Report 8(Dr). Whenever Anchors or Chain cables are replaced or retested the necessary particulars are to be given on Report 8(Eq) which is to be attached to this Report.

SHIP'S CLASS			Machinery	
Date of Special and of Drydocking Surveys, etc.				
<u>100A1</u>	<u>SS</u>	<u>1/56</u>	<u>LMC</u>	
<u>SS (Dr)</u>	<u>7/52</u>		<u>Engines</u>	<u>1/56</u>
	<u>1/56</u>		<u>Boilers</u>	<u>M 9/58</u>
<u>Docking</u>	<u>2/59</u>		<u>Tailshaft</u>	<u>CL 11/57</u>
			<u>Steampipes</u>	<u>1/56</u>

Give dates and references to any letters relating to this Report

In damage cases where the Surveyor has not made a special damage report he should state whether he offered his services for this purpose and to whom and why they were declined.

Freeboard as marked on ship and now verified - ft - ins

Was a damage report made by anyone else? If so, by whom? -

MINATION AND REPAIRS AS PER RULE FOR Repairs Wear & Tear.

At request of Master attended on board on account of reported leakage in No.5 Hold bilge Port side. Soundings taken & bilge subsequently examined after discharge of cargo and condition found satisfactory. It was observed that No.5 Hold bilge NRV was found in poor condition & leaking, now seat & lid refaced. Bilge observed over 6 hour interval, no pumping or cargo operations meantime and found no increase. Pumping arrangements generally examined & tested & found in order.

It was stated that the ship was proceeding via Inland Sea to Kure for breaking up & considered efficient meantime.

CONTINUATION OVER/OR SHEET 2

SUMMARY OF DAMAGE REPAIRS	Shell Plates	Frames	R. Frames	Floors and Bracket Floors	Inner Bottom Plates	Deck Plates	Beams	Other Items
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

Has a Survey also been held on machinery of the Ship? No

Is Classification Certificate required? If so, to be sent to No

If so, is the Report sent now, or when will it be sent? -

Has Interim Certificate been issued? Yes, (No. C-7812), copy attached.

GENERAL OBSERVATIONS, OPINION AND RECOMMENDATION AS TO CLASS

State clearly what alteration, if any, is suggested to be made in the existing Classification or Survey or other records of the Ship in the Register Book consequent upon this survey; for example:— "to remain as Classed in the Register Book without fresh record of Docking"; "to remain as Classed and to have record of drydocking 1,55"; or "to remain as Classed and to have record of drydocking 1,55, and the notation of S.S. . . . 1,55".

This ship so far as now seen is in good condition & eligible in my opinion to remain as now classed without fresh record of Survey, subject also as previously recommended.

K. Okada  
Surveyor to Lloyd's Register of Shipping  
K. Okada

THURSDAY 28 JAN 1960

Date of Committee

Minute

30m, 4, 57 T.

003487-003494-0194

© 2020

Lloyd's Register  
Foundation



TABLE 1

PARTS OF THE SHIP AS INDICATED BELOW HAVE BEEN EXAMINED FOR

SURVEY

Items	Now Examined YES NO or NONE	Tanks	Now Examined Internally	Now Tested
Shell plating, sternframe and rudder cleaned, examined and recoated in drydock		F.P. Tank		
Rudder lifted		A.P. „		
Weather Decks, Superstructures and Casings		D.B. Tanks (indicate Oil Fuel and Cofferdams		
Hatchways, Covers, closing and securing appliances				
Ventilator coamings, skylights, companionways and closing appliances		Fresh Water Tanks		
Holds		Deep Tanks		
'Tween Decks		Oil Fuel Bunkers and Settling Tanks		
Fore Peak Spaces		Side Tanks		
After „ „		Wing Tanks		
Engine Space		Other Tanks		
Boiler „		Cargo Tanks (Tankers)		
Under Engines and Boilers				
Tunnel and Well		Cofferdams		
Coal Bunkers		Pump Rooms		
Chain Locker				
Other Spaces				
		Have Tanks now Examined been Cleaned as Necessary?		
		Have Strums in Cargo Tanks (of Tankers) been removed?		
		Have Tanks been Retested as necessary after completion of any Repairs?		

Have the spaces now surveyed been cleared and cleaned as necessary?

Have the close ceiling and cargo battens, linings, pipe casings, etc., been removed and replaced as required by the Rules?

Have the bilges been cleaned out and examined?

Has cement in bottom been examined?

Has steelwork had rust removed and afterwards been recoated as necessary?

Were inspection plugs or any insulation removed in insulated spaces for examination of steelwork?

Has a Load Line Survey been held? If so, state which

Have the shell and deck plating been drilled as per Rule?

If so, Report 8(Dr) to be attached

Have any alterations to the approved scantlings and arrangements now been effected?

If so, report details in body of Report.

NOTE:—Indicate which compartments and/or tanks have been examined or tested by giving the identification numbers and inserting the word "Yes", e.g. Holds: Nos. 1, 2 & 3—Yes; or All—Yes.

TABLE 2

The present condition of the following parts in so far as examined is to be reported:—

Shell plating	Ceiling and Cargo Battens	Sluice Valves examined and found
„ „ in way of side scuttles	Cement or Asphalt	Air and Sounding Pipes
Rudder and Sternframe	Cargo and other Hatchways	Doubling Plates under Sounding Pipes
Decks	Hatches and closing appliances	Masts and Rigging examined and found
Superstructures and their closing appliances	Ventilators, their coamings and closing appliances	Condition, how ascertained (State if wedges removed)
Coamings and Casings	Companionways and Skylights	Chain Locker
Beams and Fastenings	Shell Openings	EQUIPMENT
Frames	Ash Shoots	Equipment Letter
Reverse Frames	Overboard Discharges and Scuppers	Anchors, No. of Condition
Longitudinals	Freeing ports	Cables (State if now ranged and examined)
Transverses	Steering Gear (Main and Auxiliary)	„ length mean diam. (on board)
Floors	examined and found	„ Rule Length Size
Keelsons	Windlass examined and found	Hawsers and Warps
Stringers	Pumps „ „ „	State if any Anchors or Chain Cable have
Inner Bottom Plating	W.T. Doors „ „ „	now been supplied or retested, if so,
Bulkheads and Tunnel		complete Report 8(Eq) and attach.

Have conditions (A) or endorsements (B) of Class (if any) been dealt with?

No

See Below

REMARKS, REPAIRS, Etc. (Contd.)

Survey Fee

Second Surveyor's Fee (if any)

Special Damage or Repair Fee (if any)

£10-0-0

Date when A/c. Rendered

Travelling Expenses (if chargeable)

-10-0

No rendered from London 2/12

© 2020

Lloyd's Register Foundation