

## REPORT of SURVEY for REPAIRS, &amp;c.

Date of writing Report 23/4 1936 When handed in at Local Office 23/4 1936 Port of Oslo  
 No. in Survey held at Oslo Date, First Survey 10/2 5 Last Survey 7/4 1936  
 Reg. Book. (No. of Visits 5)

37280 on the Wood, Iron or Steel screw steamer "BALI"

TONNAGE:—  
 GROSS 1428 Built at Newcastle By whom Swan Hunter & Wigham Richardson YEAR. MONTH. 1928 4  
 UNDER DK. 920 Owners A/S Ganger Rolf Owners' Address Oslo  
 NET 614 Managers Fred Olsen & Co Port belonging to Oslo  
 (if not already recorded in Appendix to Register Book).

Surveyed at or in Dry Dock Fl. dock. Name of Dock Akers mek. Verksted Destined Voyage Rotterdam Trade

WB=Cell DBor DBa feet; uE&B 75 feet; f 115 feet  
 total capacity 214 tons. FPT 17 tons; APT 12 tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 93273 Port Nwc

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER.	Years Assigned	How expired.	Machinery and Boiler surveys (including date of N.B., if any).
✗ for Special Survey Date of last Survey and of Periodical Surveys.			
<u>+100 A1</u>			<u>CL 12.35</u>
<u>with freeboard</u>			<u>BS 2.35</u>
<u>12.35</u>			<u>+LMC 2.33</u>
<u>ssNwc. No.1-33</u>			

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Society's Freeboard (if assigned) as painted on Ship and now verified } fl. 7 ins.

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Repairs.

This vessel was placed in floating dock. Examined bottom, stem, stern frame, rudder and fastenings. Generally examined the decks with bulwarks, ventilators, hatchways with covers and tarpaulins and means of securing same.

The following repairs were effected:-

Rudder lifted, 2 pintles renewed and all gudgeons re-bushed.

Peak tanks scaled and cementwashed, all bottom tanks cementwashed. Bottom cement 1" thick laid in all double bottom tanks. Space under boilers scraped and painted.

The forecastle railing repaired

Bridge after end bulkhead (E.R. casing after end) at centre made curved, making a passage forward of mast.

## SUMMARY OF DAMAGE REPAIRS:—

	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

## PRESENT CONDITION OF THE

Decks <u>Good</u>	State if Tanks have been examined inside <u>✓</u>	Air and Sounding Pipes <u>✓</u>	Copper, or Y.M. of Wood Vessels <u>✓</u>
Caulking of Decks <u>✓</u>	State if Tanks now tested <u>✓</u>	Dblng. Plates under Sounding Pipes <u>✓</u>	(State if on Felt). When put on, Month <u>✓</u> Year <u>✓</u>
Coamings <u>✓</u>	Bulkheads <u>Good</u>	Engine Room Skylights <u>✓</u>	Boats <u>✓</u>
Beams & Fastenings <u>Good</u>	Ceiling <u>Good</u>	Coal Bunkers, Open'gs, Lids, &c. <u>✓</u>	Masts, Yards, &c. <u>✓</u>
Outside Plating <u>Good</u>	Cement or Asphalt (State which.) <u>Good</u>	Oil Bunkers <u>✓</u>	Condition, how ascertained. (State if wedges removed) <u>✓</u>
" " in way of sidelights <u>✓</u>	Rudder <u>Good</u>	Scuppers <u>✓</u>	Sails <u>✓</u>
Breasthooks <u>✓</u>	Steering gear and its connections <u>✓</u>	Cargo Hatchways <u>✓</u>	Equipment letter <u>✓</u>
Transoms <u>Good</u>	Windlass <u>✓</u>	Hatches <u>✓</u>	Anchors, No. of <u>✓</u>
Frames <u>Good</u>	Have pumps now been examined and found efficient? <u>✓</u>	Plancking of Wood Vessels <u>✓</u>	Chain Locker <u>✓</u>
Reverse Frames <u>✓</u>	Have Sluice Valves now been examined and found efficient? <u>✓</u>	Caulking ditto <u>✓</u>	Cables (State if now ranged) <u>✓</u>
Longitudinals <u>✓</u>	Have Watertight Doors now been examined and found efficient? <u>✓</u>	Treenails ditto <u>✓</u>	" length (on board) mean diam. <u>✓</u>
Transverses <u>✓</u>	Have Ventilators and their Coamings been examined and found efficient? <u>✓</u>	Breasthooks & Stemson ditto <u>✓</u>	" Rule length size <u>✓</u>
Floors <u>✓</u>		Transoms Pointers, & Crutches ditto <u>✓</u>	Hawser & Warps <u>✓</u>
Keelsons <u>✓</u>		Timbers of Frame at openings ditto <u>✓</u>	Standing and Running Rigging <u>✓</u>
Stringers <u>✓</u>		Ditto Ditto at other places ditto <u>✓</u>	
Inner Bottom Plating <u>✓</u>		Stringers, Clamps & Shells ditto <u>✓</u>	
		Salting ditto <u>✓</u>	
		(State if examined.) <u>✓</u>	

## General Observations, Opinion as to Class, Recommendation, &amp;c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and pND24, &c."

It is recommended that this vessel be maintained in her present class in the Society's Register Book with fresh record of survey 4,36 and notation of S.S.No.2 when the survey is completed before the end of April 1937.

Survey Fee (per Section 20) Kr. 120.-

Special Damage or Repair Fee (if any) £

Travelling Expenses (if chargeable) £

Second Surveyor's Fee (if any) £

Committee's Minute TUE. 12 MAY 1936

Character Assigned note

Fees applied for,

23/4 1936

Received by me,

19

Surveyor to Lloyd's Register of Shipping.

TUE 23 FEB 1937

TUE 16 MAR 1937

FRI 23 APR 1937

TUE 25 MAY 1937

003495-003502-0116



New Registered dimensions:- 254.1 x 38.8 x 14.4.

## ANCHORS.

Number of Certificate.	Anchors.*	WEIGHT, EX. STOCK.			WEIGHT OF STOCK.			TEST PER CERTIFICATE.				WEIGHT REQUIRED BY RULE.			Description of Anchor.	Makers.	Where and when tested and Superintendent.
		Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.	Tons	Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.			
	1st Bower ...																
	2nd "																
	3rd "																
	Collective Weight.																
	Stream .....																
	Kedge .....																

\* If Patent state name of Patentee.

\* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

## CHAIN CABLES.

[illegible]