

# REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office

19 MAY 1958

MONTREAL

Date of writing Report April 21st 1958

When handed in at Local Office

19

Port of

No in Reg. Book. Survey held at Prescott, Ont.

Date. First Survey 12 - 12 - 57 Last Survey April 16th 1958

(No. of Visits THREE)

25178 on the Machinery of the ~~Woodschone~~ Steel S.S. "R. H. MARSHALL"

Tonnage { Gross 1926 Vessel built at Wallsend-on-Tyne By whom Swan, Hunter & Wgham. Rdhdsn. When 1929 Month 4  
 Net 1147 Engines made at Newcastle-on-Tyne By whom Swan, Hunter & Wgham. Rdhdsn. When 1929  
 Nominal 1147 Boilers, when made (Main) (Donkey)  
 Horse Power Owners Colonial Steamships Limited Owners' Address  
 (if not already recorded in Appendix to Register Book.)  
 No. of Main Boilers 2 SB Port Port Colborne Voyage  
 No. of Donkey Boilers Managers  
 Steam Pressure If Surveyed Afloat or in Dry Dock Afloat  
 in Main Boilers 180 lb. (State name of Dock.)  
 in Donkey Boilers 180 lb.

Last Report No. Port

Particulars of Examination and Repairs (if any) MBS &amp; Pt. M.

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a through examination at this time? Yes

" " Donkey " " "

If not, state for what reasons? What parts of the Boilers could not be thus thoroughly examined?

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler. Port 12th Dec. 1957 Stbd. 17th Dec. 1957 Present condition of funnel(s) Good

Did the Surveyor examine the Safety Valves of the Main Boilers? Yes To what pressure were they afterwards adjusted under steam? 180 lb.

Did the Surveyor examine the Safety Valves of the Donkey Boilers? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? Yes, and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers? Yes, and of the Donkey Boilers?

Did the Surveyor examine all the mountings of the Main Boilers? Yes, and of the Donkey Boilers?

Has the screw shaft now been drawn and examined? Has it a continuous liner? Is an approved oil retaining appliance fitted at the after end?

Has shaft now been changed? If so, state reasons Has the shaft now fitted been previously used? Has it a continuous liner?

Is an approved oil retaining appliance fitted at the after end? State date of examination of Screw Shaft State the wear down in the

stern bush Is electric light and/or power fitted? If so, did the Surveyor examine the generators, motors, switchgear cables and fuses?

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

Engine parts, when referred to by numbers, should be counted from forward. Auxiliary machinery should be referred to by position in Machinery Space.

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done

NOW DONE FOR BOILER SURVEY:- The Port and Starboard boilers examined internally and externally together with mountings and found or placed in good condition. The boilers afterwards examined under steam and the safety valves subsequently adjusted by a Canadian Government Steamship Inspector.

MACHINERY SURVEY:- The following opened up, examined and found or placed in good condition:-

All crankshaft journals and main bearings.

Steering engine.

Windlass.

WEAR AND TEAR REPAIRS:-

The lower two rows of plain tubes renewed, inboard combustion chamber, port boiler.

## General Observations, Opinion, and Recommendation:-

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, BS 9,11, B&MS 9,11, LMC 9,11 or LMC 110 lb., FD, &c.)

CS 3,34

The machinery of this vessel, so far as now seen, is eligible in my opinion to remain as classed with fresh record of MBS 2,58.

Survey Fee (per Section 23) MBS &amp; Pt. M. £ \$ 85.00

Special Damage or Repair Fee (if any) £ : : (per Section 23.)

Travelling expenses (if chargeable) £ \$ 30.00

Fees applied for

MAY 1 1958

Received by me, 19

Committee's Minute THURSDAY 22 MAY 1958

Assigned MBS 2,58



Engineer Surveyor to Lloyd's Register of Shipping.  
 (Wm. HEATLIE)



Lloyd's Register  
 Foundation

003556-00366 0155