

# REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office 13 JUN 1949)

of writing Report..... 19. When handed in at Local Office 18 MAY 1949 19. Port of NEWCASTLE-ON-TYNE

in Survey held at South Shields and Hebburn-on-Tyne. Date. First Survey 11.1.49. Last Survey 6.6.49. 1949  
Book. (No. of Visits 20.....)6 on the Machinery of the ~~W.L. Linn~~ Steel S.S. "ROY"

Gross 4871	Vessel built at Middlesbrough	By whom Smith Dock Co. Ltd.	Year. 1930	Month. 5
Net 2995	Engines made at Middlesbrough	By whom Smith Dock Co. Ltd.	When 1930	
Final Power 522 MN	Boilers, when made (Main) 1930	(Donkey)		
Main Boilers 3 SB.	Owners A/S D/S ASK.	Owners' Address	-	
Donkey Boilers (SPT)	Managers A. Kjerland	(if not already recorded in Appendix to Register Book.)	Port BERGEN	Voyage
Main Pressure 200 lb	If Surveyed Afloat or in Dry Dock afloat. South Shields, Tyne Dock			
Donkey Boilers	(State name of Dock.) Engg'd: R & W. Hawthorne Leslie & Co. Ltd. DRY.DK.			

Report No. Port

iculars of Examination and Repairs (if any) T.S. : B.S. O.F. CONVERSION.

Particulars of Classification (which must be inserted precisely as in Register Book &amp; Supplements).

CHARACTER. For Special Survey. Date of last Survey and of Periodical Surveys.	Years assigned now expired	Machinery and Boiler Surveys (including date of N.B., if any)
+ 100 ft.		+ LMC. 2, 47.
11.47		B.S. 4, 48.
SS. Mold. - 2. 47		C.L. 8, 46.

Cargo bottom not fitted.

Damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.

Damage report made by anyone else? If so, by whom?

Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

Donkey "

state for what reasons What parts of the Boilers could not be thus thoroughly examined?

special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Latest date of internal examination of each boiler 14-3-49

Present condition of funnel(s) Efficient

Surveyor examine the Safety Valves of the Main Boilers? Yes PORT &amp; CENTRE ONLY

To what pressure were they afterwards adjusted under steam? 200 lb./sq.in

Surveyor examine the Safety Valves of the Donkey Boilers? To what pressure were they afterwards adjusted under steam?

Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? Yes , and of the Donkey Boilers?

Surveyor examine the drain plugs of the Main Boilers? Yes , and of the Donkey Boilers?

Surveyor examine all the mountings of the Main Boilers? Yes , and of the Donkey Boilers?

Screw shaft now been drawn and examined? Yes Has it a continuous liner? Yes Is an approved oil retaining appliance fitted at the after end? No.

Screw shaft now been changed? Yes If so, state reasons See below. Has the shaft now fitted been previously used? Yes Has it a continuous liner? Yes

Approved oil retaining appliance fitted at the after end? No State date of examination of Screw Shaft 4-4-49 State the wear down in the

bush CLOSE FIT. Is electric light and/or power fitted? Yes If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses? No.

Insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? No.

Engine parts, when referred to by numbers, should be counted from forward.

Survey is not complete, state what arrangements have been made for its completion and what remains to be done. To complete the survey for  
5. of 5.49, the safety valves of the starboard boiler remain to be adjusted under  
steam. The Owners' Representative states that the safety valves will be adjusted on  
return of the vessel to the U.K. in a few weeks time.

Now Done

Vessel placed in dry dock, propeller stern bush and outside fastenings examined  
connections (inlets) opened out, examined and found or placed in good order.  
New shaft drawn, examined, taper badly wasted, 1/4" cut off end of liner and shaft found  
acked. Spare screw shaft marked: - 792 Lloyds No. 6508 D. D.D.W. 30.1.30.; fitted. Wood in  
bush bored out to suit. Wear down close.  
Propeller, cast steel, badly wasted at tips and on leading edge and wasted on inside bore of boss.  
One cast iron propeller fitted. (Cast steel propeller fitted March 1947 see Middlesbrough  
at No. 18242. The Owners' Representative states that a new spare propeller has been ordered  
will be placed on board as soon as it comes to hand. The cast steel propeller was not

General Observations, Opinion, and Recommendation:— The machinery of this vessel as now seen, (see continuation sheet)

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9,11, B&MS 9,11 or LMC 9,11 or 140 lb., FD, &c.)

CS 2,34,  
In efficient condition and eligible in our opinion to remain as classed with fresh records  
T.S. (C.L.) 4,49, now, B.S. 5,49 when the survey has been completed and notation "Fitted for  
Fuel 5.49. Flash Point above 150° F." now subject to spare propeller being supplied.

Fees (per Section 29). T.S. £3 : 0 : 0 Fees applied for 2-JUN-1949  
B.S. 13 0 0 19  
Damage or Repair Fee (if any) £5 : 5 : 0 Received by me,  
(per Section 29.) O.F. CONVERSION. 15 - 15 - 0  
Legal expenses (if chargeable) £ : : 19  
FRI. 1 JUL 1949

Committee's Minute

See B.R. 3244

ed

Lloyd's Register Foundation

00591-003548-01712

S. S. "Roy"

replaced on board as considered unfit for further use.

B.S.: Main boilers examined throughout with superheaters, mountings, manholes doors and fastenings and found all placed in safe working condition. The safety valves of the port and centre boilers adjusted under steam to pressure stated above.

Oil Fuel Conversion:- The vessel has been converted to oil fuel burning at this time in accordance with the Secretary's letters, approved Plans and Rule Requirements. The suction and pressure lines and heating coils hydraulically tested after adjoining as per Rule Requirements. The installation and deck control gear in connection with the O.F. and Steam Smoothering installations examined and tested under working conditions and all found satisfactory.

Particulars of the installation are as follows.

Whites Marine System Contract No. 1443.

O.F. Unit No. 16606 A+B. 2 Weir O.F. pressure pumps No. 217236-7.

O.F. Transfer Pump: Lamont No. 20375. Size 5" x 5" x 6" Lloyds test 400 lbs. 6.2.48.R.T.E.

Bilge Pump: " 20875 " " " 470 lbs. 20.2.48.R.

Whites Marine oily Water Separator No. 191.

Pneumercator system of sounding in Settling Tanks and side bunker oil fuel tanks.

Repairs:-

B.S. Starboard boiler: 9 c.c. stays renewed. 2 fractures in the port furnace cut out and welded.

Centre boiler: 31 defective c.c. stays renewed. End plate in way of internal feed pipe joints welded where wasted; defective drain plug renewed, forward collision chock part renewed.

Port boiler: 3 defective c.c. stays renewed, 2 fractures cut out in centre furnace and welded. Port furnace faired.

All boiler mountings overhauled. Defective valve spindles of port boiler main and aux. feed check valves and main feed check valve cover renewed. Main stop valve shut off clutch gear renewed. Starboard boiler safety valve springs renewed. Several other minor repairs effected.

6 evaporator coils renewed. Glasgow Certificate No. C. 71116 attached herewith.

Electrical Installation: At the instigation of the Owners an additional oil engine driven generator set for port use has been installed at this time.

Particulars as follows:- Pelapone Engine Ltd. Engine No. 529385. Generator Plant No. 529385. Campbell and Fisherwood Generator No. 42216. 12 KW. 110.V. 109 amps. Compound wound. 1000 R.P.M.

A new switch board complete with meters, pilot and earth lamps, double pole main switch and fuses has now been fitted for the above set. The main cables of this switch board connected to existing switch board in engine room by means of double pole change over switch.

The port and starboard tween deck accommodation rewired, stokehold lighting rewired, engine room lighting wiring part rewired. 2 additional deck lights fitted on boat deck. Ammeter on main switch board renewed. On completion of repairs, repair examined megger tested & found in order. New oil engine driven generator set examined tested under load and governing and found satisfactory.

D. Kelly.

SURVEYOR TO LLOYD'S REGISTER  
NEWCASTLE-ON-TYNE

© 2020

Lloyd's Register Foundation

S.S. "ROY"

Attached herewith:

O.F. Installation Newcastle Certificate Nos 26150 - 26838 - 27253

Evaporator coils Glasgow Certificate No 71116.  
12 K.W. Generator set. Pellephone Engines Ltd.

O.F. Installation: Plans

"Tank Pipe arrangement for oil burning." (2 sheets) DRG. N° 1431.

"Steam, Exhaust, & drain pipes for O.F. auxiliaries DRG. N° 1432.

"Tank pipe suction for oil burning". DRG. N° M/53

Dalef.

BURVEYOR TO LLOYD'S REGISTER,  
NEWCASTLE-ON-TYNE.



© 2020  
Lloyd's Register  
Foundation