

15

ived by Chief Engineer Surveyor.

Received from Chief Engineer Surveyor

SSEL'S NAME

Empire Grace

Rpt.

Bel
ges.

No. 13212

" 64727

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

(“The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.”—*Extract from Sub-Committee's Report, 24/5/92.*)

Type of Engine

Poil Engines 2 S.C.D.A.
12 Cy. 24 $\frac{7}{16}$ " - 55 $\frac{1}{8}$ "

~~If Boilers fitted with forced draught~~

Tail Shaft. If fitted with a continuous liner

If fitted with an outside gland of approved type

Several lengths of intermediate shafting were distorted by enemy action. These have been fairied machined & heat-treated. The small electric generator will be completed in vessels return. After the vessel's arrival at Pir, repairs were effected to the refrigerating cooling fan. This vessel's machinery appears to have been built in accordance with the

with the Rules and the approved plans, and it is submitted she is eligible to be classed *+ L MC 4 43*

2 DB 100 lb.

Subject to the 25 KW electric generator being tested and all the refrigerating cooling fan motors examined I certify on vessel's return from present voyage.

22/4/62

23/4/42

Lloyd's Register
Foundation

003816-003823-0052

If a wood vessel, what means are provided to prevent leakage of either fuel oil or of lubricating oil from saturating the woodwork

Wet Air Compressors

No. of stages

Diameters

Stroke

Driven by