

# REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office)

27 AUG 1947

Date of writing Report 24<sup>th</sup> JULY 1947 When handed in at Local Office 25<sup>th</sup> JULY 1947 Port of GLASGOW

No. in Survey held at PORT GLASGOW Date. First Survey 26<sup>th</sup> JUNE Last Survey 23<sup>rd</sup> JULY 1947 (No. of Visits 3)

eg. Book. ELECTRICAL INSTALLATION on the Machinery of the WOOD, IRON OR STEEL S.S. YEW FOREST (EX EMPIRE FENCIBLE - 46) Year. Month. 1945

Gross 1047 Vessel built at HERDEEN By whom J. LEWIS & SONS LTD When 1945

Net 567 Engines made at HERDEEN By whom J. LEWIS & SONS LTD When 1945

Nominal Horse Power 1945 (Donkey)

No. of Main Boilers 1 Owners J. STEWART & CO SHIPPING LTD Owners' Address GLASGOW Voyage GLASGOW

No. of Donkey Boilers 1 Managers J. STEWART & CO SHIPPING LTD

Team Pressure 1 If Surveyed Afloat or in Dry Dock ON SLIP - LAMONT'S CASTLE YARD

In Main Boilers 1 Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

In Donkey Boilers 1

Last Report No. 1 Port GLASGOW

Particulars of Examination and Repairs (if any)

CLASSIFICATION.

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.

as a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

" " Donkey " " " "

not, state for what reasons.

What parts of the Boilers could not be thus thoroughly examined?

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler.

Present condition of funnel(s).

Did the Surveyor examine the Safety Valves of the Main Boilers?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of the Donkey Boilers?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

, and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers?

, and of the Donkey Boilers?

Did the Surveyor examine all the mountings of the Main Boilers?

, and of the Donkey Boilers?

Has the screw shaft now been drawn and examined?

Has it a continuous liner?

Is an approved oil retaining appliance fitted at the after end?

Has shaft now been changed? If so, state reasons.

Has the shaft now fitted been previously used?

Has it a continuous liner?

Is an approved oil retaining appliance fitted at the after end?

State date of examination of Screw Shaft.

State the wear down in the

stern bush. Is electric light and/or power fitted? YES

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses? YES

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? YES

COMPLETE.

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done.

NOW DONE A Special Survey of the electrical installation carried out with a view to the vessel being classified by the Society. For full particulars see attached Report 13.

General Observations, Opinion, and Recommendation: The electrical installation of this vessel, as now seen,

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, BS 9,11, B&MS 9,11 & LMC 9,11 or & LMC 140 lb., FD, &c.)

is in good condition and is in accordance with the Society's Rules.

Survey Fee (per Section 29) ELECTRICAL £ 6 : 0 : 0

Special Damage or Repair Fee (if any) (per Section 29.) £ ✓

Travelling expenses (if chargeable) £ - : 12 : 6

Committee's Minute GLASGOW

Assigned See Machinery Rep 9

Fees applied for

25 AUG 1947

Received by me,

19

26 AUG 1947

J. M. Gardiner  
Engineer Surveyor to Lloyd's Register of Shipping.

© 2020  
Lloyd's Register  
Foundation  
003846-003857-0033