

REPORT OF SURVEY FOR REPAIRS, &c.

Writing Report 2/12/56 19... When handed in at Local Office 19... Port of LAS PALMAS, GRAND CANARY
 No. in Survey held at SANTA CRUZ DE TENERIFE Date, First Survey 28th Sep/56 Last Survey 28th November 1956.
 Reg. Book on the Wood, Iron or Steel M.V. 'BRUNA' (ex Bruna M-52) (No of Visits Three)

TONNAGE: — Built at Muggia By whom Cant. Nav. Martinzzi When 1947
 GROSS 146 Owners Societe Liberienne de Transports Owners' Address —
 UNDER DECK — Managers — Port belonging to Monrovia

Surveyed Afloat or in Dry Dock? Drydock Name of Dock Industrias Maritimas Destined Voyage —

DBorDBa — feet; uE&B — feet; f — feet }
 capacity — tons. FPT — tons; APT — tons; MT — feet — tons. }

only alterations in the existing records of tanks should be inserted.

N.B.—All alterations in the existing records should be underlined.

st Report, No. 13641 Port TRI

Radical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

Classn(S) RJH; - 10/10/56

Classn(H) LAL; 12/10/56-Fbd.HWM; 17/10/56-Admin/F. MB

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. For Special Survey. Date of last Survey and of Periodical Surveys.
 Machinery and Boiler Surveys (Including date of N.B., if any).
 Class Expunged
 non-compliance with
 Regulations 2/54.
 Society's Freeboard (if assigned) as painted on Ship and now verified 9 ft. 9.2" ins.

Was a damage report made by anyone else? if so, by whom?

PAIRS, OR EXAMINATION AS PER RULE FOR RECLASSIFICATION AND SPECIAL SURVEY.

Vessel was slipped on Industrias Maritimas Slipway Tenerife on 18th September 1956 and remained under repair and cleaning until 8th November 1956. Shellplating, sternframe and rudder were closely examined. Rudder lifted and new packing fitted at top of shank gland. Pintles found good. The hold, peaks, side tanks, deep tank, engine space, and accommodation were cleared and examined and found good. All bilges and limbers fore and aft were examined when cleaned, and engine plat forms lifted and examined below. All found or made good. All close ceiling was lifted and inner bottom plating thoroughly cleaned and painted bitumastic. The aft peak was tested under full head of oil. The forepeak and ballast deep tank under head of water acc. to Rules. Side tanks in Engine Room were tested full. All were found or made good. (Forepeak required 8' welding renewed, seen carried out satisfactory).

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors.	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed ...								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place ..								

PRESENT CONDITION OF THE	Bulkheads	Engine Room Skylights	Copper, or Y.M.
cks Good	Good	Good	(State if on Felt.)
ulling of Decks -	Ceiling "	Coal Bunkers, Openings, Covers, &c. -	When fitted, Month Year.
amings -	Cement or Asphalt. Cement	Oil Bunkers Good	Boat Good
ams & Fastenings -	Rudder Good	Scuppers Good	Masts, Yards, &c. Good
tside Plating -	Steering gear and its connections. Good	Cargo Hatchways Good	Condition, how ascertained. By rigger.
" " in way of sidelights -	Windlass Good	Hatches Good	(State if wedges removed.) home.
ames -	Have pumps been examined and found efficient? Yes	Planking	Equipment letter A
verse Frames -	Have Sluice Valves been examined and found efficient? -	Caulking	Anchors, No. of Two bow
ngitudinals -	Have Watertight Doors been examined and found efficient? Yes	Treenails	Cables (State if new ranged) Good ranged
ansverses -	Have Ventilators and their Coamings been examined and found efficient? Yes	Breasthooks & Stemson	" length 120 ✓ mean diamr. 11/16"
doors Good	Air and Sounding Pipes. Good	Transoms, Pointers & Crutches	" Rule length 120 ✓ size 11/16"
elsons "	Doubling Plates under Sounding Pipes. Good	Timbers of Frame at openings	Chain Locker Good
ingers "		" " at other places	Hawsers & Warps Good and suff.
er Bottom Plating		Stringers, Clamps & Shelves	Standing and Running Rigging Good
ve the Tanks been examined internally? Yes		Salting	Sails
ve the Tanks been tested? Yes		State if examined	

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Vessel was 'Class expunged due to non compliance with the Regulations'. It was also laid up by Spanish Government authority for 4 years, but has in my opinion now been put in good order and to the requirements of the Rules, and I Recommend vessel be Reclassed and reinstated in the Register Book with Character 100A- (West African & Spanish Coasting Service) and with the notation SS.

Fee (per Section 23) Ptas. 3.650.00 Fees applied for, 19
 Total Damage or Repair Fee (if any) £ : : Received by me, 19
 Selling Expenses (if chargeable) £ : :
 and Surveyor's Fee (if any) £ : :

Committee's Minute

Character Assigned

to L.A.P.

Re. N.Y.K. (SHE)

FRIDAY 14 DEC 1956

NON-EXCLUSIVE Surveyor to Lloyd's Register of Shipping.

J. STUART JOLLY

LAS PALMAS

Lloyd's Register of Shipping Foundation

...the ink paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

1

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN

Sa
 an
 Re
 rec
 the
 I
 O
 LV
 bin

Stockless, state Mechanical Tests.

bin

...the
...that
...in an
...error
...society."

B.) 7