

No. 19055

# REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office)

Date of writing Report. 25<sup>th</sup> July 1953 When handed in at Local Office. 10. Port of Amsterdamin Book. Survey held at Amsterdam Date. First Survey 1<sup>st</sup> July Last Survey 24<sup>th</sup> July 1953  
(No. of visits 14)

96 on the Machinery of the Wood, Iron or Steel T/S. M.V. "SKOTAA"

Gross 8190	Vessel built at Dundee	By whom Caledon S.B. & E Co Ltd	Year. 1931	Month. 4
Net 4894	Engines made at Got	By whom Gotaverken AB	When 1931	
Per Rule 6.53	Boilers, when made (Main) X	(Donkey) 1931		
Main Boilers X	Owners Ships AIS Janset	Owners' Address		
" " X	Managers Iver Bugge	Port Harwich	Voyage	
Donkey Boilers 2	If Surveyed Afloat in Dry Dock N.D.S.M.			
Pressure—	(State name of Dock.)			
Air Boilers X				
Donkey Boilers 150 lb				

Report No. Port

Details of Examination and Repairs (if any) DBS and part 175.

State Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and of any letters respecting this case.

In cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.

Damage report made by anyone else? If so, by whom?

Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Donkey " " " Yes

State for what reasons? What parts of the Boilers could not be thus thoroughly examined? Continuous Survey.

Special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? ✓

Last date of internal examination of each boiler 17/7/52 9/7/52 Present condition of funnel(s) good

Surveyor examine the Safety Valves of the Main Boilers? To what pressure were they afterwards adjusted under steam?

Surveyor examine the Safety Valves of the Donkey Boilers? Yes To what pressure were they afterwards adjusted under steam? 150 lb

Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? and of the Donkey Boilers? Yes

Surveyor examine the drain plugs of the Main Boilers? and of the Donkey Boilers? ✓

Surveyor examine all the mountings of the Main Boilers? and of the Donkey Boilers? Yes

Screw shaft now been drawn and examined? no Has it a continuous liner? ✓ Is an approved oil retaining appliance fitted at the after end? no

now been changed? ✓ If so, state reasons. ✓ Has the shaft now fitted been previously used? ✓ Has it a continuous liner? ✓

Approved oil retaining appliance fitted at the after end? ✓ State date of examination of Screw Shaft. ✓ State the wear down in the shaft. 2.5 mm

Push. Part. 1.8 mm Is electric light and/or power fitted? Yes If so, did the Surveyor examine the generators, motors, switchgear cables and fuses? ✓

Insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? ✓

Parts, when referred to by numbers, should be counted from forward. Auxiliary machinery should be referred to by position in Machinery Space.

Surveyor is not complete, state what arrangements have been made for its completion and what remains to be done.

Propellers and outside fastenings examined and found in order.

BOARD MAIN ENGINE:

Cylinders opened out and examined with cylinder covers, valves & valve gear, and pistons and piston pins & bushes and found or placed in good condition. Nos 1-2-4 cylinder liners worn renewed. N° 4 cyl. cover, showing a crack in way of exhaust valve, repaired by Metalloc, tested and found in order. Gudgeon pin of N° 1 piston renewed.

Left crankpin jayed; found readings satisfactory. All crankpins with bottom end 10, and N° 1-2-3-4-6-7-9 journals with main bearings examined and found in order.

Order of Main air compressor opened out, examined with piston and gudgeon pin & bush found or placed in order; gudgeon pin renewed. Crankpins of same examined and with bottom end bearing in order.

Please see Continuation sheet.

Observations, Opinion, and Recommendation:—

State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, etc.)

Machinery being in a good condition I am of opinion that same is eligible main as classed with fresh record of DBS. 7.53

A item "aux. condenser" to be suspended from S.R. list.


Fee (per Section 23) £. 3.00.— Fees applied for £. 20.8 19.53

Damage or Repair Fee (if any) £ : : Received by me,

(per Section 23) £. 1.19 19. Expenses (if chargeable)

tee's Minute TUESDAY 22 SEP 1953

As now, without spl. can DBS 7.53

  
Ophirhouse © 2020  
Engineer Surveyor to Lloyd's Register of Shipping

Insert Character of Ship and Machinery precisely as in the Register Book

0040555-004061-0102 1/2

Is a Certificate required? If so, to be sent to

Lloyd's Register Foundation

Machinery of the MV "SKOTAA5"PORT MAIN ENGINE:

All cylinders opened out and examined with cyl. covers, valves & valve gear, and pistons with guides pins & bushes and found or placed in good condition. N° 6 & 7 cylinder liners (being worn) renewed. N° 6 cylinder cover (showing a crack in way of exhaust valve) repaired by Metalock, hyd. tested & found in order. Guide pin of N° 6 & 7 pistons renewed.

Crankshafts clock payed; found readings satisfactory. All crankpins with bottom end bearings, and N° 1-4-5-7-8-9 journals with main bearings examined and found in order.

Cylinder of Main air compressor opened out, examined with piston and guide pin & bush and found or placed in order; guide pin renewed.

Crankpin of same examined and found with bottom end bearing in order.

Air coolers opened out and examined (H.P. air cooler coils annealed) hyd. tested, and found in good condition.

Port & Starboard intermediate shafts examined with their plummer blocks and found or made in order; aft plummer block of each re-metalled.

The following auxiliaries opened out, examined and found or made in order:

Steam driven Auxiliary air compressor (only compressor part examined incl.

air coolers hyd. tested) — Both main circulating pumps (centrif.- impeller shafts renewed) — Aft Feed pump (Simplex - steam cylinder bored out & piston renewed, crack in water end welded by special Cast Iron Welding Work & hyd. tested) — F.O. Transfer pump (Duplex - both steam cylinders bored out & pistons renewed and all piston rods renewed) —

both F.O. burning pumps (Simplex horizont.) — Steering engine (crankshafts renewed, vertical worm/pinion shaft skinned & bushes renewed).

NOTE: Aft. condenser circulating pump (steam driven centrif.) replaced by a Duplex pump (Mumford. 8" x 10" x 10") of larger capacity, this being a re-conditioned pump, supplied by the Owners. Same opened out, examined and found in good condition.

Outboard water box (being wasted) of auxiliary condenser replaced by a new one.

Both donkey boilers throughout examined and found in efficient condition.

Mountings & safety valves opened out, examined and found or made in order.

Boilers tried under steam and found with the F.O. burning plant and steam smothering arrangement in good working order; their safety valves were adjusted.

During trials of the machinery Starboard main thrust block ran hot; it was found that the inside cooling water coil was nearly broken at the inlet nipple, so that the oil was contaminated with water. Thrust block opened out and found Ahead face of thrusts left collar badly scored & pads molten out. Thrusts left placed on lathe, worn face machined, examined and found again in order. Spare pads fitted and existing pads re-metalled (new spare). Found thrust block bearings in order. Cooling water coil repaired.

Machinery again tried under working condition with satisfactory results.

004058-004061-102 2/2