

REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office)

Date of writing Report... 27/1/55 19... When handed in at Local Office... 28/1/55 19... Port of... VALENCIA **28 JAN 1955**
 in Book. Survey held at... Cartagena Date. First Survey... 22/12/54 Last Survey... 20/1/55 19
 (No. of Visits 19)

5174 on the Machinery of the ~~Woolston~~ Steel **MV "RIO DEVA"**

Age { Gross 7912 Vessel built at **Newcastle** By whom **Armstrong Whitworth & Co. (Shipbuilders)** When **1930** Month **11**
 Net 4971 Engines made at **Newcastle** By whom **Armstrong Whitworth & Co. (Engineers) Ltd.** When **1930**
 660 MN Boilers, when made (Main) - (Donkey) **1930**
 Owners **Naviera Estelar, S.A.** Owners' Address -
 (if not already recorded in Appendix to Register Book.)
 Managers **Fernando M. Pereda** Port **Panama** Voyage -
 If Surveyed Afloat or in Dry Dock **Both**
 (State name of Dock.) **Cartagena**

Donkey Boilers **150 lbs**
 t Report No. Port

Particulars of Examination and Repairs (if any) **Dkg. & Mch. repairs**

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides, detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

Damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.

Damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a through examination at this time?

" " Donkey " " " "

State for what reasons **Boilers under steam** What parts of the Boilers could not be thus thoroughly examined?

Special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Latest date of internal examination of each boiler Present condition of funnel(s) **Good**

Did the Surveyor examine the Safety Valves of the Main Boilers? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of the Donkey Boilers? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors, and their fastenings of the Main Boilers? and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers? and of the Donkey Boilers?

Did the Surveyor examine all the mountings of the Main Boilers? and of the Donkey Boilers?

Has screw shaft now been drawn and examined? **No** Has it a continuous liner? Is an approved oil retaining appliance fitted at the after end?

Has shaft now been changed? **No** If so, state reasons Has the shaft now fitted been previously used? Has it a continuous liner?

Is approved oil retaining appliance fitted at the after end? State date of examination of Screw Shaft State the wear down in the

in bush **3.3 mm.** Is electric light and/or power fitted? **Yes** If so, did the Surveyor examine the generators, motors, switchgear cables and fuses? **No**

Is insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? **Not tested**

Parts, when referred to by numbers, should be counted from forward. Auxiliary machinery should be referred to by position in Machinery Space.

Survey is not complete, state what arrangements have been made for its completion and what remains to be done. **To complete the C.S. please see form 7E.**

WORK DONE FOR DOCKING:

Vessel in dry dock -examined propeller, aft end of stern bush and outside fastenings of sea connections and all found in good order. Wear down of 3.3 mm.

WORK DONE FOR MACHINERY:

The Main Engine No 4 and 8 cylinder liners renewed and the No 7 piston renewed.

All Main Engine crankshaft bearings examined and numbers 1, 2, 3, 5, 6, 7, 8, 9 & 10 lower halves retalled. The top halves of No 4, 7 and 10 also retalled.

Deflection readings checked and found in order.

The lubricating system drained and cleaned.

The main compressor L.P. valve suction and delivery chest renewed.

Sea trials & sea trials were held following these repairs with satisfactory results.

It was then stated that the vessel would proceed direct to England for breaking up.

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, BS 9,11, B&MS 9,11, LMC 9,11 or 140 lb., FD, &c.)

The machinery of this vessel, so far as now surveyed, is eligible in opinion to remain as now classed with record of +LMC-CS (with date) when the survey has been completed.

Fee (per Section 23) **Mch. rep. Pts. 2.500'**
Sunday Fee Pts. 500' 27/1/55

Damage or Repair Fee (if any) £ : :
 (per Section 23.)

Expenses (if chargeable) **Pts. 1.750'**

Surveyor's Minute **FRIDAY 18 FEB 1955**

Received by me, **For E. Montalbo & self**

Engineer Surveyor to Lloyd's Register of Shipping.

0042 06-004212-0183