

23 JUL 1945

(Received at London Office.....)

No. 18667

REPORT OF SURVEY FOR REPAIRS, &c.

Reporting Report 2971 1945 When handed in at Local Office 2971 1945 Port of West Hartlepool

Survey held at Hartlepool Date, First Survey and Last Survey 12th July 1945

on the Wood, Iron or Steel S.S. "Halvard Bratt" (No. of Visits.....)

Age: 1030 Built at Elbing By whom F. Schichau When 1921

DK 852 Owners Augfarbygg Owners' Address

648 Managers A. Bratt & Co Port belonging to Gothenburg, Swedish

Afloat or in Dry Dock? afloat Name of Dock Victoria Destined Voyage

or DBa feet; uE & B feet; f feet

Capacity tons. FPT tons; APT tons; MT tons.

Only alterations in the existing records of tanks should be inserted.

All alterations in the existing records should be underlined.

Report, No. Port

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.

Examined L.R. 6-44 B.S. 6-44 (2004) 6.44 0.9.9-41

Machinery and Boiler Surveys (Including date of N.B., if any).

Society's Freeboard (if assigned) as painted on Ship and now verified

Was a damage report made by anyone else? if so, by whom?

S, OR EXAMINATION AS PER RULE, FOR General Examination (Continuation)

DONE:- Vessel examined afloat & partly loaded. General Examination made of upper part of holds, fore peak tank internally, machinery space, and structure under boilers, and found in good condition.

lower parts of holds, aft peak tank and coal bunkers remain to be examined to complete the General Examination.

is stated it is hoped to dry dock the vessel on return to N.E. Coast.

OF DAMAGE REPAIRS :-

Shell Plates. Frames. R. Frames. Floors and Bracket Floors. Beams. Inner Bottom Plates. Dk. Plates. Other Items :-

oved ...

oved and Fair'd or Repaired

ed or Repaired in place ...

CONDITION OF THE

Good Bulkheads Part Examined Good

Decks Ceiling

fastenings Cement or Asphalt

ing Rudder

in way of sidelights Steering gear and its connections

Part Examined Good Windlass

Have pumps been examined and found efficient?

Have Sluice Valves been examined and found efficient?

Have Watertight Doors been examined and found efficient?

Have Ventilators and their Coamings been examined and found efficient?

Air and Sounding Pipes

Doubling Plates under Sounding Pipes

Engine Room Skylights

Coal Bunkers, Openings, Covers, &c.

Oil Bunkers

Scuppers

Cargo Hatchways

Hatches

Planking

Caulking

Treenails

Breasthooks & Stemson