

REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office)

Date of writing Report

19

When handed in at Local Office

9/7/

19

Port of

NEWCASTLE-ON-TYNE

No. in Survey held at

Newcastle

Date. First Survey

7-7-43

Last Survey

7-7-1943

Reg. Book. 25368 on the Machinery of the

Wood, Iron or Steel

S/S Harvard Bratt

(No. of Visits)

Year. Month.

Tonnage { Gross 1030
Net 648

Vessel built at

Elbing

By whom

F. Schichau

When

1921

Nominal Horse Power

72

Engines made at

Elbing

By whom

F. Schichau

When

1921

No. of Main Boilers

2

Boilers, when made (Main)

1921

(Donkey)

✓

No. of Donkey Boilers

✓

Owners

Angfartigs A/B Adolf

Owners' Address

(if not already recorded in appendix to Register Book.)

Port

Voyage

Steam Pressure in Main Boilers

200

Managers

A. Bratt & Co

If Surveyed Afloat or in Dry Dock

(State name of Dock.)

Afloat

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER.
* for Special Survey
Date of last Survey and of
Periodical Surveys.Years
assigned
to class
expired.Machinery and Boiler
Surveys
(including date of N.B., if any).

Examined L.R. 5.43

B.S. 5.42 (200 lb)

5.43

OG 9.41

Last Report No.

Port

Particulars of Examination and Repairs (if any) Part B.S.

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Donkey

If this was not done, state for what reasons

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler

Present condition of funnel(s)

Efficient

Did the Surveyor examine the Safety Valves of the Main Boiler?

To what pressure were they afterwards adjusted under steam?

200 lb □"

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers?

and of the Donkey Boilers?

Did the Surveyor examine all the mountings of the Main Boilers?

and of the Donkey Boilers?

Has the screw shaft now been drawn and examined?

Is it fitted with continuous liner?

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Has shaft now been changed? If so, state reasons

Has the shaft now fitted been previously used? Has it a continuous liner?

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

State date of examination of Screw Shaft

State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft

Engine parts, when referred to by numbers, should be counted from forward.

Is electric light and/or power fitted

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses?

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done

Now done :- Safety valves of main boilers adjusted under steam to the above stated pressure

A letter, dated 1-7-43, from the Glasgow surveyors, stated that to complete the boiler survey, the safety valves of both boilers remain to be adjusted

General Observations, Opinion, and Recommendation:— The machinery of this vessel, as

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9.11, B.&M.S. 9.11, & L.M.C. 9.11, or

ELMC
CS 3.34,
140 lb., F.D., &c.)

far as now seen, is in efficient condition, and eligible in my opinion to remain as classed, with fresh record of survey B.S. with date as previously recommended.

Survey Fee (per Section 29)

£

Fees applied for

Special Damage or Repair Fee (if any)

£

Received by me,

Travelling expenses (if chargeable)

£

19

Committee's Minute

Assigned

FRI. 23 JUL 1943

TUES. 13 JUL 1944

B. Booker
Engineer Surveyor to Lloyd's Register of Shipping.Lloyd's Register
Foundation

Is a Certificate required? If so, to be sent to

004238-004248-0139

PS dec 5-43 fairly well 5:43,
now complete.

It is submitted that
this vessel is eligible for
THE RECORD, PS 5:43.

L.P.
21/2/43.



© 2020

Lloyd's Register
Foundation