

REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office

17 JUN 1948

Date of writing Report 6/6/48 19 When handed in at Local Office 19

Port of ALGIERS (N.A.)

No. in Survey held at ALGIERS(Quai Biarritz).

Date. First Survey 5/6/48

Last Survey 6/6/48

19

g. Book. Part

(No. of Visits 13 hours)

0377 on the Machinery of the Wood, Iron or Steel Motor Vessel "OAKMORE" (ex Empire Kent-47, ex Levante-45)

Year. Month.

Gross 4700 769 Vessel built at KATX Emden

By whom Nordseewerke Emden G.m.b.H.

When 1939

Net 2662 755 Engines made at Kiel

By whom Fr. Krupp Germaniawerft A.G.

When 1939

Nominal Horse Power Boilers, when made (Main)

(Donkey)

of Main Boilers Owners Johnston Warren Lines, Ltd.

Owners' Address

(If not already recorded in Appendix to Register Book.)

of Donkey Boilers Managers Furness Withy & Co. Ltd.

Port LIVERPOOL

Voyage United Kingdom

eam Pressure

n Main Boilers If Surveyed Afloat or in Dry Dock Afloat

(State name of Dock.)

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Years assigned How expired	Machinery and Boiler Surveys (including date of N.B., if any)
Examined LR2, 47		CL
8, 47		12, 45
Docking date 8, 47		
(Classification contemplated)		

st Report No. Port

rticulars of Examination and Repairs (if any) FRACTURED MAIN ENGINE PISTON.

Medical Surveys, when held, must be reported in detail and serialim in the terms of the Rules. State clearly the cause of Repairs, if any, d, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be ted) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly mmarised at the end of the report. State also the dates and initials of any letters respecting this case.

amage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

a damage report made by anyone else? If so, by whom?

the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

" " Donkey " " " "

ot, state for what reasons What parts of the Boilers could not be thus thoroughly examined?

at special means, in the absence of internal examination, were adopted by the rveyor to assure himself of the thorough efficiency of those parts of each Boiler?

e latest date of internal examination of each boiler

Present condition of funnel(s)

the Surveyor examine the Safety Valves of the Main Boilers?

To what pressure were they afterwards adjusted under steam?

the Surveyor examine the Safety Valves of the Donkey Boilers?

To what pressure were they afterwards adjusted under steam?

the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

, and of the Donkey Boilers?

the Surveyor examine the drain plugs of the Main Boilers?

, and of the Donkey Boilers?

the Surveyor examine all the mountings of the Main Boilers?

, and of the Donkey Boilers?

the screw shaft now been drawn and examined?

Has it a continuous liner?

Is an approved oil retaining appliance fitted at the after end?

shaft now been changed? If so, state reasons

Has the shaft now fitted been previously used?

Has it a continuous liner?

approved oil retaining appliance fitted at the after end?

State date of examination of Screw Shaft

State the wear down in the

vn bush Is electric light and/or power fitted?

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses?

the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

Engine parts, when referred to by numbers, should be counted from forward.

e Survey is not complete, state what arrangements have been made for its completion and what remains to be done Complete.

This vessel was visited at the request of CORY BROTHERS & CO. LTD, LLOYD'S AGENTS, ALGIERS and AGENCE MARITIME GERO SCANDINAVE, ALGIERS, Owners' Agents, on account of Fractured Main Engine Piston.

OW FOUND :-

RECOMMENDED & DONE :-

IN ENGINE. NO. 5. CYLINDER. (2 S.C.SA. Archauloff solid ection):-

Cylinder opened up. Defective Piston and broken parts removed. Liner carefully examined and lubricating points checked. Spare working Piston fitted and 2 piston rings renewed. Piston rod attachment, Cover and Valves examined and refitted. Piston cooling system checked. Exhaust manifold cleaned. Removals and re-placements of pipe lines, connections, covers and fittings.

iston head fractured circumferentially through the top ton groove and separated from the remainder of the ton. One Piston ring broken. Bottom edge of aft venging port slightly marked. Cylinder liner, Cover Valves in good condition.

After completion of the foregoing Permanent repairs, Main Engines tried under working conditions, during dock trial, with satisfactory results. Copy of Rpt. 10, issued 6/6/48, attached.

Survey confined to the above.

eral Observations, Opinion, and Recommendation:-

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, BS 9, 11, B&S 9, 11, LMC 9, 11 or LMC 140 lb., FD, &c.) CS 2, 34,

This vessel's Machinery, so far as now seen, is in efficient condition. Vessel certified Seaworthy and sidered fit to proceed on her contemplated voyages.

y Fee (per Section 29)

Fees applied for

l Damage or Repair Fee (if any) £ Fcs. 10; 886.

Received by me,

ing expenses (if chargeable) £ Fcs. : 680.

19

(To be collected in Algiers).

WED. 20 OCT 1948

nittee's Minute

ned See Lon. 117/122

Engineer Surveyor to Lloyd's Register of Shipping.



Lloyd's Register Foundation

004466-004476-0350

3/6