

(Received at London Office

19 SEP 1952

Port of **26 SEP 1952**

5049 on the Machinery of the ~~XXXXXXX~~ S.Sc. Steam Trawler "ST. CELESTIN"

Last Report No.

Port

Particulars of Examination and Repairs (if any)..... DAMAGE

On damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined Yes - not required

Was a damage report made by anyone else? If so, by whom?.....Underwriters' Surveyor

Did the Surveyor personally go inside each Main Boiler separately and make a through examination at this time?.....

" " Donkey "

not, state for what reasons.....What parts of the Boilers could not be thus thoroughly examined?

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler.....Present condition of funnel(s)

Did the Surveyor examine the Safety Valves of the Main Boilers? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of the Donkey Boilers?..... To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?, and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers?, and of the Donkey Boilers?

Did the Surveyor examine all the mountings of the Main Boilers?, and of the Donkey Boilers?

as the screw shaft now been drawn and examined?.....Has it a continuous liner?.....Is an approved oil retaining appliance fitted at the after end?

Has shaft now been changed? If so, state reasons Has the shaft now fitted been previously used? Has it a continuous liner?

an approved oil retaining appliance fitted at the after end?.....State date of examination of Screw Shaft.....State the wear down in the

stern bush.....Is electric light and/or power fitted?.....If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses?

as the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

Engine parts, when referred to by numbers, should be counted from forward. Auxiliary machinery should be referred to by position in Machinery Space.

the Survey is not complete, state what arrangements have been made for its completion and what remains to be done.....**COMPLETE**

OW DONE FOR DAMAGE: due to grounding in River Humber, whilst on trial on 14th August, 1952.
Propeller, principal sea connections and outside fastenings examined and found
in good condition.

Screwshaft drawn and examined and found in good condition.

Main circulating pump opened up, impeller shaft found scored and renewed with bushes.

Ballast pump opened up and found in order.

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, BS 9,11, B&MS 9,11, ~~SLMC~~ 9,11 or ~~SLMC~~ 140 lb., FD, &c.)

The machinery of this vessel is eligible in my opinion to remain as now classed (Class contemplated)

Survey Fee (<i>per Section 29</i>).....	£	:	:	<div style="display: inline-block; vertical-align: middle;"> Fees applied for <div style="border: 1px solid black; padding: 2px; display: inline-block;"> 24 SEP 19... </div> </div> <div style="display: inline-block; vertical-align: middle; margin-left: 10px;"> Received by me, 19... </div>
Special Damage or Repairs Fee (if any)	£	3	3	
(<i>per Section 29.</i>)				
Travelling expenses (if chargeable)	£	:	:	

Committee's Minute

Signed See F.E. Welch, rpt. Hnd 58680

F. U. Mackinnon
Engineer Surveyor to Lloyd's Register of Shipping.

© 2020
Lloyd's Reg
Foundation

004918-004926-0050