



Steam Trawler "SLETNES" (ex "P.V.6111")

(Continued)

Selected lengths of main steam pipes, engine stop valve, removed, examined and hydraulically tested to Rule requirements.

ELECTRICAL: See report attached herewith:

Repairs due to Wear and Tear: HP, MP and LP piston rods skimmed, metallic gland packing renewed.

Screw shaft skimmed; stern tube bored and lined with white metal.

Bilge pump buckets (2) renewed. Donkey feed pump water end liners bored and new buckets fitted.

Boiler superheater elements and headers reconditioned (Certificate attached).

Main and auxiliary feed check valves and blow-down valve renewed. (Valves hydraulically tested to Rule requirements.)

On completion of repairs the main and auxiliary machinery tried under working conditions and found satisfactory.

NOTE: A stand-by turbine lubricating oil pump (Weirs No.226078. 4 1/2" x 5" x 12") now fitted on board, and is in addition to the original rotary oil pump.

*N.P. Watson*



© 2020

Lloyd's Register Foundation