

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report.....19..... When handed in at Local Office.....19..... Port of Copenhagen
 No. in Survey held at Copenhagen Date, First Survey 7th May Last Survey 12th May 1949
 Reg. Book. 73680 on the Wood, Iron or Steel S.S. ST ELWYN (No. of Visits.....)

TONNAGE:— Built at Sunderland By whom Sir J. Laing & Sons Ltd When 1940
 GROSS 5200 Owners Shakespeare Shipping Co Ltd Owners' Address.....
 UNDER DK. 4563 Managers South American Steam Line Ltd (If not already recorded in Appendix to Register Book).
 NET 2984 Port belonging to Newport, Mon.

Surveyed Afloat or in Dry Dock? afloat Name of Dock Frihavn Destined Voyage.....
 Cell DBor DBa.....feet; uE & B.....feet; f.....feet
 total capacity.....tons. FPT.....tons; APT.....tons; MT.....feet.....tons.

Only alterations in the existing records of tanks should be inserted.

N.B.—All alterations in the existing records should be underlined.

Last Report, No..... Port.....

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.....

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)	
CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Machinery and Boiler Surveys (Including date of N.B., if any).
100A1	
with freeboard	
(Classification contemplated)	
	Ritted Peril fuel
Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.	

Was a damage report made by anyone else? if so, by whom?.....

REPAIRS, OR EXAMINATION AS PER RULE, FOR General examination for class and advancement of special survey commenced 6.48., and freeboard renewal survey in accordance with Letter to Copenhagen dated 2nd May 1949.
Vessel examined afloat. Examined decks, casing, hatchways, peaks, tween decks, machinery spaces, tunnel, structure under boilers, masts, rigging, hatch covers, tarpaulins, supports & fastenings, ventilator coamings & covers, steering engine, windlass, watertight doors and general equipment and found satisfactory.
Freeboard renewal survey effected - Renewal report form and verification of marking forwarded to London 18.5.49.
Due to the presence of cargo in the holds it was not possible to

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE								
Decks	good	Bulkheads	good	Engine Room Skylights	good	Copper, or Y.M.		
Caulking of Decks	"	Ceiling	-	Coal Bunkers, Openings, Covers, &c.	-	(State if on Felt.)		
Coamings	good	Cement or Asphalt	-	Oil Bunkers	good	When fitted, Month		Year
Beams & Fastenings	"	Rudder	not seen	Scuppers	good	Boats	good	
Outside Plating	good above WL	Steering gear and its connections	good	Cargo Hatchways	good	Masts, Yards, &c.	good	
" " in way of sidelights	"	Windlass	good	Hatches	good	Condition, how ascertained	from deck	
Frames	good	Have pumps been examined and found efficient?	-	Planking	-	(State if wedges removed.)		
Reverse Frames	-	Have Sluice Valves been examined and found efficient?	-	Caulking	-	Equipment letter	-	
Longitudinals	-	Have Watertight Doors been examined and found efficient?	yes.	Treenails	-	Anchors, No. of	3 - 1.	
Transverses	-	Have Ventilators and their Coamings been examined and found efficient?	yes.	Breasthooks & Stemson	-	Cables (State if now ranged)	no.	
Floors	not seen	Air and Sounding Pipes	good	Transoms, Pointers & Crutches	-	" length 225 mean diamr. 2 1/2 in.		
Keelsons	-	Doubling Plates under Sounding Pipes	-	Timbers of Frame at openings	-	" Rule length 270 size		
Stringers	-			" " at other places	-	Chain Locker	not seen	
Inner Bottom Plating	not seen			Stringers, Clamps & Shelves	-	Hawsers & Warps	stated sufficient	
Have the Tanks been examined internally?	No.			Salting	-	Standing and Running Rigging	efficient	
Have the Tanks been tested?	No.			State if examined.		Sails	-	

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1.38," or "to remain as classed and to have record of survey, 1.38, and the notations of as No. 1.38."


The vessel is, in my opinion, eligible to be classed 100A1 with freeboard with the notation S.S. 6.48 subject to the cross bunker and port and starboard settling tanks being tested to Rule requirements and to the holds being internally examined and found satisfactory.

Survey Fee (per Section 29)	£ Kr : 200-00	Fees applied for,	
Light & Sound signals	£ 10 : 360-00	19/5	1949
Special Damage or Repair Fee (If any)		Received by me,	
(per Sec. 29)		19	
Travelling Expenses (If chargeable)	£ : 40-00		
Second Surveyor's Fee (If any)	£ : :		

FRI. 21 OCT 1949

Committee's Minute.....
 Character Assigned.....

Surveyor to Lloyd's Register of Shipping.



Lloyd's Register Foundation

examine the holds or double bottom tanks.

The Antwerp surveyors were advised of the position (See Copenhagen letter to Antwerp dated 12.5.49 - Copy to London) with a view to the S.S. notation being amended to 5.49.

For advancement of S.S. commenced 6.48 by B.C. surveys. -

Oil fuel cross bunker P & S and starboard aft settling tank internally examined and found satisfactory.

At the request of the owners superintendent a survey was held on the boats, life saving equipment, lights and sound signals and all found or put in a satisfactory condition. Interim certificate issued - Copy attached.

The vessel holds two seaworthy certificates issued by the B.C. surveyors:-

31.10.46 Damage stated to be caused by contact with the quay wall at London Docks. Starboard side shell slightly indented abreast nos 2 & 3 holds.

18-2-49. Damage stated to have been caused by contact with dock wall at Buenos Ayres. Slight indent Port and Starboard sides in the second strake below the sheerstrake between frames 149 & 150.

Both these damages have now been examined and it is considered that they do not affect the seaworthiness of the vessel, and come within Category B, and the

When Anchors or Cables are supplied, the particulars are to be reported in the following form :—

ANCHORS.

Number of Certificate.	Anchors.*	WEIGHT, EX. STOCK.			WEIGHT OF STOCK.			TEST PER CERTIFICATE.				WEIGHT REQUIRED BY RULE.			Description of Anchor.	Makers.	Where and when tested and Superintendent.
		Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.	Tons	Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.			
	1st Bower																
	2nd "																
	3rd "																
	Collective Weight																
	Stream.....																
	Kedge																

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

CHAIN CABLES.

[illegible]

repairs can therefore be left to the Owners convenience.

A first entry report on this vessel will be prepared and forwarded in due course.