

REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office)

Date of writing Report..... 8 - 5 - 47..... When handed in at Local Office..... 19..... Port of..... Hamburg.....
No. in Survey held at..... Lubeck..... Date. First Survey 28 - 1 - 47 Last Survey 7 - 5 - 47 19.....
Reg. Book. 68658 on the Machinery of the ~~Weser~~ Steel " Anna Rehder " (No. of Visits..... 5.....)

Tonnage { Gross 725 Vessel built at Linhamm By whom Linhamms Skepps. A/B When 1921 Month 10
Net 377 Engines made at Sunderland By whom N.E. Marine Co., Ltd. When 1924
Nominal - Boilers, when made (Main) 1921 (Donkey) -
Horse Power - Owners ~~Creek Maritime Commission~~ Owners' Address -
No. of Main Boilers 48 Managers - (If not already recorded in Appendix to Register Book.)
No. of Donkey Boilers 4 Port - Voyage -
Steam Pressure 180 lbs in Main Boilers
in Donkey Boilers 400 lbs
If Surveyed Afloat or in Dry Dock Bath, Flenderwerke Dry Dock. Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
Last Report No. 7 OKgs Port

Particulars of Examination and Repairs (if any) Docking, Examined L.R. TS, BS.

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.....

Damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined -

As a damage report made by anyone else? If so, by whom? -

Did the Surveyor personally go inside Main Boiler separately and make a thorough examination at this time? Yes

" " Donkey " " Yes

not, state for what reasons -

What parts of the Boilers could not be thus thoroughly examined? -

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? -

Latest date of internal examination of each boiler Main, 6 - 2 - 47, Donkey, 23 - 4 - 47

Present condition of funnel/s Satisfactory

Did the Surveyor examine the Safety Valves of the Main Boilers? Yes

To what pressure were they afterwards adjusted under steam? 180 lbs/sq. in.

Did the Surveyor examine the Safety Valves of the Donkey Boilers? Yes

To what pressure were they afterwards adjusted under steam? 12.7 Kgs/sq. cm.

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? Yes

and of the Donkey Boilers? Yes 100 lbs/sq. in.

Did the Surveyor examine the drain plugs of the Main Boilers? -

and of the Donkey Boilers? - 7 Kgs/sq. cm.

Did the Surveyor examine all the mountings of the Main Boilers? Yes

and of the Donkey Boilers? Yes

Has the screw shaft now been drawn and examined? Yes

Has it a continuous liner? No

Is an approved oil retaining appliance fitted at the after end? Yes

Has the shaft now been changed? No

If so, state reasons -

Has the shaft now fitted been previously used? -

Has it a continuous liner? -

Is an approved oil retaining appliance fitted at the after end? -

State date of examination of Screw Shaft 6 - 2 - 47

State the wear down in the

Is electric light and/or power fitted? Yes

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses? Yes

Is the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? Yes

Engine parts, when referred to by numbers, should be counted from forward.

Survey is not complete, state what arrangements have been made for its completion and what remains to be done. To complete the Survey for Notation

Examined L.R. 5,47, renewal of screw shaft is recommended by the end of August 1947, (six months limit)

Note:- Docking, Vessel placed in drydock, propeller, stern bush, sea connections and their fastenings examined.

Screw shaft drawn in and examined (found badly worn) skimmed up to a diameter of 234 mm, (Rule size 236.5 mm) bottom of shaft at top end radiused and stern bush remetalled; considered efficient for a period of six months.

Examined L.R.:- It is stated by Chief Engineer that systematic overhauling of machinery has been carried out and machinery is in good condition. Germanischer Lloyd Classification certificates record no restrictions on class that have been dealt with.

Main and auxiliary machinery now examined externally, parts as under opened up and examined and on completion examined working conditions and pumping arrangements tried with satisfactory results.

Engine cylinders, pistons, slide valves, thrust shaft and bearings, engine driven pumps, stand by circulating pump, electrical installation (lighting) generally examined, megger tested and tested under working conditions.

Main and Donkey boilers examined internally and externally together with their principle mountings and the safety valves tested under steam to 180 lbs/sq. in. and 100 lbs/sq. in. (12.7 Kgs/sq. cm. per Germanischer Lloyd Certificate and sq. cm. per boiler inspection book.)

Observed that main boiler water gauge pipes are not fitted with terminal cocks at boiler shell.

Note:- A small number of fractured combustion chamber stays in main boiler renewed, main and auxiliary feed valve seats renewed.

Repairs and adjustments effected.

Observations, Opinion, and Recommendation:- The machinery of this vessel is eligible in our opinion to

be clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, BS 9,11, B&MS 9,11 or LMC 9,11 or LMC 140 lb., FD, &c.) CS 2,34,

Re the Notation of Examined L.R. 5,47 for a period of 12 months, BS, 2,47, when the Survey is completed (as stated

) and subject to Main boiler water gauge pipes being fitted with cocks at shell at the first opportunity.

(per Section 29)..... B.S. £ 14: 0: 0 Fees applied for
& T.S. 4 0 0 19
Damage or Repair Fee (if any) £ 10: 10: 0
(per Section 29.)
Expenses (if chargeable) £ : :
Received by me,
A. J. P. 1947
London

See's Minute
Note subject

WED. 3 SEP 1947

BS 2,47 (LR)

See Rpt. 8

S. 2,47

MBS 180 lb.

DAS 100 lb.

L.P. cyl. diam. 4 3/4"

005280-005292-0183



Lloyd's Register
Foundation