

PORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

No. 116627

of writing Report 2 JUN 1948 When handed in at Local Office 2 JUN 1948 (Received at London Office 7 JUN 1948)

Survey held at Tilbury Date. First Survey and Last Survey 14-5-1948
on the Machinery of the Wood Iron or Steel "TRESUS" (No. of Visits 1)

Gross 10669 Vessel built at Portland By whom Kaiser Co. Inc. Year. Month.
Net 6317 Engines made at Lynn, Mass By whom General Electric When 1944
Main Boilers 2WTB (S.M.) Boilers, when made (Main) (Donkey) When 1944
Donkey Boilers Owners Anglo-Saxon Petroleum Co. Ltd Owners' Address
Pressure Managers (If not already recorded in Appendix to Register Book.)
Main Boilers 500 Port London Voyage
Donkey Boilers If Surveyed Afloat or in Dry Dock Dry Dock Tilbury (State name of Dock.)

Report No. Port Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

ulars of Examination and Repairs (if any) Docking.
l Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs. If any detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated at the end of the report. State also the dates and initials of any letters respecting this case.
ge cases where the Surveyor has not made a special damage report he is required to state whether he offered his
ices for this purpose, and why they were declined
amage report made by anyone else? If so, by whom?
urveyor personally go inside each Main Boiler separately and make a thorough examination at this time?
Donkey "

ate for what reasons What parts of the Boilers could not be thus thoroughly examined?
acial means, in the absence of internal examination, were adopted by the
or to assure himself of the thorough efficiency of those parts of each Boiler?
st date of internal examination of each boiler
urveyor examine the Safety Valves of the Main Boilers?
urveyor examine the Safety Valves of the Donkey Boilers?
urveyor examine all the manholes, doors and their fastenings of the Main Boilers?
urveyor examine the drain plugs of the Main Boilers?
urveyor examine all the mountings of the Main Boilers?
rew shaft now been drawn and examined? No Has it a continuous liner? Is an approved oil retaining appliance fitted at the after end?
now been changed? If so, state reasons Has the shaft now fitted been previously used? Has it a continuous liner?
oven oil retaining appliance fitted at the after end? State date of examination of Screw Shaft State the wear down in the
in Good fit Is electric light and/or power fitted? If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses?
ulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?
ey is not complete, state what arrangements have been made for its completion and what remains to be done.

Done:- Vessel placed in dry dock; propeller, aft end of stern hull and all outside sea fastenings examined. Main injection valve opened up and examined; some wastage in the chest was cleaned, specially examined, considered efficient and coated with asphor.
No opportunity at this time to advance classification survey.

Observations, Opinion, and Recommendation: The machinery of this vessel, so far as now is in good condition and eligible in my opinion to retain the record
Classification contemplated.

(per Section 29) Fees applied for
Age or Repair Fee (if any) Received by me,
Expenses (if chargeable)
WED 23 JUN 1948
As now
Engineer Surveyor to Lloyd's Register of Shipping.
H. C. Mathiam