

## REPORT OF SURVEY FOR REPAIRS, &amp;c., OF ENGINES AND BOILERS

(Received at London Office

6 JUL 1950

Date of writing Report 14<sup>th</sup> JUNE 1950

When handed in at Local Office

D2

Port of SOUTHAMPTON

No. in Survey held at SOUTHAMPTON

Reg. Book.

Date. First Survey 19<sup>th</sup> DEC<sup>3</sup> Last Survey 24<sup>th</sup> APRIL 1950

(No. of Visits) 3

02260 on the Machinery of the ~~Wood, Iron~~ Steel S.S. "AUTOCARRIER"

Tonnage { Gross 985 Vessel built at GLASGOW By whom D & W HENDERSON & CO. LTD When 1931  
 Net 362 Engines made at GLASGOW By whom D & W HENDERSON & CO. LTD When 1931  
 Nominal 228 HP Boilers, when made (Main) 1931 (Donkey) -  
 Horse Power }  
 No. of Main Boilers 2 Owners BRITISH TRANSPORT CORPORATION Owners' Address -  
 No. of Donkey Boilers - Managers - (if not already recorded in Appendix to Register Book.)  
 Steam Pressure - Port LONDON Voyage -  
 in Main Boilers -  
 in Donkey Boilers -  
 Surveyed Afloat in Dry Dock N°1 Dry Dock.  
 (State name of Dock.)

Particulars of Classification (which must be inserted precisely as in Register Book &amp; Supplements).

Last Report No. Port

Particulars of Examination and Repairs (if any) COME LMC 1 B.S.

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined -

Was a damage report made by anyone else? If so, by whom? -

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? YES

" " Donkey " " "

If not, state for what reasons -

What parts of the Boilers could not be thus thoroughly examined? -

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Date latest date of internal examination of each boiler 19<sup>th</sup> JAN 1950

Present condition of funnel(s) GOOD.

Did the Surveyor examine the Safety Valves of the Main Boilers? YES

To what pressure were they afterwards adjusted under steam? 200 LBS<sup>2</sup>

Did the Surveyor examine the Safety Valves of the Donkey Boilers? -

To what pressure were they afterwards adjusted under steam? -

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? YES

and of the Donkey Boilers? -

Did the Surveyor examine the drain plugs of the Main Boilers? -

and of the Donkey Boilers? -

Did the Surveyor examine all the mountings of the Main Boilers? YES

and of the Donkey Boilers? -

Has the screw shaft now been drawn and examined? NO Has it a continuous liner? -

Is an approved oil retaining appliance fitted at the after end? -

Has the shaft now been changed? - If so, state reasons -

Has the shaft now fitted been previously used? -

Has it a continuous liner? -

Is an approved oil retaining appliance fitted at the after end? -

State date of examination of Screw Shaft -

State the wear down in the

Wear bush CLOSE FIT

Is electric light and/or power fitted? YES

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses? YES

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? YES

Engine parts, when referred to by numbers, should be counted from forward.

Is the Survey not complete, state what arrangements have been made for its completion and what remains to be done COMPLETE.

WORK DONE: Vessel placed in dry dock. Propellers, stern tube & outside fastenings examined. Wear down as above.

The following parts of machinery opened up & examined, found or altered in good order:-

Port & Starboard Main engine complete, thrust shafts, blocks, packs & bearings; intermediate shafting & bearings; air, circulating, & feed pumps; large & ballast pumps; fan engines; condensers (retested & tested); steering engine, windlass; pumping arrangements examined & tested. Electrical equipment examined & tested as required by the Rules & left in good order. Steam & emergency generator engine examined. Both boilers examined in their entirety together with Safety Valves & principal mountings, all found in good order. Boilers afterwards examined under steam & safety valves regulated to their stated pressure. A number of minor repairs effected.

General Observations, Opinion, and Recommendation:-

P.T.O.

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, BS 1,1, B&MS 1,1 or LMC 1,1 or LMC 140 lb., FD, &c.)

The machinery of this vessel, as far as now seen, is in good & safe working condition, & eligible in my opinion to be licensed with this survey & to have record of LMC 4, 50; and BS 1, 50

Survey Fee (per Section 23) LMC 40:0:0 BS 7:0:0

Fees applied for

Special Damage or Repair Fee (if any) £ : :

(per Section 23.)

Received by me,

Printing expenses (if chargeable) £ : :

19

Committee's Minute

Signed

LMC MS 4.50

Both S(N) 2.49; BS 1.50

Robert W. Strachan  
 Engineer Surveyor to Lloyd's Register of Shipping.

© 2020

Lloyd's Register Foundation

005367-005376-0170



On completion, main & auxiliary machinery examined under  
working conditions & left in good working order

*[Signature]*



© 2020

Lloyd's Register  
Foundation