

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report. 22. 5. 1948. When handed in at Local Office. 14. 6. 1948. Port of GRIMSBY.

No. in Survey held at IMMINGHAM. Date, First Survey 21. 4. 48. Last Survey 19. 5. 19 48

Reg. Book. 90445 on the ~~Woodstock~~ Steel S/S "BALTONIA" ex "Empire Gallop" ex "Fangturm" (No. of Visits 12)

19378 Built at Hamburg By whom Deutsche Werft A.G. When 1944

TONNAGE :- Gross 1944 Owners United Baltic Corporation, Ltd. Owners' Address -

UNDER DK. 1410 Managers - Port belonging to London.

NET 965

Surveyed Afloat or in Dry Dock? Both. Name of Dock King's Dock. Destined Voyage -

Ceil DBor DBa feet; uE & B feet; f feet

total capacity tons. FPT tons; APT tons; MT feet tons.

Only alterations in the existing records of tanks should be inserted.

N.B. - All alterations in the existing records should be underlined.

Last Report, No. Port

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER: * for Special Survey. Date of last Survey and of Periodical Surveys. Examined L.R. 3, 47.

Machinery and Boiler Surveys (Including date of M.B., if any). B.S. 10, 47

(225 lb.)

T 6.4.48 & 18.5.48. S 16.4.

48. 19.4.48 & 19.5.48.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he

offered his services for this purpose and to whom and why they were declined Yes. Owners

Superintendent. Not required. Was a damage report made by anyone else? if so, by whom? Underwriters' Surveyor.

REPAIRS, OR EXAMINATION AS PER RULE, FOR CLASSIFICATION, LOAD LINE RENEWAL, DAMAGE & S.R.L.

Classification.

NOW DONE:

Vessel placed in dry dock, shell plating, rudder, sternframe cleaned, examined,

placed in an efficient condition and recoated.

The holds, peaks, bunkers, machinery spaces, 'tween decks, and chain locker cleared,

wood ceiling lifted as required by the Rules, plating and framing examined, found in good

order and recoated as necessary.

Fore and after peaks and all double bottom tanks examined internally and

satisfactorily tested to Rule requirements.

(See overleaf)

SUMMARY OF DAMAGE REPAIRS :-

Shell Plates. Frames. R. Frames. Floors and Bracket Floors. Beams. Inner Bottom Plates. Dk. Plates. Other Items :- Bulwarks with top

Renewed ... rail angle stiffeners &

Removed and Faird or Repaired stanchions faird. Approx.

Faird or Repaired in place ... 2,000 rivets renewed, 1000

caulked. 500 ft. seams

caulked, 20ft. E.W.

PRESENT CONDITION OF THE

Decks Good. Bulkheads Good. Engine Room Skylights Good. Copper, or Y.M. -

Caulking of Decks. Ceiling. Coal Bunkers, Openings, Covers, &c. -

Coamings. Cement on ~~ASPHALT~~. Oil Bunkers. When fitted, Month - Year -

Beams & Fastenings. Rudder. Scuppers. Good. Boats Good.

Outside Plating. Steering gear and its connections. Cargo Hatchways. Masts, Yards, &c. -

In way of sidelights Good. Windlass. Hatches. Condition, how ascertained Examination.

Frames. Reverse Frames. Have pumps been examined and found eff- None

Longitudinals. cient? Yes. Planking. Equipment letter S

Transverses. Have Sluice Valves been examined and found Anchors, No. of 3B & 1S

Floors Good. efficient? - Treenails. Cables (State if now ranged) Yes.

Keelsons. Have Watertight Doors been examined and found length 244 3/4 mean diamr. 1 3/4"

Stringers. efficient? Yes. Transoms, Pointers & Crutches. Appdx length 244 3/4 size 1 3/4"

Inner Bottom Plating. Have Ventilators and their Coamings been length 244 3/4 size 1 3/4"

Have the Tanks been examined Internally? Yes. Air and Sounding Pipes. Chain Locker. Good.

Have the Tanks been tested? Yes. Doubling Plates under Sounding Pipes. Hawser & Warps. -

Standing ~~3000~~ Rigging. -

Sails. -

General Observations, Opinion as to Class, Recommendation, &c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon

this survey, thus, for example: - "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of

survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

This vessel is eligible, in my opinion, to be classed 100A1 with freeboard "Subject to Annual

Examination", with fresh record of survey 5,48, and the notation of s.s.Imm. 5,48, subject to

indented keel, bottom and side plating etc. being permanently repaired at first convenient

opportunity.

Survey Fee (per Section 29) S.S. x 2 £ 56 : - : - Fees collected for, 14.6. 1948.

Special Damage or Repair Fee (if any) No. 2: 10 : 10 : - Received by me, 19

(per Sec. 29) No. 3 1 1 : -

Travelling Expenses (if chargeable) £ 15 : 9

Second Surveyor's Fee (if any) £ : : -

Committee's Minute FRI. 23 JUL 1948

Character Assigned Assign 100A1 with freeboard subject to Annual Examination

Note ~~2~~ S (CL) 4.48 S.S. 5.48 classed 5.48 Lloyd's Register

22/9/48

S/S "BALTONIA"DAMAGE No.3 (continued):

bulwark plate faired in place, 1 bulward stiffener with stanchion removed, faired and refitted, and one stanchion faired in place.

Bulwark top rail (p.s.a.) faired in place, No.3 bulwark plate (from aft) faired in place, 3 bulwark stanchions with 2 stiffeners removed, faired and refitted, and one stiffener faired in place.

CEMENT.

Inner surface of bottom plating in dry tank under boilers cleaned and laid with cement. Bilges all fore and aft are cement washed only.

WOOD CEILING.

Wood ceiling laid over tank top plating in all holds and side bunkers.

CARGO BATTENS.

Cargo battens fitted in all holds and 'tween decks.

REPAIRS:- Wood hatches renewed or part renewed, as required. (Wear & Tear).

Approximately 2,000 defective shell rivets renewed. (Part Wear & Tear, part Damage No.2).

" 1,000 " " " caulked. (Damage No.2)

" 500 ft. " " seams re-caulked. (" ")

" 20 ft. " " " electric welded. (Damage No.2)

A number of minor deck repairs effected.

R.S. Piddington

Write Over
Guns (copy)

© 2020

Lloyd's Register
Foundation