

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office WED. JAN. -8. 1913)

Date of writing Report 6th January 1913 When handed in at Local Office 7. 1. 13 Port of MIDDLESBROUGH-ON-TEES

No. in Reg. Book. 35 S Survey held at Middlesbrough Date, First Survey 1st January Last Survey 4th January 1913 (No. of Visits 2)

on the Machinery of the Wood, Iron or Steel S.S. PENANG MARU Master YEAR. MONTH.

Tonnage { Gross 1912
Net 1912

Vessel built at Port Glasgow By whom Russell & Co

Engines made at Greenock By whom Rankine & Blackmore When 1912

Registered Horse Power (Donkey)

No. of Main Boilers Boilers, when made (Main)

No. of Donkey Boilers Owners Nippon Yusen Kabushiki Kaisha Port Tokio

Steam Pressure If Surveyed Afloat or in Dry Dock North Eastern Dock

in Main Boilers (State name of Dock.)

in Donkey Boilers Voyage London

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

| CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys. | Years Assigned how long expired. | Machinery and Boiler Surveys (including date of N.B., if any). |
|---|--|--|
| <u>100 A 1</u> | | |
| <u>Class Contingent</u> | | |

Last Report No. Port

Particulars of Examination and Repairs (if any) Comp. L M C

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined? Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

, and of the Donkey Boiler?

Did the Surveyor examine the drain plugs of the Main Boilers?

, and of the Donkey Boiler?

Did the Surveyor examine all the mountings of the Main Boilers?

, and of the Donkey Boiler?

Was screw shaft now been drawn and examined?

Is it fitted with continuous liner?

or two liners?

or is it without liners?

Has shaft now been changed?

If so, state reasons

Is the shaft now fitted new?

Has it a continuous liner?

or two liners?

or is it without liners?

State the distance between lignum vitae of stern bush and top of after bearing of screw shaft?

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done? To complete this survey.

The compression nuts of Star Main Boiler require to be overhauled & the valves adjusted under steam, and two bottom manhole doors, McNeil type, to be fitted to Bentin Main boiler and a new Dynamo Stop valve to be fitted to Bentin Boiler.
The Owners Representatives stated that this would be done in London, when the vessel has proceeded. The Surveyors have been advised.
(As per Greenock Letter dated 30th December 1912)

Now Done. Star Main Boiler safety valves opened up and examined. The valves appeared to be in good order, but when valves were closed up, with steam on, it was found that the compression nuts jammed the spindles in certain positions & caused the valves to leak.
McNeil type manhole doors for Bentin boiler on board but not fitted.
Dynamo Stop Valve on Bentin boiler, examined & found slight fracture in casting.

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9, 11, or L.M.C. 9, 11, 140 lb., H.D., &c.)

The above forwarded for the information of the Committee

| | | | | |
|--|---|---|---|------------------|
| Survey Fee (per Section 28)..... | £ | : | : | Fees applied for |
| Special Damage or Repair Fee (if any)..... | £ | : | : | 19 |
| (per Section 28.) | | | | Received by me, |
| Travelling Expenses (if chargeable)..... | £ | : | : | 19 |

Committee's Minute

TUE. JAN. 14. 1913

Assigned

See Minute
on Lm. rpt. W. 75278

John P. Robson
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

006067-006079-0169

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.

Spool not yet cleared.
Submitted the London
Surveys be advised.

(2)
8.1.13



© 2021

Lloyd's Register
Foundation