

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report January 17th 1921 Where Handled in at Local Office

No. in Reg. Book Survey held at St. John's, NFL.

40282 on the Wood, Iron or Steel 3 Mot. Sch. "Alosno"

TONNAGE: 256 Built at Pasajes
GROSS 256 Owners Lago + Cia
UNDER DE. 213
NET 207 Owners' Address

Surveyed Afloat or in Dry Dock? Both Name of Dock St. John's A. Dock Destined Voyage Seville

WB=CellDBorDBa feet; uE&B feet; t feet; t feet; t feet; t tons.
total capacity tons. FPT tons; APT tons; MT tons.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.
If the vessel has Water Ballast Tanks, state whether the manholes covers have been removed, and the inside tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, and of the inner bottom plating, especially in the bilge space.

1st Report, No. 177 Port Slew

CHARACTER.	For Special Survey.	Date of Last Survey and of Periodical Surveys.	Machinery and Boiler Survey (including date of N.B., if any).
* 10 A -	1, 19.		

odical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the use of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the lacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on Society's Freeboard (if assigned) as painted on Ship and now verified

back of this form. State also the dates and initials of any letters respecting this case.

image cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined?

Requested

Was a damage report made by anyone else? If so, by whom?

AIRRS, OR EXAMINATION AS PER RULE, FOR heavy weather whilst on a voyage from Seville to St. John's, NFL.

Upon examination found:- Forecastle Head:- Rails + stanchions bent and torn from deck. Covering board broken. 2 fairleads broken. Deck seams started. Main deck:- 4 deck planks damaged. Seams of deck planking and around hatch coamings + stanchions started. Mast wedging slack on all three masts. 3 Topmasts carried away. Mainmast outrigger broken. Lugsail broken. Deck pumps out of order.

Prop. deck:- Deck seams started, and top of cabin leaking. Wheel house badly damaged. Rudder post and rudder casing badly damaged. Compass badly damaged.

MARY OF DAMAGE REPAIRS:-	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:-
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								

SENT CONDITION OF THE	Stringers	—	Dblng. Plates under Sounding Pipes	—	Copper, or Y.M. of Wood Vessels	None
ting of Decks	Good	—	Engine Room Skylights	—	(State if on Felt.)	
rways	"	—	Coal Bunkers, Open'gs, Lids, &c.	—	When put on, Month	Year
ings	"	—	Scuppers	—	Boats	Good
is & Fastenings	—	—	Cargo Hatchways	Good	Masts, Yards, &c.	
de Plating	—	—	Hatches	—	Condition, how ascertained	Examined
ing of ditte	—	—	Planking of Wood Vessel	—	(State if wedges removed)	New
stheads & Crutches	—	—	Caulking	ditto	Sails	Good
oms	—	—	Treenails	ditto	Equipment letter	2 B, 1 S.
ies	—	—	Breasthooks & Stemson	ditto	Anchors, No. of	No
rise Frames	—	—	Transoms, Pointers, & Crutches	ditto	Cables (State if new ranged)	
BS	—	—	Timbers of Frame at openings	ditto	," length (on board)	size
BOES	—	—	Ditto ditto at other places	ditto	," Rule length	size
			Stringers, Clamps & Shells	ditto	Hawser & Warps	Good
			Salting (State if examined.)	ditto	Standing & Running Rigging	"

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"..... to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-18 and ptdl18, &c."

This vessel is in my opinion eligible to remain as now classed in the Register Book with fresh record of Survey 1,21. subject to spare Bow anchor and Kedge anchor being placed on board.

Survey Fee (per Section 28) \$ 2
Special Damage or Repair Fee (if any) per Sec. 29 \$ 72-00
Travelling Expenses (if chargeable) \$ 3-00
Second Surveyor's Fee (if any) \$ 2
Committee's Minute FRI. FEB. 18 1921
Character Assigned Wat

Fees applied for, Jan. 13 1921
Received from me, Jan. 13 1921

Surveyor to Lloyd's Register of Shipping.



Wood Sch. "Alosno"

All sails more or less damaged.

Rigging damaged through breaking of topmasts.

Sidelights badly damaged.

Vessel examined on Dry dock found:- Rudders braces and pintles badly damaged. Bottom seams started.

One plank split and several planks bruised.

Repairs:-

Vessel in Dry dock, bottom and pudder cleaned. examined, repaired and painted.

Examined holds, decks, bulwarks, coamings,

hatches, steering gear, windlass, anchors, masts + rigging. boats + general equipment and pumps.

Gorecastle head:- New part covering board fitted. Rails + stanchions repaired + renewed. 2 new fairleads fitted. Deck seams caulked.

Main deck:- 4 deck planks part renewed. Deck seams and around hatch coamings + stanchions caulked. Wash stroke part renewed each side. New mast wedges fitted to all masts. 3 new topmasts fitted. New mainmast outriggers and halyard fitted. Deck pumps overhauled and put in good working order.

Poop deck:- Deck seams and top of cabin caulked. Wheel house rebuilt. New pudder post and braces fitted. Rudder casing repaired. Steering gear overhauled and put in good working order.

Bottom:- One bottom plank renewed, and greasing pieces fitted on bruised planks. All bottom seams gone over and caulked.

Sails + Rigging:- All damaged sails repaired. New square sail, jumbo, and inner jib sails fitted.

Rigging gone over, repaired, and set up.

New sidelights fitted to screens

New compass fitted on board.

New 7 H.P. gasoline driven hoist fitted on board.

All repairs were carried out to my satisfaction.

NOTE:- This vessel is fitted with only 2 Bower Anchors and 1 stream. A spare Bower, and Kedge anchor, to be placed on board on arrival of vessel at her home port.

A. M. Macfarlane.

© 2020



Lloyd's Register
Foundation