

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

WED. AUG. 13. 1919

Date of writing Report

When handed in at Local Office

26 JUL 1919

Port of

LIVERPOOL

No. in Reg. Book

Survey held at Birkenhead

Date, First Survey June 13

Last Survey July 25 1919

783 on the Machinery of the Wood, Iron or Steel

sp "Dunleith"

Master

YEAR. MONTH.

Gross Tonnage 292
Net Tonnage 111

Vessel built at Paisley

By whom J. Fullerton & Co.

When 1896 9

Registered Horse Power 45
No. of Main Boilers 2
No. of Donkey Boilers none

Engines made at Glasgow

By whom Bell, Brown, Rutter & Co.

When 1896

Boilers, when made (Main) 1896

(Donkey) ✓

Port

Voyage

Last Report No.

Port

Particulars of Examination and Repairs (if any) B.S. No.

Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

Where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined? Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? ✓

Do. " Donkey " " " " ✓

Where this was not done, state for what reasons? ✓

What parts of the Boilers could not be thus thoroughly examined? ✓

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? ✓

Did the Surveyor examine the Safety Valves of the Main Boiler? ✓ To what pressure were they afterwards adjusted under steam? 120 lbs per sq. in.

Did the Surveyor examine the Safety Valves of Donkey Boiler? ✓ To what pressure were they afterwards adjusted under steam? ✓

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? ✓, and of the Donkey Boiler? ✓

Did the Surveyor examine the drain plugs of the Main Boilers? ✓, and of the Donkey Boiler? ✓

Did the Surveyor examine all the mountings of the Main Boilers? ✓, and of the Donkey Boiler? ✓

Has the screw shaft now been drawn and examined? ✓ Is it fitted with continuous liner? ✓ or two liners? ✓ or is it without liners? ✓

Has the shaft now been changed? ✓ If so, state reasons ✓

Has the shaft now fitted new? ✓ Has it a continuous liner? ✓ or two liners? ✓ or is it without liners? ✓

What is the distance between lignum vitae of stern bush and top of after bearing of screw shaft? Good fit.

Where the Survey is not complete state what arrangements have been made for its completion and what remains to be done? Complete

The propeller, stern bush and fastenings of sea connection examined. The stern bush renewed. The tail shaft drawn, examined and found in good condition. The cylinders, pistons, piston rods slide valves and faces, crank shaft, pumps examined. The cracks at the corners of the ports of the HP slide valve face examined. Same do not appear to be extending. In view of the further experience of these cracks it is considered that same may be removed from the Limitation list. The boiler examined throughout and found in good condition generally. The starboard furnace is somewhat out of round but not to a serious extent. A few tubes renewed. Mountings overhauled. Safety valves afterwards adjusted under steam. See Southampton Report No. 10137.

General Observations, Opinion, and Recommendation:— (State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9,11, B.&M.S. 9,11, or L.M.C. 9,11, 140 lb., F.D., &c.) The machinery of this vessel, so far as seen, is in good condition and, in my opinion, eligible to remain as classed with records of BS 7, 19 and tail shaft examined 7, 19. The vessel's name to be removed from the Limitation list.

Survey Fee (per Section 28) £ 1 : 0 : 0
Special Damage or Repair Fee (if any) (per Section 28.) £ : :
Printing Expenses (if chargeable) £ : :
Fees applied for 11 AUG 1919
Received by me, 15.8.19 1919

B. G. Bedford
Engineer Surveyor to Lloyd's Register of Shipping.
FRI. SEP. 24 1920

Committee's Minute
Signed B. G. Bedford 7.19
Remover from Limitation List.
LIVERPOOL 12 AUG 1919
FRI. 20 FEB. 1920
FRI. 13 FEB. 1920
TUE. MAY. 4 1920
Lloyd's Register Foundation

Insert Character of Ship and Machinery precisely as in the Register Book.

As a Certificate required If so, to be sent to

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

Shaft 3.19 now held
Shaft examined
P.Cylinder valve face examined & limit
removed.

It is submitted that
vessel is eligible for
RECORD. B.S. 7.19

7.19
Name to be removed
from limit list regarding
P.Cylinder face

19/8/19

[Faint, mostly illegible handwritten text in cursive script, likely bleed-through from the reverse side of the page.]

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2020
Lloyd's Register
Foundation