





# Report of Survey for Repairs, &c., of Engines and Boilers.

Minor repairs carried out to mountings on both boilers.

SMOTHERING ENGINE barrell shaft (worn in way of gear wheel) renewed.

The above repairs have been efficiently carried out.

S.R.L. The main engine bracket carrying H.P. and L.P. valve guides together with H.P. valve guide were efficiently renewed at this time. The H.P. valve spindle remains to be renewed. Due to pressure of work the dynamo has not been rewound (windings on board).

It is recommended that "Fit new H.P. (not L.P.) guide" bracket now be deleted from the Special Reasons List.

It is recommended that the port boiler safety valve springs be renewed and dynamo repairs be carried out on arrival at the discharge port and the main engine H.P. valve spindle be renewed at earliest opportunity in the meanwhile they are considered efficient.

*S.H.!*



© 2020

Lloyd's Register  
Foundation