

Report of Survey for Repairs, &c., of Engines and Boilers.

No. 99439

(Received at London Office 20 MAY 1941)

Date of writing Report 19 When handed in at Local Office 1915/1941 Port of NEWCASTLE-on-TYNE

No. in Reg. Book. 66704 Survey held at Newcastle Date, First Survey and Last Survey 8 May 1941 (No. of Visits 1)

on the Machinery of the Wood, Iron or Steel SS "Collingwood"

Tonnage { Gross 90 Net 39 Vessel built at Willington Quay By whom Clelland & Sons Ltd When 1940-5

Nominal Horse Power { 37 Engines made at Newbury By whom Plenty & Son When 1940

No. of Main Boilers 1 Boilers, when made (Main) 1940 (Donkey) ✓

No. of Donkey Boilers 1 Owners Type Improvement Comm. #8 Owners' Address (if not already recorded in Appendix to Register Book.)

Steam Pressure in Main Boilers 130 Managers Port N. Shields Voyage

in Donkey Boilers ✓ If Surveyed Afloat or in Dry Dock T.T.C. Slipway (State name of Dock.)

Last Report No. Port

Particulars of Examination and Repairs (if any) Condⁿ

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.

CHARACTER. For Special Survey Date of last Survey and of Periodical Surveys.	Years elapsed since last survey.	Machinery and Boiler Surveys (including date of N.B., if any).
* 100 A1 for ferry purposes on River Tyne. 5. 1. 40		09. LMC 4. 40

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

" " Donkey " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler. Present condition of funnel(s).

Did the Surveyor examine the Safety Valves of the Main Boiler? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? , and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers? , and of the Donkey Boilers?

Did the Surveyor examine all the mountings of the Main Boilers? , and of the Donkey Boilers?

Is screw shaft now been drawn and examined? Is it fitted with continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Is shaft now been changed? If so, state reasons.

Is the shaft now fitted been previously used? Has it a continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

State date of examination of Screw Shaft. State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft.

Engine parts, when referred to by numbers, should be counted from forward. Is electric light and/or power fitted?

So, did the Surveyor examine the generators, motors, switchgear, cables and fuses?

Is the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done. Complete

Vessel on Slipway propeller & Sea fastenings examined

General Observations, Opinion, and Recommendation:— The machinery of this vessel (State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9,11, B.&M.S. 9,11, & L.M.C. 9,11, or CS 374, is eligible in my opinion to remain as classed.

Survey Fee (per Section 29) £ : : Fees applied for 19


Special Damage or Repair Fee (if any) (per Section 29.) £ : : Received by me, 19

Travelling expenses (if chargeable) £ : :

Committee's Minute FRI, 30 MAY 1941

Assigned As now

Robert Pitt
Engineer Surveyor to Lloyd's Register of Shipping.



It is submitted that
this vessel is eligible to
remain as **CLASSED**.

Yours
27.5.51



© 2020

Lloyd's Register
Foundation