

REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office)

10 SEP 1957

Date of writing Report 3rd Sept. 57

When handed in at Local Office

Port of Naples

No in Reg. Book. Survey held at Civitavecchia

Date. First Survey

Last Survey 19th Aug. 57

(No. of Visits one)

01832

on the Machinery of the ~~Wood, Iron or Steel~~ S/S "A P P U L O"

Year. Month.

Tonnage { Gross 7020
Net 4309

Vessel built at Victoria
Engines made at Toronto

By whom Victoria Mchy Depot Co. Ltd

When 1943 3

By whom Jhon Inglis Co. Ltd

When 1943

MN As Per Rule

Boilers, when made (Main)

(Donkey)

No. of Main Boilers

Owners L'Italica di Nav. S.p.A.

Owners' Address

(if not already recorded in Appendix to Register Book.)

HS

Managers -do-

Port Genoa

Voyage

No. of Donkey Boilers

Steam Pressure—

If Surveyed Afloat or in Dry Dock

(State name of Dock.)

Civitavecchia

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

HULL

MACHINERY

Last Report No. 7679

Port N.Ms.

COMPLETION BS

Particulars of Examination and Repairs (if any)

+100 A1
SS 6/56

+LMC
dkg 9/56
eng 6/56
blrs 6/56
CL 6/56N
stp 6/56

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Donkey

If not, state for what reasons

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler

centre 19.8.57

Present condition of funnel(s)

Did the Surveyor examine the Safety Valves of the Main Boilers?

Yes

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of the Donkey Boilers?

-

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

Yes

, and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers?

none

, and of the Donkey Boilers?

Did the Surveyor examine all the mountings of the Main Boilers?

Yes

, and of the Donkey Boilers?

Has the screw shaft now been drawn and examined?

Has it a continuous liner?

Is an approved oil retaining appliance fitted at the after end?

Has shaft now been changed? If so, state reasons

Has the shaft now fitted been previously used?

Has it a continuous liner?

Is an approved oil retaining appliance fitted at the after end?

State date of examination of Screw Shaft

State the wear down in the

Is electric light and/or power fitted?

If so, did the Surveyor examine the generators, motors, switchgear cables and fuses?

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

Engine parts, when referred to by numbers, should be counted from forward. Auxiliary machinery should be referred to by position in Machinery Space.

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done

COMPLETE

NOW DONE:-

The Centre boiler examined throughout with Safety Valves all mountings and superheater

CONDITION OF CLASS:- A welded stay tube in the centre box now renewed, this item may now be deleted.

Note:- Owing to the long distance and pressure of work the surveyor was not able to attend for adjustment of Safety Valves. As this vessel holds dual Class the valves were adjusted by R.I.Na surveyor who has confirmed this. It is therefore submitted that R.I.Na surveyor be accepted in this case and the new survey date be assigned.

General Observations, Opinion, and Recommendation:-

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, etc.)

The machinery of this ships, so far as now surveyed is eligible in my opinion to remain as now classed with fresh record of MBS 6.57 as previously recommended without special condition.

MBS..... Lit. 15.300
Survey Fee (per Section 23) " 2.300
Gen. Exps " 12.360
Trav. Exps " 8999
Tax " 8999

Fees applied for,

Received by me,

(E.F. Butler)

Engineer Surveyor to Lloyd's Register of Shipping.

Committee's Minute

Assigned

As now, without special condition

MBS 7.57

006780-006786-0075

Is a Certificate required? If so, to be sent to