

# Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

-4 SEP 1941

Writing Report 14th June '41 When handed in at Local Office 6/6/41 Port of Kobe  
 Survey held at Harima Date, First Survey 17/5/41 Last Survey 6/6 1941  
 (No. of Visits 3)  
 on the Machinery of the ~~Kondokoku~~ Steel M/S "NAKO MARU"  
 Gross 7145 Vessel built at Uraga By whom Uraga Dock Co. Ltd. When 1934, 10 mo.  
 Net 4271 Engines made at Uraga. By whom Uraga Dock Co. Ltd. When 1934.  
 Main Boilers 1851 NHP Boilers, when made (Main) -- (Donkey) 1934.  
 Owners Nippon Yusen Kaisha Owners' Address --  
 Managers -- (if not already recorded in Appendix to Register Book.)  
 If Surveyed Afloat or in Dry Dock Both. Port -- Voyage --  
 (State name of Dock.) Harima Dock.  
 Key Boilers 100 lbs.

Report No. -- Port --Particulars of Examination and Repairs (if any) PART LMC (CS). DBS 100A1

at Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the nature and extent of Examinations and subsequent Repairs. Repairs on of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and being detailed in the body of the report, should be briefly summarised at the end of the report. State also the initials of any letters respecting this case.

ge cases where the Surveyor has not made a special damage report he is required to state whether he red his services for this purpose, and why they were declined --

damage report made by anyone else? If so, by whom? --

Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? --

" Donkey " " " Yes

as not done, state for what reasons? --

at parts of the Boilers could not be thus thoroughly examined? --

at special means, in the absence of internal examination, were adopted by the yor to assure himself of the thorough efficiency of those parts of each Boiler? --

test date of internal examination of each boiler June 1941.

Present condition of funnel(s)

Good.

Surveyor examine the Safety Valves of the Main Boiler? --

To what pressure were they afterwards adjusted under steam? --

Surveyor examine the Safety Valves of Donkey Boiler? Yes.

To what pressure were they afterwards adjusted under steam? 100 lbs=

Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? --

, and of the Donkey Boilers? Yes.

Surveyor examine the drain plugs of the Main Boilers? --

, and of the Donkey Boilers? --

Surveyor examine all the mountings of the Main Boilers? --

, and of the Donkey Boilers? Yes.

rew shaft now been drawn and examined? --

Is it fitted with continuous liner? --Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? --

shaft now been changed? -- If so, state reasons --

shaft now fitted been previously used? --

Has it a continuous liner? --Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? --

ate of examination of Screw Shaft --

State the distance between lignum vitae of stern bush and top of after bearing of screw shaft 3.75 m/m

Engine parts, when referred to by numbers, should be counted from forward.

Is electric light and power fitted? Yes.

did the Surveyor examine the generators, motors, switchgear, cables and fuses? Yes, see below.

Yes, see below.

insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? Yes.

Yes.

Survey is not complete, state what arrangements have been made for its completion and what remains to be done

DONE:- Vessel placed in dry dock, propeller, aft end of stern bush, sea cocks and valves with ir shell fastenings, examined and found in good condition.

TS NOW EXAMINED FOR LMC (CS):-

Main Engine:-

Nos. 1, 4 & 5 cylinders, pistons, valves, gears and covers.

Nos. 1 & 4 connecting rods and top ends.

No. 4 bottom end.

Nos. 3 & 6 crankshaft journals.

Thrust shaft.

Intermediate shafts.

(P.T.O.)

General Observations, Opinion, and Recommendation:— The Machinery and Boilers of this vessel

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, E.S. 9,11, B.E.M.S. 9,11, L.M.C. 9,11, or L.M.C. 140 lb., E.D., &c.)

e in good condition and eligible in my opinion that the record of LMC (C.S.) 1, 39.

retained with fresh under date 6. 41. and D.B.S. 6, 41.

Key Fee (per Section 20) Yen : 80.00

Fees applied for

12/6 1941

Damage or Repair Fee (if any) --

Received by me,

19

Travelling expenses (if chargeable) (See Hull Rpt.)

Committee's Minute

FRI. 10 SEP 1941

Assigned

K. Takabayashi  
Engineer Surveyor to Lloyd's Register of Shipping.



Lloyd's Register  
Foundation

007088-007099-0209 1/2

Nos. 1, 2 & 3 (Starboard outboard, Inboard & aft) Auxiliary

Diesel engines - complete.

No. 2 (Forward Inboard) auxiliary air compressor - complete.

No. 2 L.P. air receiver.

No. 2 (Outboard) Piston & Jacket Cooling (combined) water pumps.

No. 2 oil fuel transfer pump.

No. 2 donkey boiler feed water pump.

Bilge and sanitary pump.

The one Donkey Boiler was examined over all parts with doors, mountings and safety valves and found in good condition. Safety valves adjusted under steam as stated above.

The oil fuel burning installation for boiler examined under working condition and found satisfactory.

REPAIRS DUE TO WEAR AND TEAR:-

Auxiliaries:-

Nos. 2 & 3 (S.inboard and S.aft.) Auxiliary Diesel Engines, Crank shafts, lifted up and alignment adjusted and all crank shaft journal brushes - renewed.

Bilge and Sanitary Pump, water cylinders - renewed on account of corrosion and tested by  $6\text{Kg/cm}^2$ , of hydraulic pressure and found sound and tight.

Other minor repairs and adjustments, effected. K.S.



© 2020

Lloyd's Register  
Foundation

ABS due 4.41 Held  
C.P. advanced

It is submitted that  
this vessel is eligible for  
**THE RECORD.** ABS 6.41

It is submitted that  
this vessel is eligible for fresh  
**RECORD** of Survey  
6.41 for the oil engines.

TRm  
17.9.41

