

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Steel S.S. "CANADIAN SETTLER" Rpt. Quebec No. 1769
1775

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 72 Depth "d" 22-25'Framing: Table No. 3 Description Bulb angle as approved.Longitudinal No. 23832Proportions $\frac{\text{Length}}{\text{Depth}} = \frac{\quad}{\quad} = \underline{10.03}$

Bridge Deck Sheerstrake as approved.

Repairs have been effected to damage to Bollard, Fairlead, & Windlass.

This vessel is classed for a period of more than 15 years, subject to Special Surveys as required by the rules.

The Downton Pump is not satisfactory & is to be replaced on vessel's return to Canada

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ☒ 100 A.1. (steel) } Subject to Downton Pump being put in order.
1 DK. (steel).

Cell DB 266' 674 t. FPT 95 t. APT 73 t.

FK. 6 BH. Cam. Lloyds A.C.P. P 33', B 28', F 33'.

It is included that alternate frames extend to erections as per approved plans, & that the diameter of rivets in bulbs of keel & sheerstrake, where of increased thickness, are as required and that the tank bottom plating has been increased under hatchways as approved. But the Surveyor should be requested to state if this is so.

The Surveyor should be requested to forward plans of midship section as built.

007342-007351-0277