

## Report of Survey for Repairs, &amp;c., of Engines and Boilers.

Date of writing Report 10 When handed in at Local Office 4/5 19 40 Port of TRIESTE (Received at London Office MAY 14 1940)

No. in Reg. Book 19845 Survey held at Venice Date, First Survey Apr 28 Last Survey Apr 28 1940 (No. of Visits one)

on the Machinery of the Wood, Iron or Steel S.S. "AQUITANIA"

Tonnage { Gross 4971 Vessel built at Glasgow By whom Blythsw'd S.B. Co Ltd. Year. Month. 1924-9  
 Net 3024 Engines made at Greenock By whom J. G. Knicard & Co Ltd. When 1924

Nominal Horse Power 425 Boilers, when made (Main) 1924 (Donkey) —

No. of Main Boilers 3 Owners ITA LUIGI PITALUGA VAPORI Owners' Address —

No. of Donkey Boilers — Managers — (if not already recorded in Appendix to Register Book.)

Steam Pressure in Main Boilers 180 lb Port Genoa Voyage —

in Donkey Boilers — If Surveyed Afloat or in Dry Dock Dry dock (State name of Dock.) Principe di Piemonte

Last Report No. — Port —Particulars of Examination and Repairs (if any) Docking

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

Was a damage report made by anyone else? If so, by whom? —Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? —" " Donkey " " " " —If this was not done, state for what reasons? —And what parts of the Boilers could not be thus thoroughly examined? —Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? —State latest date of internal examination of each boiler —Present condition of funnel(s) GoodDid the Surveyor examine the Safety Valves of the Main Boiler? —To what pressure were they afterwards adjusted under steam? —Did the Surveyor examine the Safety Valves of Donkey Boiler? —To what pressure were they afterwards adjusted under steam? —Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? —, and of the Donkey Boilers? —Did the Surveyor examine the drain plugs of the Main Boilers? —, and of the Donkey Boilers? —Did the Surveyor examine all the mountings of the Main Boilers? —, and of the Donkey Boilers? —Has screw shaft now been drawn and examined? —Is it fitted with continuous liner? —Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? —Has shaft now been changed? — If so, state reasons —Has the shaft now fitted been previously used? —Has it a continuous liner? —Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? —State date of examination of Screw Shaft —State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft 6 1/4 in

Engine parts, when referred to by numbers, should be counted from forward.

Is electric light and/or power fitted? YesIf so, did the Surveyor examine the generators, meters, switchgear, cables and fuses? —Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? —If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done Complete

Now done: Vessel placed in dry dock, propeller, after end of stern bush and outside fastening examined and found in order.

General Observations, Opinion, and Recommendation:— The vessel is, in my opinion,

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9,11, B.&M.S. 9,11, \* L.M.C. 9,11, or \* L.M.C. 140 lb., F.D., &c.)

worthy to remain as classed, without fresh record regarding machinery.


Survey Fee (per Section 29) £ : : Fees applied for —

Special Damage or Repair Fee (if any) (per Section 29.) £ : : Received by me, —

Travelling expenses (if chargeable) £ : : —

Committee's Minute As nowAssigned —

Engine Surveyor to Lloyd's Register of Shipping.



Lloyd's Register Foundation




*Joel King*

It is submitted that  
this vessel is eligible to  
remain as **CLASSED**.

*Flux*

21. 5. 40



© 2021

Lloyd's Register  
Foundation