

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 7th Dec. 1921 When handed in at Local Office 7th Dec. 1921 Port of GothenburgNo. in Survey held at Gothenburg Date, First Survey 28th Nov. Last Survey 3rd Dec 1921
Reg. Book. on the ~~Wood, Iron or Steel~~ *senior steamer* "HOLMENGRA" Master ✓18625 TONNAGE:— Built at Lübeck By whom Schiffsver. v. Henry Koch When 1904
GROSS 1748 Owners aktieb. Nordiska Lloyd (R. Frode, Mgr) Port belonging to Gothenburg
UNDER DK. 1395 Owners' Address
NET 946 (if not already recorded in Appendix to Register Book).Surveyed Afloat or in Dry Dock? *floating dock* Name of Dock *inkuberg* Destined Voyage *Norland*WB=CellDBorDBa feet; uE&B feet; f feet; Particulars of Classification (which must be inserted
total capacity tons. FPT tons; APT tons; MT feet tons. precisely as in Register Book & Supplements).N.B.—All alterations in the existing records should be underlined.
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. Port

(Periodical Surveys, when held, must be reported in detail and serialim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

Society's Freeboard (if assigned) as painted on Ship and now verified } ✓ ft. ✓ ins.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined? ✓ Was a damage report made by anyone else? If so, by whom? ✓

REPAIRS, OR EXAMINATION AS PER RULE, FOR Classification in Register Book and No 3 Survey.

This vessel was built in 1904 to class with the Germanischer Lloyd and is still classed in that Register.

The usual periodical special survey is stated to have been carried out by the Germanischer Lloyd's surveyor in Stockholm last spring, except for some minor details.

It was contemplated in 1919 to transfer the class of the vessel to this Society and the results as ascertained were entered in a "First Entry" report and forwarded to London together with plans of the vessel as built, see Goth. report No 4300.

The project was not proceeded with at that time but the Owners have now definitely decided to class the vessel with this Society and the remaining particulars required for the completion of the "First Entry" report have now been ascertained and are contained in (OVER)

SUMMARY OF DAMAGE REPAIRS:—

	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								

PRESENT CONDITION OF THE

Decks	Stringers	Sort	Dblng. Plates under Sounding Pipes	Sort	Copper, or Y.M. of Wood Vessels	✓
Caulking of Decks	Inner Bottom Plating	"	Engine Room Skylights	"	(State if on Feet.)	
Waterways	State if Tanks have been examined inside	yes	Coal Bunkers, Open'gs, Lids, &c.	"	When put on, Month	✓ Year
Coamings	State if Tanks now tested	yes	Scuppers	"	Boats	Sort
Beams & Fastenings	Bulkheads	Sort	Cargo Hatchways	"	Masts, Yards , &c.	"
Outside Plating	Ceiling	"	Hatches	"	Condition, how ascertained	examined
Caulking of ditto	Cement or Asphalt	Cement good	Flanking of Wood Vessels	"	(State if wedges removed)	no
Rivets	Rudder	"	Caulking ditto	"	Sails	none
Breasthooks & Crutches	Steering gear and its connections	"	Treenails ditto	"	Equipment letter	9/
Transoms	Windlass	"	Breasthooks & Stemson ditto	"	Anchors, No. of	3 B. 15 + 1 K
Frames	Have Pumps now been examined and found efficient?	yes	Transoms, Pointers, & Crutches ditto	"	Cables (State if now ranged)	yes
Reverse Frames	Have Sluice Valves now been examined and found efficient?	none	Timbers of Frame at openings ditto	"	" length (on board)	210 size 1 9/16
Floors	Have Watertight Doors now been examined and found efficient?	yes	Ditto ditto at other places ditto	"	" Rule length	240 size 1 1/4
Keelson			Stringers, Clamps & Shelves ditto	"	Hawser & Warps	Sort
			Salting (State if examined.)	"	Standing & Running Rigging	"

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptND15, &c."

This vessel is eligible, in our opinion, to be classed 100A1 in the Register Book with record of survey 12.21. and with notation of S.S. Got. No 3 12.21 subject to 30 fathoms of chain cable 1 1/4 dia. being placed on board.

Survey Fee (per Section 28) £14 430.00

Special Damage or Repair Fee (if any) (per Sec. 29) £

Travelling Expenses (if chargeable) £

Second Surveyor's Fee (if any) £

Fees applied for,

8th Dec 1921

Received by me,

8th Dec 1921

288

W. Wilson

H. Thomson

A. Lundin

Surveyor to Lloyd's Register of Shipping.

Committee's Minute

TUL 19 JAN. 1922

Character Assigned

See Minute on

Got. No 4938

FRI. 4 AUG. 1922

FRI. DEC. 29 1922

007626-007638-0227

© 2020

Lloyd's Register Foundation

12 If this cannot be avoided by covering these essential parts must be taken that the convincing manner is not so much damped as to spread the link, or to cause it to show through to the other side.

at the same time the S.S. No 3 has been held as follows. viz:-

The shoe piece in way of the electric welding, repair to the stemframe as reported by the Malmö Surveyors on 20th Nov. 1919 was examined and found in order.

in way of the sildges, manholes, pillars, bulkheads & tunnel in order to ascertain the conditions of the tank tops and margin plates and the tightness of the double bottom tanks.

hatchways, engine & boiler heaters, tank tops, masts, and both surfaces of outside plating, in these spaces were examined, found in good condition, free from oxidation and recently coated. Shell plating examined in way of side lights & found in order.

7.0 ± 0.5 after peak tanks and all double bottom tanks scanned internally, steelwork & cement found in good order and steelwork free from oxidation.

chain cables rigged, anchors, masts, rigging, boats and general equipment examined.

The deck, steam steering engine & its connections, steering rods, chains, blocks, muller

ANCHORS.

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

[illegible]

The thickness of the shell plating was carefully ascertained amidships, at the forward end about 4 frame spaces abaft the collision bulkhead and at the after end about 4 frame spaces forward of the after peak bulkhead.

3 hold stanchions removed, jacked & replaced, 9 nuts in coll. bulk. removed

Note:- Attention is drawn to the recommendations in the 1st entry report regarding the die of the chain cable.

7-12-21