

Rpt. 8.

(Received at London Office)

7 AUG 1941

DISCLOSED

May No.

No 11483

## REPORT of SURVEY for REPAIRS, &amp;c.

Date of writing Report 28/4/41 When handed in at Local Office 6 May 1941 Port of Kobe.

No. in Survey held at Kobe. Date, First Survey 15/3/41 Last Survey 7/4/1941.  
Reg. Book. (No. of Visits Three.)25-305 75975 on the ~~Wendy Iron~~ Steel T.M.S. "HOKUROKU MARU".TONNAGE:- Built at Nagasaki. By whom Mitsubishi Zosen K.K. When 1930 1  
GROSS 8360 Owners Osaka Syosen Kabusiki Kaisya. Owners' Address  
UNDER DK 7812 (if not already recorded in Appendix to Register Book).  
NET 5045 Managers Port belonging to Osaka.

Surveyed Afloat or in Dry Dock? Both Name of Dock Mitsubishi Dock. Destined Voyage

WB=CellDBorDBa feet; uE&B feet; f feet; Particulars of Classification (which must be inserted  
total capacity tons. FPT tons; APT tons; MT feet tons. precisely as in Register Book & Supplements)  
N.B.—All alterations in the existing records should be underlined.

Last Report, No. 11638 Port Kobe

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

Damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? If so, by whom?

PAIRS, OR EXAMINATION AS PER RULE, FOR COMPLETION OF SPECIAL SURVEY 2nd No.1 (SRL).

W DONE:- Vessel placed in dry dock. Hull, bottom, rudder (lifted), stern frame, propeller brackets, and stem cleaned, examined and found in good condition, afterwards recoated.

Nos.2 & 5 holds, tween decks, chain locker, spaces under bridge, engine and boiler space cleared for survey, ceiling lifted as required by rules, all oxidation removed from all parts, steel work throughout all parts of the vessel carefully examined and found in good condition. Afterwards recoated.

The following tanks were examined, internally and found in good condition.

Nos.1, 2, 3, 4, 5 & 7 double bottom tanks, oil fuel wing tanks in No.4 hold, reserve fresh water tank, piston cooling water tank and lubricating oil main drain tank in engine room and after peak tank. (P.T.O.).

SUMMARY OF DAMAGE REPAIRS:-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:-
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

## PRESENT CONDITION OF THE

	As/Rpt.	Good, As/Rpt.	Copper, or Y.M. of Wood Vessels
Good	State if Tanks have been examined inside	Yes/	(State if on Bell.)
Working of Decks	State if Tanks now tested	Yes, As/Rpt.	When put on, Month
Paintings	Bulkheads	Good	Boats
Frames & Fastenings	Ceiling	"	Masts, Yards, &c.
Side Plating	Cement <del>xxxxxx</del> As/Rpt. Good	Good	Condition, how ascertained. From aloft.
" in way of sidelights	Rudder	Good	(State if wedges removed)
Fasthooks	Steering gear and its connections	"	Sails
Transoms	Windlass	"	Equipment letter
Frames	Have pumps now been examined and found efficient?	Yes.	Anchors, No. of 3B. 1s.
Transverse Frames	Have Sluice Valves now been examined and found efficient?	--	Chain Locker
Longitudinals	Have Watertight Doors now been examined and found efficient?	Yes.	Cables (State if now ranged)
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Yes.	" length 300 fms. 2-8/16"
Floors			" Rule length 300 fms. 2-8/16"
Keelsons			Hawser & Warps
Stringers			Standing and Running Rigging
Inner Bottom Plating			

## General Observations, Opinion as to Class, Recommendation, &amp;c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24.

This vessel, so far as now seen, is in good condition and eligible, in our opinion, to be continued as classed with fresh record of survey 4,41 and the Notation S.S.Kob.2nd No.1-41 as previously recommended.

Survey Fee (per Section 20) Yen 210:00  
Special Damage or Repair Fee (if any) --  
Travelling Expenses (if chargeable) Yen 9:00  
(Including Machinery)  
Second Surveyor's Fee (if any) --

Fees applied for, 7/4/1941

Received by me, 15/4/1941

Surveyor to Lloyd's Register of Shipping.

Committee's Minute

Character Assigned

TUE. 26 AUG 1941

FRI. 15 MAY 1942

Lloyd's Register Foundation

007679-007689-0167



pt. 9

te  
i  
Bo  
7

ag  
ni  
e I  
of 1

100

75

10

10

10

10

1

10



1

10