

10 APR 1926

No. 5163

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report

3/3/26

When handed in at Local Office

Port of

Kobe.

No. in
Reg. Book.

Survey held at

Kobe.

Date, First Survey

17/2/26.

Last Survey

27/2/26.

19

(No. of Visits

Five.)

35453

on the ~~Wood, Iron or Steel~~ T.S.S. "TOYAMA MARU"

TONNAGE:-

GROSS 7090

UNDER DK. 6574

NET 4386

Built at

Nagasaki

By whom

Mitsubishi Doky & E. Wks.

When

YEAR.

1915

MONTH.

6

Owners

Nippon Yusen Kaisha

Owners' Address

(if not already recorded in Appendix to Register Book).

Managers

Port belonging to

Tokio.

Surveyed Afloat or in Dry Dock?

both

Name of Dock

Mitsubishi Dock.

Destined Voyage

WB=Cell DBordBa

feet; uE&B

feet; f

feet

total capacity

tons. FPT

tons; APT

tons; MT

feet

tons.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 4997 Port Kob

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Society's Freeboard (if assigned) as painted on Ship and now verified

7 ft. 8 1/2 ins.

Was a damage report made by anyone else? If so, by whom?

PAIRS, OR EXAMINATION AS PER RULE, FOR PART SPECIAL SURVEY NO.3 AND CONDITION SURVEY:-

NOW DONE:- As part SS No.3

Vessel placed in dry dock. Hull, bottom, rudder, stern frame & stem cleaned, examined, found or now placed in good condition and recoated.

Decks, hatchways, hatches & supports, vents & coamings, tarpauline, cleats & fastenings, examined and found in good condition. No.3 Hold & Cross bunker examined and found in good condition. The Cross bunker was scaled and recabated.

Ash shoots and plating in way of same specially examined and found in good condition.

Cables ranged and Freeboard verified.

Nos.3 & 6 d.b.tanks were tested as per rule, and found or now made tight.

P.T.O.

SUMMARY OF DAMAGE REPAIRS:-

Renewed
Removed and Faird or Repaired
Faird or Repaired in place

Shell Plates.

Frames.

R. Frames.

Floors.

Beams.

Str. Plates.

Dk. Plates.

Other Items:-

PRESENT CONDITION OF THE

Decks Good

Baulking of Decks "

Coamings "

Beams & Fastenings In above part "

Outside Plating "

Breasthooks "

Transoms "

Frames In above part "

Reverse Frames "

Longitudinals "

Transverses "

Floors "

Keelsons "

Stringers "

Inner Bottom Plating At nos 3+6 d.b.tanks

State if Tanks have been examined inside D.T. only

State if Tanks now tested Nos. 3 & 6 d.b. and Deep Tank.

Bulkheads Good

Ceiling "

Cement or Asphalt (State which.) "

Rudder "

Steering gear and its connections. "

Windlass. "

Have Pumps now been examined and found efficient? "

Have Sluice Valves now been examined and found efficient? "

Have Watertight Doors now been examined and found efficient? "

Have Ventilators and their Coamings been examined and found efficient? Yes

Dblg. Plates under Sounding Pipes

Engine Room Skylights Good

Coal Bunkers, Open'gs, Lids, &c. "

Scuppers "

Cargo Hatchways "

Hatches "

Planking of Wood Vessels. "

Caulking ditto

Treenails ditto

Breasthooks & Stemson ditto

Transoms, Pointers, & Crutches ditto

Timbers of Frame at openings ditto

Ditto ditto at other places ditto

Stringers, Clamps & Shells ditto

Salting ditto

(State if examined.)

Copper, or Y.M. of Wood Vessels

(State if on Felt.)

When put on, Month Year

Boats

Masts, Yards, &c. Good

Condition, how ascertained from deck.

(State if wedges removed)

Sails

Equipment letter b +

Anchors, No. of 3B. 1S. 1K.

Cables (State if now ranged) Yes

" length 300 fms. size 2.5/16

" Rule length 300 fms. size 2 3/8

Hawser & Warps Good

Standing & Running Rigging "

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND24, &c."

This vessel, so far as now seen, is in good condition and eligible in our opinion to be continued as classed with fresh record of survey 2-26, and the notation SS No.3 with date, when the survey is completed.

Survey Fee (per Section 20) £ 145:00
Deep Tank & No.6 D.B. ..£ 60:00
Special Damage or Repair Fee (if any) (per Sec. 20) £
Travelling Expenses (if chargeable) £ 15:00
Inclg. MC, D.T. & No.6 d.b.
Second Surveyor's Fee (if any) £

Fees applied for, 27/2/26
Received by me, 19

Committee's Minute

TUES. 13 APR 1926

FRI. 6 AUG 1926

TUES. 17 AUG 1926

TUES. 15 FEB 1927

Character Assigned

100A1

FRI. 27 AUG 1926

© 2020

Lloyd's Register Foundation

007707-007713-0193

NOTE: It was not considered necessary to drill the shell plating in way of the above

The holds and tween deck spaces were generally examined and found in good condition.

Heating coils 1" dia. have now been fitted in the Deep Tank in order to carry Pea Nut Oil from Tsingtao. The coils have been tested to 250 lbs water - being about twice the working pressure.

REPAIRS DUE TO WEAR & TEAR:-

In Deep Tank:

1 beam knee on Starb. side re-riveted to frame.

No.6 d.b.tank in way of Deep Tank:

one flange bracket to tank top - cropped and an angle connection fitted.

3 broken pointed rivets in tank top renewed.

ANCHORS.

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

[illegible]